



CVE-2017-9632

Published on: 08/07/2017 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:26:57 PM UTC

CVE-2017-9632

Source: Mitre

Source: NIST

CVE.ORG

Print: PDF



Certain versions of [Laserjet](#) from [Pdqinc](#) contain the following vulnerability:

A Missing Encryption of Sensitive Data issue was discovered in PDQ Manufacturing LaserWash G5 and G5 S Series all versions, LaserWash M5, all versions, LaserWash 360 and 360 Plus, all versions, LaserWash AutoXpress and AutoExpress Plus, all versions, LaserJet, all versions, ProTouch Tandem, all versions, ProTouch

ICON, all versions, and ProTouch AutoGloss, all versions. The username and password are transmitted insecurely.

CVE-2017-9632 has been assigned by [ics-cert@hq.dhs.gov](#) to track the vulnerability - currently rated as **CRITICAL** severity.

CVSS3 Score: **9.8 - CRITICAL**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: **5 - MEDIUM**

Access Vector	Access Complexity	Authentication
NETWORK	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
PARTIAL	NONE	NONE

CVE References

Description	Tags	Link
PDQ Manufacturing, Inc. LaserWash, LaserJet and ProTouch	CVE-2017-9632	MISC ics-cert us-cert.gov/advisories/ICSA

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware  	Pdqinc	Laserjet	-	All	All	All
Hardware  	Pdqinc	Laserjet	-	All	All	All
Operating System	Pdqinc	Laserjet Firmware	-	All	All	All
Operating System	Pdqinc	Laserjet Firmware	-	All	All	All
Hardware  	Pdqinc	Laserwash 360	-	All	All	All
Hardware  	Pdqinc	Laserwash 360	-	All	All	All
Operating System	Pdqinc	Laserwash 360 Firmware	-	All	All	All
Operating System	Pdqinc	Laserwash 360 Firmware	-	All	All	All
Hardware  	Pdqinc	Laserwash 360 Plus	-	All	All	All
Hardware  	Pdqinc	Laserwash 360 Plus	-	All	All	All
Operating System	Pdqinc	Laserwash 360 Plus Firmware	-	All	All	All
Operating System	Pdqinc	Laserwash 360 Plus Firmware	-	All	All	All
Hardware  	Pdqinc	Laserwash Autoxpress	-	All	All	All
Hardware  	Pdqinc	Laserwash Autoxpress	-	All	All	All
Operating System	Pdqinc	Laserwash Autoxpress Firmware	-	All	All	All
Operating System	Pdqinc	Laserwash Autoxpress Firmware	-	All	All	All
Hardware  	Pdqinc	Laserwash Autoxpress Plus	-	All	All	All
Hardware  	Pdqinc	Laserwash Autoxpress Plus	-	All	All	All
Operating System	Pdqinc	Laserwash Autoxpress Plus Firmware	-	All	All	All

cpe:2.3:h:pdqinc:laserjet:-:*:*:*:*:*:*:

```
cpe:2.3:o:pdqinc:laserjet firmware:-:*:*:*:*:*:
```

cpe:2.3:o:pdqinc:laserjet firmware:-:*:*:*:*:*:

```
cpe:2.3:h:pdqinc:laserwash_360:-:*:*:*:*:*:
```

```
cpe:2.3:h:pdqinc:laserwash_360:-:*:*:*:*:*:
```

```
cpe:2.3:o:pdqinc:laserwash 360 firmware:-:~::~~::~~::~~::~~::~~::~::
```

```
cpe:2.3:o:pdqinc:laserwash 360 firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:h:pdqinc:laserwash_360_plus:-:*:*:*:*:*:*:
```

cpe:2.3:h:pdqinc:laserwash 360 plus:-:.*:.*:.*:.*:.*:.*:.*:.*:.*:.*

```
cpe:2.3:o:pdqinc:laserwash_360_plus_firmware:-:*:*:*:*:*:
```

cpe:2.3:o:pdqinc:laserwash 360 plus firmware:-:*:*:*:*:*.*

```
cpe:2.3:h:pdginc:laserwash_autoexpress:-.*:.*:.*:.*:.*:.*
```

```
cpe:2.3:h:pdginc:laserwash_autoexpress:-.*:*:*:*:*:*:
```

```
cpe:2.3:o:pdqinc:laserwash_autoexpress_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:pdqinc:laserwash_autoexpress_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:pdqinc:laserwash_autoexpress_plus:-:*:*:*:*:*:*

cpe:2.3:h:pdqinc:laserwash_autoexpress_plus:-:*:*:*:*:*:

```
cpe:2.3:o:pdqinc:laserwash autoexpress plus firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:pdginc:laserwash autoexpress plus firmware:-:*:*:*:*:*:
```

cpe:2.3:h:pdqinc:laserwash_g5:-:*:*:*:*:*:*:

```
cpe:2.3:h:pdqinc:laserwash_g5:-:*:*:*:*:*:
```

```
cpe:2.3:o:pdqinc:laserwash_g5_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:pdqinc:laserwash_g5_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:pdqinc:laserwash_g5_s:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:pdqinc:laserwash_g5_s:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:pdqinc:laserwash_g5_s_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:pdqinc:laserwash q5 s firmware:-.*:.*:.*:.*:.*:.*
```

```
cpe:2.3:h:pdqinc:laserwash m5:-:*:*:*:*:*:
```

[illegible]

cpe:2.3:n:pdqinc:laserwash_m5_firmware:-:*****:
cpe:2.3:o:pdqinc:laserwash_m5_firmware:-:*****:
cpe:2.3:o:pdqinc:laserwash_m5_firmware:-:*****:
cpe:2.3:h:pdqinc:protouch_autogloss:-:*****:
cpe:2.3:h:pdqinc:protouch_autogloss:-:*****:
cpe:2.3:o:pdqinc:protouch_autogloss_firmware:-:*****:
cpe:2.3:o:pdqinc:protouch_autogloss_firmware:-:*****:
cpe:2.3:h:pdqinc:protouch_icon:-:*****:
cpe:2.3:h:pdqinc:protouch_icon:-:*****:
cpe:2.3:o:pdqinc:protouch_icon_firmware:-:*****:
cpe:2.3:o:pdqinc:protouch_icon_firmware:-:*****:
cpe:2.3:h:pdqinc:protouch_tandem:-:*****:
cpe:2.3:h:pdqinc:protouch_tandem:-:*****:
cpe:2.3:o:pdqinc:protouch_tandem_firmware:-:*****:
cpe:2.3:o:pdqinc:protouch_tandem_firmware:-:*****:

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID→](#)