



CVE-2018-11482

Published on: 05/30/2018 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:24:18 PM UTC

CVE-2018-11482

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [lpc TL-ipc223p-6](#) from [Tp-link](#) contain the following vulnerability:

/usr/lib/luajit/luajit/luasys.lua on TP-LINK IPC TL-IPC223(P)-6, TL-IPC323K-D, TL-IPC325(KP)-*, and TL-IPC40A-4 devices has a hardcoded zMiVw8Kw0oxKXL0 password.

CVE-2018-11482 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **CRITICAL** severity.

CVSS3 Score: **9.8 - CRITICAL**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: **7.5 - HIGH**

Access Vector	Access Complexity	Authentication
NETWORK	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
PARTIAL	PARTIAL	PARTIAL

CVE References

Description	Tags	Link
IOT-pwn-for-fun/TP-LINK-login-Escalation-of-Privileges at master · yough3rt/IOT-pwn-for-fun · GitHub	Broken Link github.com text/html	MISC github.com/yough3rt/IOT-pwn-for-fun/blob/master/TP-LINK-login-Escalation-of-Privileges
Vulnerability Summary for the Week of May 28, 2018 US-	Third Party Advisory	MISC www.us-cert.gov/ncas/bulletins/SB18-155

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware  	Tp-link	lpc TI-ipc223p-6	-	All	All	All
Operating System	Tp-link	lpc TI-ipc223p-6 Firmware	All	All	All	All
Hardware  	Tp-link	lpc TI-ipc223p-6	-	All	All	All
Hardware  	Tp-link	lpc TI-ipc223p-6	-	All	All	All
Operating System	Tp-link	lpc TI-ipc223p-6 Firmware	All	All	All	All
Operating System	Tp-link	lpc TI-ipc223p-6 Firmware	All	All	All	All
Hardware  	Tp-link	TI-ipc323k-d	-	All	All	All
Hardware  	Tp-link	TI-ipc323k-d	-	All	All	All
Operating System	Tp-link	TI-ipc323k-d Firmware	All	All	All	All
Operating System	Tp-link	TI-ipc323k-d Firmware	All	All	All	All
Hardware  	Tp-link	TI-ipc325kp	-	All	All	All
Operating System	Tp-link	TI-ipc325kp Firmware	All	All	All	All
Hardware  	Tp-link	TI-ipc325kp	-	All	All	All
Hardware  	Tp-link	TI-ipc325kp	-	All	All	All
Operating System	Tp-link	TI-ipc325kp Firmware	All	All	All	All
Operating System	Tp-link	TI-ipc325kp Firmware	All	All	All	All
Hardware  	Tp-link	TI-ipc40a-4	-	All	All	All
Hardware  	Tp-link	TI-ipc40a-4	-	All	All	All
Operating System	Tp-link	TI-ipc40a-4 Firmware	All	All	All	All
Operating System	Tp-link	TI-ipc40a-4 Firmware	All	All	All	All

וְיָצֵא

```
cpe:2.3:h:tp-link:ipc_tl-ipc223(p)-6:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:ipc_tl-ipc223(p)-6_firmware:::*:*:*:*:
```

```
cpe:2.3:h:tp-link:ipc_tl-ipc223\:(p\)-6:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:ipc_tl-ipc223:(p\)-6:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:ipc_tl-ipc223(p)-6_firmware:*.*.*.*.*.*.*.*
```

```
cpe:2.3:o:tp-link:ipc_tl-ipc223(p)-6_firmware:::*:*:*:*:
```

```
cpe:2.3:h:tp-link:tl-ipc323k-d:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:tl-ipc323k-d:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:tl-ipc323k-d firmware:*.*.*.*.*.*.*.*
```

```
cpe:2.3:o:tp-link:tl-ipc323k-d firmware:*.:.:.:.:.:.:.:.:
```

```
cpe:2.3:h:tp-link:tl-ipc325(kp):-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:tl-ipc325(kp) firmware:*:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:tl-ipc325\((kp\)):-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:tl-ipc325\((kp\)):-:*:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:tl-ipc325\(\kp\) firmware:*.~*~*~*~*~*~*~*~*~*
```

```
cpe:2.3:o:tp-link:tl-ipc325\(\kp\) firmware:*:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:tl-ipc40a-4:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:tl-ipc40a-4:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:tl-ipc40a-4 firmware:*.:.:.:.:.:.:.:
```

```
cpe:2.3:o:tp-link:tl-ipc40a-4 firmware:*.:.:.:.:.:.:.:
```

No vendor comments have been submitted for this CVE

[← Previous ID](#)

Next ID→

