



CVE-2018-12004

Published on: 05/24/2019 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:24:23 PM UTC


CVE-2018-12004

Source: Mitre

Source: NIST

CVE.ORG

Print: PDF



Certain versions of [Mdm9206](#) from [Qualcomm](#) contain the following vulnerability:

Secure keypad is unlocked with secure display still intact in Snapdragon Auto, Snapdragon Compute, Snapdragon Consumer Electronics Connectivity, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon Mobile, Snapdragon Voice & Music, Snapdragon Wearables in MDM9206, MDM9607, MDM9650, MDM9655, QCS605, SD 210/SD 212/SD 205, SD 410/12, SD 615/16/SD 415, SD 636, SD 712 / SD 710 / SD 670, SD 835, SD 845 / SD 850, SD 8CX, SDA660, SDM630, SDM660, SXR1130

CVE-2018-12004 has been assigned by [Q](#) product-security@qualcomm.com to track the vulnerability - currently rated as **MEDIUM** severity.

Affected Vendor/Software: [Q](#) **Qualcomm, Inc. - Snapdragon Auto, Snapdragon Compute, Snapdragon Consumer Electronics Connectivity, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon Mobile, Snapdragon Voice & Music, Snapdragon Wearables** version **MDM9206, MDM9607, MDM9650, MDM9655, QCS605, SD 210/SD 212/SD 205, SD 410/12, SD 615/16/SD 415, SD 636, SD 712 / SD 710 / SD 670, SD 835, SD 845 / SD 850, SD 8CX, SDA660, SDM630, SDM660, SXR1130**

CVSS3 Score: **5.5 - MEDIUM**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
LOCAL	LOW	LOW	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	NONE	NONE

CVSS2 Score: **4.9 - MEDIUM**

Access Vector	Access Complexity	Authentication
LOCAL	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact

COMPLETE

NONE

NONE

CVE References

Description	Tags	Link
Bulletins Qualcomm	Vendor Advisory www.qualcomm.com text/html	CONFIRM www.qualcomm.com/company/product-security/bulletins#_CVE-2018-12004

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Qualcomm	Mdm9206	-	All	All	All
Hardware 	Qualcomm	Mdm9206	-	All	All	All
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All
Hardware 	Qualcomm	Mdm9607	-	All	All	All
Hardware 	Qualcomm	Mdm9607	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Hardware 	Qualcomm	Mdm9650	-	All	All	All
Hardware 	Qualcomm	Mdm9650	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All
Hardware 	Qualcomm	Mdm9655	-	All	All	All
Hardware 	Qualcomm	Mdm9655	-	All	All	All
Operating System	Qualcomm	Mdm9655 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9655 Firmware	-	All	All	All

Hardware  	Qualcomm	Qcs605	-	All	All	All
Hardware  	Qualcomm	Qcs605	-	All	All	All
Operating System	Qualcomm	Qcs605 Firmware	-	All	All	All
Operating System	Qualcomm	Qcs605 Firmware	-	All	All	All
Hardware  	Qualcomm	Sda660	-	All	All	All
Hardware  	Qualcomm	Sda660	-	All	All	All
Operating System	Qualcomm	Sda660 Firmware	-	All	All	All
Operating System	Qualcomm	Sda660 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm630	-	All	All	All
Hardware  	Qualcomm	Sdm630	-	All	All	All
Operating System	Qualcomm	Sdm630 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm630 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm660	-	All	All	All
Hardware  	Qualcomm	Sdm660	-	All	All	All
Operating System	Qualcomm	Sdm660 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm660 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 205	-	All	All	All
Hardware  	Qualcomm	Sd 205	-	All	All	All
Operating System	Qualcomm	Sd 205 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 205 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 210	-	All	All	All
Hardware  	Qualcomm	Sd 210	-	All	All	All
Operating System	Qualcomm	Sd 210 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 210 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 212	-	All	All	All
Hardware  	Qualcomm	Sd 212	-	All	All	All
Operating System	Qualcomm	Sd 212 Firmware	-	All	All	All

Operating System	Qualcomm	Sd 212 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 410	-	All	All	All
Hardware  	Qualcomm	Sd 410	-	All	All	All
Operating System	Qualcomm	Sd 410 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 410 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 412	-	All	All	All
Hardware  	Qualcomm	Sd 412	-	All	All	All
Operating System	Qualcomm	Sd 412 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 412 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 415	-	All	All	All
Hardware  	Qualcomm	Sd 415	-	All	All	All
Operating System	Qualcomm	Sd 415 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 415 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 615	-	All	All	All
Hardware  	Qualcomm	Sd 615	-	All	All	All
Operating System	Qualcomm	Sd 615 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 615 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 616	-	All	All	All
Hardware  	Qualcomm	Sd 616	-	All	All	All
Operating System	Qualcomm	Sd 616 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 616 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 636	-	All	All	All
Hardware  	Qualcomm	Sd 636	-	All	All	All
Operating System	Qualcomm	Sd 636 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 636 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 670	-	All	All	All

Hardware  	Qualcomm	Sd 670	-	All	All	All
Operating System	Qualcomm	Sd 670 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 670 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 710	-	All	All	All
Hardware  	Qualcomm	Sd 710	-	All	All	All
Operating System	Qualcomm	Sd 710 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 710 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 712	-	All	All	All
Hardware  	Qualcomm	Sd 712	-	All	All	All
Operating System	Qualcomm	Sd 712 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 712 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 835	-	All	All	All
Hardware  	Qualcomm	Sd 835	-	All	All	All
Operating System	Qualcomm	Sd 835 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 835 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 845	-	All	All	All
Hardware  	Qualcomm	Sd 845	-	All	All	All
Operating System	Qualcomm	Sd 845 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 845 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 850	-	All	All	All
Hardware  	Qualcomm	Sd 850	-	All	All	All
Operating System	Qualcomm	Sd 850 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 850 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 8cx	-	All	All	All
Hardware  	Qualcomm	Sd 8cx	-	All	All	All
Operating System	Qualcomm	Sd 8cx Firmware	-	All	All	All
Operating	Qualcomm	Sd 8cx Firmware	-	All	All	All

System						
Hardware	Qualcomm	Sxr1130	-	All	All	All
Hardware	Qualcomm	Sxr1130	-	All	All	All
Operating System	Qualcomm	Sxr1130 Firmware	-	All	All	All
Operating System	Qualcomm	Sxr1130 Firmware	-	All	All	All
cpe:2.3:h:qualcomm:mdm9206:-:*:*:*:*:*:						
cpe:2.3:h:qualcomm:mdm9206:-:*:*:*:*:*:						
cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*:						
cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*:						
cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*:*:						
cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*::~:						
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*::~:						
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*::~:						
cpe:2.3:h:qualcomm:mdm9650:-:*:*:*:*::~:						
cpe:2.3:h:qualcomm:mdm9650:-:*:*:*:*::~:						
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*::~:						
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*::~:						
cpe:2.3:h:qualcomm:mdm9655:-:*:*:*:*::~:						
cpe:2.3:h:qualcomm:mdm9655:-:*:*:*:*::~:						
cpe:2.3:o:qualcomm:mdm9655_firmware:-:*:*:*:*::~:						
cpe:2.3:o:qualcomm:mdm9655_firmware:-:*:*:*:*::~:						
cpe:2.3:h:qualcomm:qcs605:-:*:*:*:*::~:						
cpe:2.3:h:qualcomm:qcs605:-:*:*:*:*::~:						
cpe:2.3:o:qualcomm:qcs605_firmware:-:*:*:*:*::~:						
cpe:2.3:o:qualcomm:qcs605_firmware:-:*:*:*:*::~:						
cpe:2.3:h:qualcomm:sda660:-:*:*:*:*::~:						
cpe:2.3:h:qualcomm:sda660:-:*:*:*:*::~:						
cpe:2.3:o:qualcomm:sda660_firmware:-:*:*:*:*::~:						
cpe:2.3:o:qualcomm:sda660_firmware:-:*:*:*:*::~:						

```
opc.z.o.o.quadcoiiii.gdaooo_iiiiivao. . . . .
```

```
cpe:2.3:h:qualcomm:sdm630:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm630:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdm630_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm630_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm660:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm660:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdm660_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm660_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_205:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_205:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_205_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:sd_205_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_210:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_210:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_210_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_210_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_212:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_212:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_212_firmware:-:*:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:sd_212_firmware:-:*:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_410:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_410:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_410_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_410_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_412:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_412:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_412_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_412_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sd_415:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_415:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_415_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_415_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_615:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_615:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_615_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_615_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_616:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_616:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_616_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_616_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_636:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_636:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_636_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_636_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_670:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_670:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_670_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_670_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_710:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_710:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_710_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_710_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_712:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_712:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_712_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_712_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_712:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_712:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_712_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_712_firmware:-:~::~~::~~::~~::~~::~~::~~:::

cpe:2.3:h:qualcomm:sd_835:-:*****:
cpe:2.3:h:qualcomm:sd_835:-:*****:
cpe:2.3:o:qualcomm:sd_835_firmware:-:*****:
cpe:2.3:o:qualcomm:sd_835_firmware:-:*****:
cpe:2.3:h:qualcomm:sd_845:-:*****:
cpe:2.3:h:qualcomm:sd_845:-:*****:
cpe:2.3:o:qualcomm:sd_845_firmware:-:*****:
cpe:2.3:o:qualcomm:sd_845_firmware:-:*****:
cpe:2.3:h:qualcomm:sd_850:-:*****:
cpe:2.3:h:qualcomm:sd_850:-:*****:
cpe:2.3:o:qualcomm:sd_850_firmware:-:*****:
cpe:2.3:o:qualcomm:sd_850_firmware:-:*****:
cpe:2.3:h:qualcomm:sd_8cx:-:*****:
cpe:2.3:h:qualcomm:sd_8cx:-:*****:
cpe:2.3:o:qualcomm:sd_8cx_firmware:-:*****:
cpe:2.3:o:qualcomm:sd_8cx_firmware:-:*****:
cpe:2.3:h:qualcomm:sxr1130:-:*****:
cpe:2.3:h:qualcomm:sxr1130:-:*****:
cpe:2.3:o:qualcomm:sxr1130_firmware:-:*****:
cpe:2.3:o:qualcomm:sxr1130_firmware:-:*****:

No vendor comments have been submitted for this CVE

[← Previous ID](#)

Next ID→

© CVE.report 2023 |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status status.cve.report