



CVE-2018-12574

[MITRE](#)[NVD](#)[CVE.ORG](#)[Print: PDF](#)

Summary

CVE	CVE-2018-12574
State	PUBLIC
Assigner	cve@mitre.org
Source Priority	CVE Program / NVD first with legacy fallback
Published	2018-07-02 16:29:00 UTC
Updated	2018-09-04 16:13:00 UTC
Description	CSRF exists for all actions in the web interface on TP-Link TL-WR841N v13 00000001 0.9.1 4.16 v0001.0 Build 180119 Re

Risk And Classification

Problem Types: CWE-352

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Tp-link	TL-wr841n	13.0	All	All	All
Hardware	Tp-link	TL-wr841n	13.0	All	All	All
Operating System	Tp-link	TL-wr841n Firmware	0.9.1_4.16	All	All	All
Operating System	Tp-link	TL-wr841n Firmware	0.9.1_4.16	All	All	All

References

Reference	Source	Link	Tags
Page not found - Advices That You Must Listen To Before Learning Online Casino.	MISC	software-talk.org	Broken Link, Third Party
CVE Program record	CVE.ORG	www.cve.org	canonical
NVD vulnerability detail	NVD	nvd.nist.gov	canonical, analysis

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](#)