




CVE-2018-19694

Published on: 03/17/2019 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:24:40 PM UTC

CVE-2018-19694

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [Netbiter Ec150](#) from [Hms-networks](#) contain the following vulnerability:

HMS Industrial Networks Netbiter WS100 3.30.5 devices and previous have reflected XSS in the login form.

CVE-2018-19694 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **MEDIUM** severity.

CVSS3 Score: **6.1 - MEDIUM**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	REQUIRED
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
CHANGED	LOW	LOW	NONE

CVSS2 Score: **4.3 - MEDIUM**

Access Vector	Access Complexity	Authentication
NETWORK	MEDIUM	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
NONE	PARTIAL	NONE

CVE References

Description	Tags	Link
Bugtraq: [SYSS-2018-042] XSS in HMS Netbiter WS100 - CVE-2018-19694	Exploit Mailing List Third Party Advisory seclists.org text/html	MISC seclists.org/bugtraq/2019/Jan/9

Netbiter communication gateways and accessories

Product

Third Party Advisory

www.netbiter.com

text/html

 MISC www.netbiter.com/products

Patch

Vendor Advisory

www.hms-networks.com

application/pdf

 CONFIRM www.hms-networks.com/docs/librariesprovider6/cybersecurity/hms-security-advisory-2018-12-04-001-ec150-ec250-lc310-lc350-ws100-ws200-cve-2018-19694.pdf

HMS Netbiter WS100 3.30.5 Cross Site Scripting ≈ Packet Storm

Exploit

Third Party Advisory

VDB Entry

packetstormsecurity.com

text/html

 MISC packetstormsecurity.com/files/151119/HMS-Netbiter-WS100-3.30.5-Cross-Site-Scripting.html

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Hms-networks	Netbiter Ec150	-	All	All	All
Hardware 	Hms-networks	Netbiter Ec150	-	All	All	All
Operating System	Hms-networks	Netbiter Ec150 Firmware	All	All	All	All
Hardware 	Hms-networks	Netbiter Ec250	-	All	All	All
Hardware 	Hms-networks	Netbiter Ec250	-	All	All	All
Operating System	Hms-networks	Netbiter Ec250 Firmware	All	All	All	All
Hardware 	Hms-networks	Netbiter Lc310	-	All	All	All
Hardware 	Hms-networks	Netbiter Lc310	-	All	All	All
Operating System	Hms-networks	Netbiter Lc310 Firmware	All	All	All	All
Hardware 	Hms-networks	Netbiter Lc310 Thingworx	-	All	All	All
Hardware 	Hms-networks	Netbiter Lc310 Thingworx	-	All	All	All
Operating System	Hms-networks	Netbiter Lc310 Thingworx Firmware	All	All	All	All
Hardware 	Hms-networks	Netbiter Lc350	-	All	All	All
Hardware 	Hms-networks	Netbiter Lc350	-	All	All	All
Operating System	Hms-networks	Netbiter Lc350 Firmware	All	All	All	All

Hardware		Hms-networks	Netbiter Lc350 Thingworx	-	All	All	All
Hardware		Hms-networks	Netbiter Lc350 Thingworx	-	All	All	All
Operating System		Hms-networks	Netbiter Lc350 Thingworx Firmware	All	All	All	All
Hardware		Hms-networks	Netbiter Ws100	-	All	All	All
Hardware		Hms-networks	Netbiter Ws100	-	All	All	All
Operating System		Hms-networks	Netbiter Ws100 Firmware	All	All	All	All
Hardware		Hms-networks	Netbiter Ws200	-	All	All	All
Hardware		Hms-networks	Netbiter Ws200	-	All	All	All
Operating System		Hms-networks	Netbiter Ws200 Firmware	All	All	All	All
cpe:2.3:h:hms-networks:netbiter_ec150:-:*:*:*:*:*:							
cpe:2.3:h:hms-networks:netbiter_ec150:-:*:*:*:*:*:							
cpe:2.3:o:hms-networks:netbiter_ec150_firmware:*:*:*:*:*:							
cpe:2.3:h:hms-networks:netbiter_ec250:-:*:*:*:*:*:							
cpe:2.3:h:hms-networks:netbiter_ec250:-:*:*:*:*::~:							
cpe:2.3:o:hms-networks:netbiter_ec250_firmware:*:*:*:*:*:							
cpe:2.3:h:hms-networks:netbiter_lc310:-:*:*:*:*:*:							
cpe:2.3:h:hms-networks:netbiter_lc310:-:*:*:*:*::~:							
cpe:2.3:o:hms-networks:netbiter_lc310_firmware:*:*:*:*:*:							
cpe:2.3:h:hms-networks:netbiter_lc310_thingworx:-:*:*:*:*::~:							
cpe:2.3:h:hms-networks:netbiter_lc310_thingworx:-:*:*:*:*:::							
cpe:2.3:o:hms-networks:netbiter_lc310_thingworx_firmware:*:*:*:*:*:							
cpe:2.3:h:hms-networks:netbiter_lc350:-:*:*:*:*:*:							
cpe:2.3:h:hms-networks:netbiter_lc350:-:*:*:*:*::~:							
cpe:2.3:o:hms-networks:netbiter_lc350_firmware:*:*:*:*:*:							
cpe:2.3:h:hms-networks:netbiter_lc350_thingworx:-:*:*:*:*::~:							
cpe:2.3:h:hms-networks:netbiter_lc350_thingworx:-:*:*:*:*:::							
cpe:2.3:o:hms-networks:netbiter_lc350_thingworx_firmware:*:*:*:*:*:							
cpe:2.3:h:hms-networks:netbiter_ws100:-:*:*:*:*::~:							

cpe:2.3:h:hms-networks:netbiter_ws100:-:*:*:*:*:*:
cpe:2.3:o:hms-networks:netbiter_ws100_firmware:*:*:*:*:*:
cpe:2.3:h:hms-networks:netbiter_ws200:-:*:*:*:*:*:
cpe:2.3:h:hms-networks:netbiter_ws200:-:*:*:*:*:*:
cpe:2.3:o:hms-networks:netbiter_ws200_firmware:*:*:*:*:*:

cpe:2.3:h:hms-networks:netbiter_ws100:-:*:*:*:*:*:
cpe:2.3:o:hms-networks:netbiter_ws100_firmware:*:*:*:*:*:
cpe:2.3:h:hms-networks:netbiter_ws200:-:*:*:*:*:*:
cpe:2.3:h:hms-networks:netbiter_ws200:-:*:*:*:*:*:
cpe:2.3:o:hms-networks:netbiter_ws200_firmware:*:*:*:*:*:

cpe:2.3:h:hms-networks:netbiter_ws100:-:*:*:*:*:*:
cpe:2.3:o:hms-networks:netbiter_ws100_firmware:*:*:*:*:*:
cpe:2.3:h:hms-networks:netbiter_ws200:-:*:*:*:*:*:
cpe:2.3:h:hms-networks:netbiter_ws200:-:*:*:*:*:*:
cpe:2.3:o:hms-networks:netbiter_ws200_firmware:*:*:*:*:*:

cpe:2.3:h:hms-networks:netbiter_ws100:-:*:*:*:*:*:
cpe:2.3:o:hms-networks:netbiter_ws100_firmware:*:*:*:*:*:
cpe:2.3:h:hms-networks:netbiter_ws200:-:*:*:*:*:*:
cpe:2.3:h:hms-networks:netbiter_ws200:-:*:*:*:*:*:
cpe:2.3:o:hms-networks:netbiter_ws200_firmware:*:*:*:*:*:

cpe:2.3:h:hms-networks:netbiter_ws100:-:*:*:*:*:*:
cpe:2.3:o:hms-networks:netbiter_ws100_firmware:*:*:*:*:*:
cpe:2.3:h:hms-networks:netbiter_ws200:-:*:*:*:*:*:
cpe:2.3:h:hms-networks:netbiter_ws200:-:*:*:*:*:*:
cpe:2.3:o:hms-networks:netbiter_ws200_firmware:*:*:*:*:*:

No vendor comments have been submitted for this CVE

← Previous ID

Next ID→

© CVE.report 2023 |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status status.cve.report