



CVE-2019-10551

Published on: 04/16/2020 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:27:40 PM UTC


CVE-2019-10551

[Source: Mitre](#)

[Source: NIST](#)

[CVE.ORG](#)

[Print: PDF](#)



Certain versions of [Apq8009](#) from [Qualcomm](#) contain the following vulnerability:

String error while processing non standard SIP messages received can lead to buffer overread and then denial of service in Snapdragon Auto, Snapdragon Compute, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon IoT, Snapdragon Mobile, Snapdragon Voice & Music, Snapdragon Wearables in APQ8009, APQ8017,

APQ8053, APQ8096, APQ8096AU, APQ8098, MDM9150, MDM9206, MDM9607, MDM9615, MDM9625, MDM9635M, MDM9640, MDM9645, MDM9650, MDM9655, MSM8905, MSM8909, MSM8909W, MSM8917, MSM8920, MSM8937, MSM8940, MSM8953, MSM8996AU, MSM8998, Nicobar, QCM2150, QCS605, QM215, Rennell, SC7180, SC8180X, SDA660, SDA845, SDM429, SDM429W, SDM439, SDM450, SDM630, SDM632, SDM636, SDM660, SDM670, SDM710, SDM845, SDM850, SDX20, SDX24, SDX55, SM6150, SM7150, SM8150, SXR1130

CVE-2019-10551 has been assigned by [Q](#) product-security@qualcomm.com to track the vulnerability - currently rated as **CRITICAL** severity.

Affected Vendor/Software: [Q](#) Qualcomm, Inc. - Snapdragon Auto, Snapdragon Compute, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon IoT, Snapdragon Mobile, Snapdragon Voice & Music, Snapdragon Wearables version APQ8009, APQ8017, APQ8053, APQ8096, APQ8096AU, APQ8098, MDM9150, MDM9206, MDM9607, MDM9615, MDM9625, MDM9635M, MDM9640, MDM9645, MDM9650, MDM9655, MSM8905, MSM8909, MSM8909W, MSM8917, MSM8920, MSM8937, MSM8940, MSM8953, MSM8996AU, MSM8998, Nicobar, QCM2150, QCS605, QM215, Rennell, SC7180, SC8180X, SDA660, SDA845, SDM429, SDM429W, SDM439, SDM450, SDM630, SDM632, SDM636, SDM660, SDM670, SDM710, SDM845, SDM850, SDX20, SDX24, SDX55, SM6150, SM7150, SM8150, SXR1130

CVSS3 Score: **9.1 - CRITICAL**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	NONE	HIGH

CVSS2 Score: **9.4 - HIGH**

Access
Vector

Access
Complexity

Authentication

NETWORK

LOW

NONE

Confidentiality
Impact

Integrity
Impact

Availability
Impact

COMPLETE

NONE

COMPLETE

CVE References

Description

Tags

Link

April 2020 Bulletin |
Qualcomm

Vendor Advisory
www.qualcomm.com
text/html

 **CONFIRM** www.qualcomm.com/company/product-security/bulletins/april-2020-bulletin

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Qualcomm	Apq8009	-	All	All	All
Hardware 	Qualcomm	Apq8009	-	All	All	All
Operating System	Qualcomm	Apq8009 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8009 Firmware	-	All	All	All
Hardware 	Qualcomm	Apq8017	-	All	All	All
Hardware 	Qualcomm	Apq8017	-	All	All	All
Operating System	Qualcomm	Apq8017 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8017 Firmware	-	All	All	All
Hardware 	Qualcomm	Apq8053	-	All	All	All
Hardware 	Qualcomm	Apq8053	-	All	All	All
Operating System	Qualcomm	Apq8053 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8053 Firmware	-	All	All	All
Hardware 	Qualcomm	Apq8096	-	All	All	All

Hardware 	Qualcomm	Apq8096	-	All	All	All
Hardware 	Qualcomm	Apq8096au	-	All	All	All
Hardware 	Qualcomm	Apq8096au	-	All	All	All
Operating System	Qualcomm	Apq8096au Firmware	-	All	All	All
Operating System	Qualcomm	Apq8096au Firmware	-	All	All	All
Operating System	Qualcomm	Apq8096 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8096 Firmware	-	All	All	All
Hardware 	Qualcomm	Apq8098	-	All	All	All
Hardware 	Qualcomm	Apq8098	-	All	All	All
Operating System	Qualcomm	Apq8098 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8098 Firmware	-	All	All	All
Hardware 	Qualcomm	Mdm9150	-	All	All	All
Hardware 	Qualcomm	Mdm9150	-	All	All	All
Operating System	Qualcomm	Mdm9150 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9150 Firmware	-	All	All	All
Hardware 	Qualcomm	Mdm9206	-	All	All	All
Hardware 	Qualcomm	Mdm9206	-	All	All	All
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All
Hardware 	Qualcomm	Mdm9607	-	All	All	All
Hardware 	Qualcomm	Mdm9607	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Hardware 	Qualcomm	Mdm9615	-	All	All	All
Hardware 	Qualcomm	Mdm9615	-	All	All	All
Operating System	Qualcomm	Mdm9615 Firmware	-	All	All	All

Operating System	Qualcomm	Mdm9615 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9625	-	All	All	All
Hardware  	Qualcomm	Mdm9625	-	All	All	All
Operating System	Qualcomm	Mdm9625 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9625 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9635m	-	All	All	All
Hardware  	Qualcomm	Mdm9635m	-	All	All	All
Operating System	Qualcomm	Mdm9635m Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9635m Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9640	-	All	All	All
Hardware  	Qualcomm	Mdm9640	-	All	All	All
Operating System	Qualcomm	Mdm9640 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9640 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9645	-	All	All	All
Hardware  	Qualcomm	Mdm9645	-	All	All	All
Operating System	Qualcomm	Mdm9645 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9645 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9650	-	All	All	All
Hardware  	Qualcomm	Mdm9650	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9655	-	All	All	All
Hardware  	Qualcomm	Mdm9655	-	All	All	All
Operating System	Qualcomm	Mdm9655 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9655 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8905	-	All	All	All
Hardware  	Qualcomm	Msm8905	-	All	All	All

Operating System	Qualcomm	Msm8905 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8905 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8909	-	All	All	All
Hardware  	Qualcomm	Msm8909	-	All	All	All
Hardware  	Qualcomm	Msm8909w	-	All	All	All
Hardware  	Qualcomm	Msm8909w	-	All	All	All
Operating System	Qualcomm	Msm8909w Firmware	-	All	All	All
Operating System	Qualcomm	Msm8909w Firmware	-	All	All	All
Operating System	Qualcomm	Msm8909 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8909 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8917	-	All	All	All
Hardware  	Qualcomm	Msm8917	-	All	All	All
Operating System	Qualcomm	Msm8917 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8917 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8920	-	All	All	All
Hardware  	Qualcomm	Msm8920	-	All	All	All
Operating System	Qualcomm	Msm8920 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8920 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8937	-	All	All	All
Hardware  	Qualcomm	Msm8937	-	All	All	All
Operating System	Qualcomm	Msm8937 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8937 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8940	-	All	All	All
Hardware  	Qualcomm	Msm8940	-	All	All	All
Operating System	Qualcomm	Msm8940 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8940 Firmware	-	All	All	All

Hardware  	Qualcomm	Msm8953	-	All	All	All
Hardware  	Qualcomm	Msm8953	-	All	All	All
Operating System	Qualcomm	Msm8953 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8953 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8996au	-	All	All	All
Hardware  	Qualcomm	Msm8996au	-	All	All	All
Operating System	Qualcomm	Msm8996au Firmware	-	All	All	All
Operating System	Qualcomm	Msm8996au Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8998	-	All	All	All
Hardware  	Qualcomm	Msm8998	-	All	All	All
Operating System	Qualcomm	Msm8998 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8998 Firmware	-	All	All	All
Hardware  	Qualcomm	Nicobar	-	All	All	All
Hardware  	Qualcomm	Nicobar	-	All	All	All
Operating System	Qualcomm	Nicobar Firmware	-	All	All	All
Operating System	Qualcomm	Nicobar Firmware	-	All	All	All
Hardware  	Qualcomm	Qcm2150	-	All	All	All
Hardware  	Qualcomm	Qcm2150	-	All	All	All
Operating System	Qualcomm	Qcm2150 Firmware	-	All	All	All
Operating System	Qualcomm	Qcm2150 Firmware	-	All	All	All
Hardware  	Qualcomm	Qcs605	-	All	All	All
Hardware  	Qualcomm	Qcs605	-	All	All	All
Operating System	Qualcomm	Qcs605 Firmware	-	All	All	All
Operating System	Qualcomm	Qcs605 Firmware	-	All	All	All
Hardware  	Qualcomm	Qm215	-	All	All	All
Hardware  	Qualcomm	Qm215	-	All	All	All
Operating	Qualcomm	Qm215 Firmware	-	All	All	All

System						
Operating System	Qualcomm	Qm215 Firmware	-	All	All	All
Hardware  	Qualcomm	Rennell	-	All	All	All
Hardware  	Qualcomm	Rennell	-	All	All	All
Operating System	Qualcomm	Rennell Firmware	-	All	All	All
Operating System	Qualcomm	Rennell Firmware	-	All	All	All
Hardware  	Qualcomm	Sc7180	-	All	All	All
Hardware  	Qualcomm	Sc7180	-	All	All	All
Operating System	Qualcomm	Sc7180 Firmware	-	All	All	All
Operating System	Qualcomm	Sc7180 Firmware	-	All	All	All
Hardware  	Qualcomm	Sc8180x	-	All	All	All
Hardware  	Qualcomm	Sc8180x	-	All	All	All
Operating System	Qualcomm	Sc8180x Firmware	-	All	All	All
Operating System	Qualcomm	Sc8180x Firmware	-	All	All	All
Hardware  	Qualcomm	Sda660	-	All	All	All
Hardware  	Qualcomm	Sda660	-	All	All	All
Operating System	Qualcomm	Sda660 Firmware	-	All	All	All
Operating System	Qualcomm	Sda660 Firmware	-	All	All	All
Hardware  	Qualcomm	Sda845	-	All	All	All
Hardware  	Qualcomm	Sda845	-	All	All	All
Operating System	Qualcomm	Sda845 Firmware	-	All	All	All
Operating System	Qualcomm	Sda845 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm429	-	All	All	All
Hardware  	Qualcomm	Sdm429	-	All	All	All
Hardware  	Qualcomm	Sdm429w	-	All	All	All
Hardware  	Qualcomm	Sdm429w	-	All	All	All
Operating System	Qualcomm	Sdm429w Firmware	-	All	All	All

Operating System	Qualcomm	Sdm429w Firmware	-	All	All	All
Operating System	Qualcomm	Sdm429 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm429 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm439	-	All	All	All
Hardware  	Qualcomm	Sdm439	-	All	All	All
Operating System	Qualcomm	Sdm439 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm439 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm450	-	All	All	All
Hardware  	Qualcomm	Sdm450	-	All	All	All
Operating System	Qualcomm	Sdm450 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm450 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm630	-	All	All	All
Hardware  	Qualcomm	Sdm630	-	All	All	All
Operating System	Qualcomm	Sdm630 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm630 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm632	-	All	All	All
Hardware  	Qualcomm	Sdm632	-	All	All	All
Operating System	Qualcomm	Sdm632 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm632 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm636	-	All	All	All
Hardware  	Qualcomm	Sdm636	-	All	All	All
Operating System	Qualcomm	Sdm636 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm636 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm660	-	All	All	All
Hardware  	Qualcomm	Sdm660	-	All	All	All
Operating System	Qualcomm	Sdm660 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm660 Firmware	-	All	All	All

Operating System	Qualcomm	Sdm660 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm670	-	All	All	All
Hardware  	Qualcomm	Sdm670	-	All	All	All
Operating System	Qualcomm	Sdm670 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm670 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm710	-	All	All	All
Hardware  	Qualcomm	Sdm710	-	All	All	All
Operating System	Qualcomm	Sdm710 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm710 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm845	-	All	All	All
Hardware  	Qualcomm	Sdm845	-	All	All	All
Operating System	Qualcomm	Sdm845 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm845 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm850	-	All	All	All
Hardware  	Qualcomm	Sdm850	-	All	All	All
Operating System	Qualcomm	Sdm850 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm850 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdx20	-	All	All	All
Hardware  	Qualcomm	Sdx20	-	All	All	All
Operating System	Qualcomm	Sdx20 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx20 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdx24	-	All	All	All
Hardware  	Qualcomm	Sdx24	-	All	All	All
Operating System	Qualcomm	Sdx24 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx24 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdx55	-	All	All	All
Hardware  	Qualcomm	Sdx55	-	All	All	All

Operating System	Qualcomm	Sdx55 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx55 Firmware	-	All	All	All
Hardware  	Qualcomm	Sm6150	-	All	All	All
Hardware  	Qualcomm	Sm6150	-	All	All	All
Operating System	Qualcomm	Sm6150 Firmware	-	All	All	All
Operating System	Qualcomm	Sm6150 Firmware	-	All	All	All
Hardware  	Qualcomm	Sm7150	-	All	All	All
Hardware  	Qualcomm	Sm7150	-	All	All	All
Operating System	Qualcomm	Sm7150 Firmware	-	All	All	All
Operating System	Qualcomm	Sm7150 Firmware	-	All	All	All
Hardware  	Qualcomm	Sm8150	-	All	All	All
Hardware  	Qualcomm	Sm8150	-	All	All	All
Operating System	Qualcomm	Sm8150 Firmware	-	All	All	All
Operating System	Qualcomm	Sm8150 Firmware	-	All	All	All
Hardware  	Qualcomm	Sxr1130	-	All	All	All
Hardware  	Qualcomm	Sxr1130	-	All	All	All
Operating System	Qualcomm	Sxr1130 Firmware	-	All	All	All
Operating System	Qualcomm	Sxr1130 Firmware	-	All	All	All
cpe:2.3:h:qualcomm:apq8009:-:~::~~::~~:::						
cpe:2.3:h:qualcomm:apq8009:-:~::~~::~~:::						
cpe:2.3:o:qualcomm:apq8009_firmware:-:~::~~::~~:::						
cpe:2.3:o:qualcomm:apq8009_firmware:-:~::~~::~~:::						
cpe:2.3:h:qualcomm:apq8017:-:~::~~::~~:::						
cpe:2.3:h:qualcomm:apq8017:-:~::~~::~~:::						
cpe:2.3:o:qualcomm:apq8017_firmware:-:~::~~::~~:::						
cpe:2.3:o:qualcomm:apq8017_firmware:-:~::~~::~~:::						
cpe:2.3:h:qualcomm:apq8053:-:~::~~::~~:::						

спр.з.с.п.гидроотримн.архивов.

cpe:2.3:h:qualcomm:apq8053:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:apq8053_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:apq8053_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:apq8096:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:apq8096:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:apq8096au:-:*~::~:

cpe:2.3:h:qualcomm:apq8096au:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:apq8096au_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:apq8096au_firmware:-:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:apq8096 firmware:-.*:.*:.*:.*:.*:.*:.*:.*
```

```
cpe:2.3:o:qualcomm:apq8096 firmware:-.*:.*:.*:.*:.*:.*:.*:.*
```

```
cpe:2.3:h:qualcomm:apq8098:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:apq8098:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:apq8098_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:apq8098_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:mdm9150:-:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:mdm9150:-:*:*:*:*:*:*:
```

cpe:2.3:o:qualcomm:mdm9150_firmware:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9150 firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:mdm9206:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:mdm9206:-:*:*:*:*:*:*:
```

cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*:

cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*.*

cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*:*
```

cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9615:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9615:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9615_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:mdm9615_firmware:-:*:*:*:*:*.*
```

cpe:2.3:h:qualcomm:mdm9625:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9625:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9625_firmware:-:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:mdm9625_firmware:-:*:*:*:*:*
```

```
cpe:2.3:h:qualcomm:mdm9635m:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:mdm9635m:-:*:*:*:*:*:
```

cpe:2.3:o:qualcomm:mdm9635m_firmware:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9635m_firmware:-:*:*:*:*:*.*
```

cpe:2.3:h:qualcomm:mdm9640:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9640:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9640 firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:mdm9640_firmware:-:*:*:*:*:*
```

cpe:2.3:h:qualcomm:mdm9645:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9645:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9645_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:mdm9645_firmware:-:*:*:*:*:*.*
```

cpe:2.3:h:qualcomm:mdm9650:-:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:mdm9650:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:h:qualcomm:mdm9655:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:mdm9655:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9655_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:mdm9655_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:h:qualcomm:msm8905:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8905:-:::~

```
cpe:2.3:o:qualcomm:msm8905_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8905_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8909:-:*:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:msm8909:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8909w:-:*:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:msm8909w:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8909w_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8909w_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8909_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8909_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:msm8917:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:msm8917:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8917_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8917_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:msm8920:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:msm8920:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8920_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:o:qualcomm:msm8920_firmware:-:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:msm8937:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:msm8937:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8937_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8937_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8940:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:msm8940:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:msm8940_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:msm8940_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:msm8953:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:msm8953:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8953_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8953_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:msm8996au:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:msm8996au:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8996au_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8996au_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8998:-:*:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:msm8998:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8998_firmware:-:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:msm8998_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:nicobar:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:nicobar:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:nicobar_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:nicobar_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:qcm2150:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:qcm2150:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qcm2150_firmware:-:~::~~::~~::~~::~~::~::
```

```
cpe:2.3:o:qualcomm:qcm2150_firmware:-:*:*:*:*:
```

cpe:2.3:h:qualcomm:qcs605:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qcs605:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qcs605 firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qcs605_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:qm215:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qm215:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qm215_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qm215_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:rennell:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:rennell:-:*:*:*:*:*:*:
```

cpe:2.3:o:qualcomm:rennell_firmware:-:*:*:*:*:*:

cpe:2.3:o:qualcomm:rennell_firmware:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sc7180:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sc7180:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sc7180_firmware:-:*:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sc7180_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sc8180x:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sc8180x:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sc8180x_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sc8180x_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sda660:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sda660:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sda660_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sda660_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sda845:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sda845:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sda845_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sda845_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm429:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm429:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdm429w:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdm429w:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdm429w_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm429w_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm429 firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm429_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm439:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdm439:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdm439_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm439_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm450:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdm450:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdm450_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm450_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm630:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm630:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm630 firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm630_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm632:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm632:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm632_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm632_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:h:qualcomm:sdm636:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm636:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm636_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm636_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm660:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm660:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdm660_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm660_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm670:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm670:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm670_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm670_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm710:-:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:sdm710:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm710_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm710_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm845:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm845:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm845_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm845_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm850:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm850:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm850_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm850_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdx20:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdx20:-:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sdx20_firmware:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdx20_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdx24:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdx24:-:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sdx24_firmware:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdx24_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdx55:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdx55:-:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sdx55_firmware:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdx55_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sm6150:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sm6150:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sm6150_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sm6150_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sm7150:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sm7150:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sm7150_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sm7150 firmware:-:*:*:*:*:*.*
```

cpe:2.3:h:qualcomm:sm8150:-:*****:*
cpe:2.3:h:qualcomm:sm8150:-:*****:*
cpe:2.3:h:qualcomm:sm8150:-:*****:*
cpe:2.3:o:qualcomm:sm8150_firmware:-:*****:*
cpe:2.3:o:qualcomm:sm8150_firmware:-:*****:*
cpe:2.3:h:qualcomm:sxr1130:-:*****:*
cpe:2.3:h:qualcomm:sxr1130:-:*****:*
cpe:2.3:o:qualcomm:sxr1130_firmware:-:*****:*
cpe:2.3:o:qualcomm:sxr1130_firmware:-:*****:*

No vendor comments have been submitted for this CVE