



CVE-2019-10558

Published on: 01/21/2020 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:27:39 PM UTC

CVE-2019-10558

[Source: Mitre](#)

[Source: NIST](#)

[CVE.ORG](#)

[Print: PDF](#)



Certain versions of [Apq8009](#) from [Qualcomm](#) contain the following vulnerability:

While transferring data from APPS to DSP, Out of bound in FastRPC HLOS Driver due to the data buffer which can be controlled by DSP in Snapdragon Auto, Snapdragon Compute, Snapdragon Consumer Electronics Connectivity, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon Mobile, Snapdragon Voice & Music,

Snapdragon Wearables in APQ8009, APQ8017, APQ8053, APQ8096AU, APQ8098, MDM9206, MDM9207C, MDM9607, MDM9640, MDM9650, MSM8909W, MSM8917, MSM8920, MSM8937, MSM8940, MSM8953, MSM8996AU, MSM8998, Nicobar, QCN7605, QCS605, QM215, SDA660, SDA845, SDM429, SDM429W, SDM439, SDM450, SDM630, SDM632, SDM636, SDM660, SDM845, SDX20, SDX24, SDX55, SM6150, SM8150, SM8250, SXR1130, SXR2130

CVE-2019-10558 has been assigned by [Q](#) product-security@qualcomm.com to track the vulnerability - currently rated as **HIGH** severity.

Affected Vendor/Software: [Q](#) Qualcomm, Inc. - Snapdragon Auto, Snapdragon Compute, Snapdragon Consumer Electronics Connectivity, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon Mobile, Snapdragon Voice & Music, Snapdragon Wearables version APQ8009, APQ8017, APQ8053, APQ8096AU, APQ8098, MDM9206, MDM9207C, MDM9607, MDM9640, MDM9650, MSM8909W, MSM8917, MSM8920, MSM8937, MSM8940, MSM8953, MSM8996AU, MSM8998, Nicobar, QCN7605, QCS605, QM215, SDA660, SDA845, SDM429, SDM429W, SDM439, SDM450, SDM630, SDM632, SDM636, SDM660, SDM845, SDX20, SDX24, SDX55, SM6150, SM8150, SM8250, SXR1130, SXR2130

CVSS3 Score: **7.8 - HIGH**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
LOCAL	LOW	LOW	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: **7.2 - HIGH**

Access Vector	Access Complexity	Authentication
LOCAL	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
COMPLETE	COMPLETE	COMPLETE

CVE References

Description	Tags	Link
January 2020 Security Bulletin Qualcomm	Patch Vendor Advisory www.qualcomm.com text/html	CONFIRM www.qualcomm.com/company/product-security/bulletins/january-2020-bulletin

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Qualcomm	Apq8009	-	All	All	All
Hardware 	Qualcomm	Apq8009	-	All	All	All
Operating System	Qualcomm	Apq8009 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8009 Firmware	-	All	All	All
Hardware 	Qualcomm	Apq8017	-	All	All	All
Hardware 	Qualcomm	Apq8017	-	All	All	All
Operating System	Qualcomm	Apq8017 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8017 Firmware	-	All	All	All
Hardware 	Qualcomm	Apq8053	-	All	All	All
Hardware 	Qualcomm	Apq8053	-	All	All	All
Operating System	Qualcomm	Apq8053 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8053 Firmware	-	All	All	All
Hardware 	Qualcomm	Apq8096au	-	All	All	All
Hardware 	Qualcomm	Apq8096au	-	All	All	All

Hardware  	Qualcomm	Apq8096au	-	All	All	All
Operating System	Qualcomm	Apq8096au Firmware	-	All	All	All
Operating System	Qualcomm	Apq8096au Firmware	-	All	All	All
Hardware  	Qualcomm	Apq8098	-	All	All	All
Hardware  	Qualcomm	Apq8098	-	All	All	All
Operating System	Qualcomm	Apq8098 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8098 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9206	-	All	All	All
Hardware  	Qualcomm	Mdm9206	-	All	All	All
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9207c	-	All	All	All
Hardware  	Qualcomm	Mdm9207c	-	All	All	All
Operating System	Qualcomm	Mdm9207c Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9207c Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9607	-	All	All	All
Hardware  	Qualcomm	Mdm9607	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9640	-	All	All	All
Hardware  	Qualcomm	Mdm9640	-	All	All	All
Operating System	Qualcomm	Mdm9640 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9640 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9650	-	All	All	All
Hardware  	Qualcomm	Mdm9650	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All

System						
Hardware  	Qualcomm	Msm8909w	-	All	All	All
Hardware  	Qualcomm	Msm8909w	-	All	All	All
Operating System	Qualcomm	Msm8909w Firmware	-	All	All	All
Operating System	Qualcomm	Msm8909w Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8917	-	All	All	All
Hardware  	Qualcomm	Msm8917	-	All	All	All
Operating System	Qualcomm	Msm8917 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8917 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8920	-	All	All	All
Hardware  	Qualcomm	Msm8920	-	All	All	All
Operating System	Qualcomm	Msm8920 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8920 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8937	-	All	All	All
Hardware  	Qualcomm	Msm8937	-	All	All	All
Operating System	Qualcomm	Msm8937 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8937 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8940	-	All	All	All
Hardware  	Qualcomm	Msm8940	-	All	All	All
Operating System	Qualcomm	Msm8940 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8940 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8953	-	All	All	All
Hardware  	Qualcomm	Msm8953	-	All	All	All
Operating System	Qualcomm	Msm8953 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8953 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8996au	-	All	All	All
Hardware  	Qualcomm	Msm8996au	-	All	All	All
Operating System	Qualcomm	Msm8996au Firmware	-	All	All	All

Operating System	Qualcomm	Msm8996au Firmware	-	All	All	All
Operating System	Qualcomm	Msm8996au Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8998	-	All	All	All
Hardware  	Qualcomm	Msm8998	-	All	All	All
Operating System	Qualcomm	Msm8998 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8998 Firmware	-	All	All	All
Hardware  	Qualcomm	Nicobar	-	All	All	All
Hardware  	Qualcomm	Nicobar	-	All	All	All
Operating System	Qualcomm	Nicobar Firmware	-	All	All	All
Operating System	Qualcomm	Nicobar Firmware	-	All	All	All
Hardware  	Qualcomm	Qcn7605	-	All	All	All
Hardware  	Qualcomm	Qcn7605	-	All	All	All
Operating System	Qualcomm	Qcn7605 Firmware	-	All	All	All
Operating System	Qualcomm	Qcn7605 Firmware	-	All	All	All
Hardware  	Qualcomm	Qcs605	-	All	All	All
Hardware  	Qualcomm	Qcs605	-	All	All	All
Operating System	Qualcomm	Qcs605 Firmware	-	All	All	All
Operating System	Qualcomm	Qcs605 Firmware	-	All	All	All
Hardware  	Qualcomm	Qm215	-	All	All	All
Hardware  	Qualcomm	Qm215	-	All	All	All
Operating System	Qualcomm	Qm215 Firmware	-	All	All	All
Operating System	Qualcomm	Qm215 Firmware	-	All	All	All
Hardware  	Qualcomm	Sda660	-	All	All	All
Hardware  	Qualcomm	Sda660	-	All	All	All
Operating System	Qualcomm	Sda660 Firmware	-	All	All	All
Operating System	Qualcomm	Sda660 Firmware	-	All	All	All
Hardware  	Qualcomm	Sda845	-	All	All	All

🇵🇪						
Hardware 🇵🇪	Qualcomm	Sda845	-	All	All	All
Operating System	Qualcomm	Sda845 Firmware	-	All	All	All
Operating System	Qualcomm	Sda845 Firmware	-	All	All	All
Hardware 🇵🇪	Qualcomm	Sdm429	-	All	All	All
Hardware 🇵🇪	Qualcomm	Sdm429	-	All	All	All
Hardware 🇵🇪	Qualcomm	Sdm429w	-	All	All	All
Hardware 🇵🇪	Qualcomm	Sdm429w	-	All	All	All
Operating System	Qualcomm	Sdm429w Firmware	-	All	All	All
Operating System	Qualcomm	Sdm429w Firmware	-	All	All	All
Operating System	Qualcomm	Sdm429 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm429 Firmware	-	All	All	All
Hardware 🇵🇪	Qualcomm	Sdm439	-	All	All	All
Hardware 🇵🇪	Qualcomm	Sdm439	-	All	All	All
Operating System	Qualcomm	Sdm439 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm439 Firmware	-	All	All	All
Hardware 🇵🇪	Qualcomm	Sdm450	-	All	All	All
Hardware 🇵🇪	Qualcomm	Sdm450	-	All	All	All
Operating System	Qualcomm	Sdm450 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm450 Firmware	-	All	All	All
Hardware 🇵🇪	Qualcomm	Sdm630	-	All	All	All
Hardware 🇵🇪	Qualcomm	Sdm630	-	All	All	All
Operating System	Qualcomm	Sdm630 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm630 Firmware	-	All	All	All
Hardware 🇵🇪	Qualcomm	Sdm632	-	All	All	All
Hardware 🇵🇪	Qualcomm	Sdm632	-	All	All	All
Operating System	Qualcomm	Sdm632 Firmware	-	All	All	All

Operating System	Qualcomm	Sdm632 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm636	-	All	All	All
Hardware  	Qualcomm	Sdm636	-	All	All	All
Operating System	Qualcomm	Sdm636 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm636 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm660	-	All	All	All
Hardware  	Qualcomm	Sdm660	-	All	All	All
Operating System	Qualcomm	Sdm660 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm660 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm845	-	All	All	All
Hardware  	Qualcomm	Sdm845	-	All	All	All
Operating System	Qualcomm	Sdm845 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm845 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdx20	-	All	All	All
Hardware  	Qualcomm	Sdx20	-	All	All	All
Operating System	Qualcomm	Sdx20 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx20 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdx24	-	All	All	All
Hardware  	Qualcomm	Sdx24	-	All	All	All
Operating System	Qualcomm	Sdx24 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx24 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdx55	-	All	All	All
Hardware  	Qualcomm	Sdx55	-	All	All	All
Operating System	Qualcomm	Sdx55 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx55 Firmware	-	All	All	All
Hardware  	Qualcomm	Sm6150	-	All	All	All
Hardware  	Qualcomm	Sm6150	-	All	All	All

Operating System	Qualcomm	Sm6150 Firmware	-	All	All	All
Operating System	Qualcomm	Sm6150 Firmware	-	All	All	All
Hardware	Qualcomm	Sm8150	-	All	All	All
Hardware	Qualcomm	Sm8150	-	All	All	All
Operating System	Qualcomm	Sm8150 Firmware	-	All	All	All
Operating System	Qualcomm	Sm8150 Firmware	-	All	All	All
Hardware	Qualcomm	Sm8250	-	All	All	All
Hardware	Qualcomm	Sm8250	-	All	All	All
Operating System	Qualcomm	Sm8250 Firmware	-	All	All	All
Operating System	Qualcomm	Sm8250 Firmware	-	All	All	All
Hardware	Qualcomm	Sxr1130	-	All	All	All
Hardware	Qualcomm	Sxr1130	-	All	All	All
Operating System	Qualcomm	Sxr1130 Firmware	-	All	All	All
Operating System	Qualcomm	Sxr1130 Firmware	-	All	All	All
Hardware	Qualcomm	Sxr2130	-	All	All	All
Hardware	Qualcomm	Sxr2130	-	All	All	All
Operating System	Qualcomm	Sxr2130 Firmware	-	All	All	All
Operating System	Qualcomm	Sxr2130 Firmware	-	All	All	All
<code>cpe:2.3:h:qualcomm:apq8009:-:~::~:</code>						
<code>cpe:2.3:h:qualcomm:apq8009:-:~::~:</code>						
<code>cpe:2.3:o:qualcomm:apq8009_firmware:-:~::~:</code>						
<code>cpe:2.3:o:qualcomm:apq8009_firmware:-:~::~:</code>						
<code>cpe:2.3:h:qualcomm:apq8017:-:~::~:</code>						
<code>cpe:2.3:h:qualcomm:apq8017:-:~::~:</code>						
<code>cpe:2.3:o:qualcomm:apq8017_firmware:-:~::~:</code>						
<code>cpe:2.3:o:qualcomm:apq8017_firmware:-:~::~:</code>						

cpe:2.3:h:qualcomm:apq8053:-:*:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:apq8053:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:apq8053_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:apq8053_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:apq8096au:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:apq8096au:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:apq8096au_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:apq8096au_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:apq8098:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:apq8098:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:apq8098_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:apq8098_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:mdm9206:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9206:-:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*:*

```
cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:qualcomm:mdm9207c:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9207c:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9207c_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9207c_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:qualcomm:mdm9640:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9640:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9640_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9640_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:mdm9650:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9650:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8909w:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:msm8909w:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:msm8909w_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8909w_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:msm8917:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8917:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:msm8917_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8917_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:msm8920:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8920:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:msm8920_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8920_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8937:-:*:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:msm8937:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8937_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8937_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:msm8940:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8940:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:msm8940_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8940 firmware:-.*:.*:.*:.*:.*:.*
```

```
cpe:2.3:h:qualcomm:msm8953:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8953:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:msm8953_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:msm8953_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:h:qualcomm:msm8996au:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8996au:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:msm8996au_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8996au_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8998:-:*:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:msm8998:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8998_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8998_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:nicobar:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:nicobar:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:nicobar_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:nicobar_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:qcn7605:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qcn7605:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qcn7605_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qcn7605_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:qcs605:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qcs605:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qcs605_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qcs605_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:qm215:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:qm215:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qm215_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qm215_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sda660:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sda660:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sda660 firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sda660_firmware:-:~::~~::~~::~~::~~::~::
```

```
cpe:2.3:h:qualcomm:sda845:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sda845:-:*:*:*:*:*:*:
```

cpe:2.3:o:qualcomm:sda845_firmware:-:*~*~*~*~*~*~*
cpe:2.3:h:qualcomm:sdm429:-:*~*~*~*~*~*~*
cpe:2.3:o:qualcomm:sdm429w_firmware:-:*~*~*~*~*~*~*
cpe:2.3:h:qualcomm:sdm429w:-:*~*~*~*~*~*~*
cpe:2.3:o:qualcomm:sdm429w_firmware:-:*~*~*~*~*~*~*
cpe:2.3:h:qualcomm:sdm439:-:*~*~*~*~*~*~*
cpe:2.3:o:qualcomm:sdm439_firmware:-:*~*~*~*~*~*~*
cpe:2.3:h:qualcomm:sdm439_firmware:-:*~*~*~*~*~*~*
cpe:2.3:h:qualcomm:sdm450:-:*~*~*~*~*~*~*
cpe:2.3:o:qualcomm:sdm450_firmware:-:*~*~*~*~*~*~*
cpe:2.3:h:qualcomm:sdm630:-:*~*~*~*~*~*~*
cpe:2.3:o:qualcomm:sdm630_firmware:-:*~*~*~*~*~*~*
cpe:2.3:h:qualcomm:sdm632:-:*~*~*~*~*~*~*
cpe:2.3:o:qualcomm:sdm632_firmware:-:*~*~*~*~*~*~*
cpe:2.3:h:qualcomm:sdm636:-:*~*~*~*~*~*~*
cpe:2.3:o:qualcomm:sdm636_firmware:-:*~*~*~*~*~*~*

cpe:2.3:o:qualcomm:sdm636_firmware:-:*****:
cpe:2.3:o:qualcomm:sdm636_firmware:-:*****:
cpe:2.3:h:qualcomm:sdm660:-:*****:
cpe:2.3:h:qualcomm:sdm660:-:*****:
cpe:2.3:o:qualcomm:sdm660_firmware:-:*****:
cpe:2.3:o:qualcomm:sdm660_firmware:-:*****:
cpe:2.3:h:qualcomm:sdm845:-:*****:
cpe:2.3:h:qualcomm:sdm845:-:*****:
cpe:2.3:o:qualcomm:sdm845_firmware:-:*****:
cpe:2.3:o:qualcomm:sdm845_firmware:-:*****:
cpe:2.3:h:qualcomm:sdx20:-:*****:
cpe:2.3:h:qualcomm:sdx20:-:*****:
cpe:2.3:o:qualcomm:sdx20_firmware:-:*****:
cpe:2.3:o:qualcomm:sdx20_firmware:-:*****:
cpe:2.3:h:qualcomm:sdx24:-:*****:
cpe:2.3:h:qualcomm:sdx24:-:*****:
cpe:2.3:o:qualcomm:sdx24_firmware:-:*****:
cpe:2.3:o:qualcomm:sdx24_firmware:-:*****:
cpe:2.3:h:qualcomm:sdx55:-:*****:
cpe:2.3:h:qualcomm:sdx55:-:*****:
cpe:2.3:o:qualcomm:sdx55_firmware:-:*****:
cpe:2.3:o:qualcomm:sdx55_firmware:-:*****:
cpe:2.3:h:qualcomm:sm6150:-:*****:
cpe:2.3:h:qualcomm:sm6150:-:*****:
cpe:2.3:o:qualcomm:sm6150_firmware:-:*****:
cpe:2.3:o:qualcomm:sm6150_firmware:-:*****:
cpe:2.3:h:qualcomm:sm8150:-:*****:
cpe:2.3:h:qualcomm:sm8150:-:*****:
cpe:2.3:o:qualcomm:sm8150_firmware:-:*****:

cpe:2.3:o:qualcomm:sm8150_firmware:-:*****:
cpe:2.3:o:qualcomm:sm8150_firmware:-:*****:
cpe:2.3:h:qualcomm:sm8250:-:*****:
cpe:2.3:h:qualcomm:sm8250:-:*****:
cpe:2.3:o:qualcomm:sm8250_firmware:-:*****:
cpe:2.3:o:qualcomm:sm8250_firmware:-:*****:
cpe:2.3:h:qualcomm:sxr1130:-:*****:
cpe:2.3:h:qualcomm:sxr1130:-:*****:
cpe:2.3:o:qualcomm:sxr1130_firmware:-:*****:
cpe:2.3:o:qualcomm:sxr1130_firmware:-:*****:
cpe:2.3:h:qualcomm:sxr2130:-:*****:
cpe:2.3:h:qualcomm:sxr2130:-:*****:
cpe:2.3:o:qualcomm:sxr2130_firmware:-:*****:
cpe:2.3:o:qualcomm:sxr2130_firmware:-:*****:

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)