



CVE-2019-10610

Published on: 04/16/2020 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:27:40 PM UTC

CVE-2019-10610


Source: Mitre

Source: NIST

CVE.ORG

Print: PDF

CVSS:31/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:N/A:H



Certain versions of [Apq8009](#) from [Qualcomm](#) contain the following vulnerability:

Possible buffer over read when trying to process SDP message Video media line with frame-size attribute in video Media line in Snapdragon Auto, Snapdragon Compute, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon IoT, Snapdragon Mobile, Snapdragon Voice & Music, Snapdragon Wearables in APQ8009, APQ8017,

APQ8053, APQ8076, APQ8096, APQ8096AU, APQ8098, MDM9150, MDM9206, MDM9607, MDM9615, MDM9625, MDM9635M, MDM9640, MDM9645, MDM9650, MDM9655, MSM8905, MSM8909, MSM8909W, MSM8917, MSM8920, MSM8937, MSM8940, MSM8953, MSM8996AU, MSM8998, Nicobar, QCM2150, QCS605, QM215, Rennell, SC7180, SC8180X, SDA660, SDA845, SDM429, SDM429W, SDM439, SDM450, SDM630, SDM632, SDM636, SDM660, SDM670, SDM710, SDM845, SDM850, SDX20, SDX24, SDX55, SM6150, SM7150, SM8150, SXR1130

CVE-2019-10610 has been assigned by [Q](#) product-security@qualcomm.com to track the vulnerability - currently rated as **CRITICAL** severity.

Affected Vendor/Software: [Q](#) Qualcomm, Inc. - Snapdragon Auto, Snapdragon Compute, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon IoT, Snapdragon Mobile, Snapdragon Voice & Music, Snapdragon Wearables version APQ8009, APQ8017, APQ8053, APQ8076, APQ8096, APQ8096AU, APQ8098, MDM9150, MDM9206, MDM9607, MDM9615, MDM9625, MDM9635M, MDM9640, MDM9645, MDM9650, MDM9655, MSM8905, MSM8909, MSM8909W, MSM8917, MSM8920, MSM8937, MSM8940, MSM8953, MSM8996AU, MSM8998, Nicobar, QCM2150, QCS605, QM215, Rennell, SC7180, SC8180X, SDA660, SDA845, SDM429, SDM429W, SDM439, SDM450, SDM630, SDM632, SDM636, SDM660, SDM670, SDM710, SDM845, SDM850, SDX20, SDX24, SDX55, SM6150, SM7150, SM8150, SXR1130

CVSS3 Score: **9.1 - CRITICAL**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	NONE	HIGH

CVSS2 Score: 9.4 - HIGH						
Access Vector		Access Complexity		Authentication		
NETWORK		LOW		NONE		
Confidentiality Impact		Integrity Impact		Availability Impact		
COMPLETE		NONE		COMPLETE		
CVE References						
Description		Tags		Link		
April 2020 Bulletin Qualcomm		Vendor Advisory www.qualcomm.com text/html		CONFIRM www.qualcomm.com/company/product-security/bulletins/april-2020-bulletin		
By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.						
There are currently no QIDs associated with this CVE						
Known Affected Configurations (CPE V2.3)						
Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Qualcomm	Apq8009	-	All	All	All
Hardware 	Qualcomm	Apq8009	-	All	All	All
Operating System	Qualcomm	Apq8009 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8009 Firmware	-	All	All	All
Hardware 	Qualcomm	Apq8017	-	All	All	All
Hardware 	Qualcomm	Apq8017	-	All	All	All
Operating System	Qualcomm	Apq8017 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8017 Firmware	-	All	All	All
Hardware 	Qualcomm	Apq8053	-	All	All	All
Hardware 	Qualcomm	Apq8053	-	All	All	All
Operating System	Qualcomm	Apq8053 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8053 Firmware	-	All	All	All
Hardware 	Qualcomm	Apq8076	-	All	All	All

Hardware  	Qualcomm	Apq8076	-	All	All	All
Operating System	Qualcomm	Apq8076 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8076 Firmware	-	All	All	All
Hardware  	Qualcomm	Apq8096	-	All	All	All
Hardware  	Qualcomm	Apq8096	-	All	All	All
Hardware  	Qualcomm	Apq8096au	-	All	All	All
Hardware  	Qualcomm	Apq8096au	-	All	All	All
Operating System	Qualcomm	Apq8096au Firmware	-	All	All	All
Operating System	Qualcomm	Apq8096au Firmware	-	All	All	All
Operating System	Qualcomm	Apq8096 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8096 Firmware	-	All	All	All
Hardware  	Qualcomm	Apq8098	-	All	All	All
Hardware  	Qualcomm	Apq8098	-	All	All	All
Operating System	Qualcomm	Apq8098 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8098 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9150	-	All	All	All
Hardware  	Qualcomm	Mdm9150	-	All	All	All
Operating System	Qualcomm	Mdm9150 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9150 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9206	-	All	All	All
Hardware  	Qualcomm	Mdm9206	-	All	All	All
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9607	-	All	All	All
Hardware  	Qualcomm	Mdm9607	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All

Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9615	-	All	All	All
Hardware  	Qualcomm	Mdm9615	-	All	All	All
Operating System	Qualcomm	Mdm9615 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9615 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9625	-	All	All	All
Hardware  	Qualcomm	Mdm9625	-	All	All	All
Operating System	Qualcomm	Mdm9625 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9625 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9635m	-	All	All	All
Hardware  	Qualcomm	Mdm9635m	-	All	All	All
Operating System	Qualcomm	Mdm9635m Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9635m Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9640	-	All	All	All
Hardware  	Qualcomm	Mdm9640	-	All	All	All
Operating System	Qualcomm	Mdm9640 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9640 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9645	-	All	All	All
Hardware  	Qualcomm	Mdm9645	-	All	All	All
Operating System	Qualcomm	Mdm9645 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9645 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9650	-	All	All	All
Hardware  	Qualcomm	Mdm9650	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9655	-	All	All	All
Hardware  	Qualcomm	Mdm9655	-	All	All	All

Operating System	Qualcomm	Mdm9655 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9655 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8905	-	All	All	All
Hardware  	Qualcomm	Msm8905	-	All	All	All
Operating System	Qualcomm	Msm8905 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8905 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8909	-	All	All	All
Hardware  	Qualcomm	Msm8909	-	All	All	All
Hardware  	Qualcomm	Msm8909w	-	All	All	All
Hardware  	Qualcomm	Msm8909w	-	All	All	All
Operating System	Qualcomm	Msm8909w Firmware	-	All	All	All
Operating System	Qualcomm	Msm8909w Firmware	-	All	All	All
Operating System	Qualcomm	Msm8909 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8909 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8917	-	All	All	All
Hardware  	Qualcomm	Msm8917	-	All	All	All
Operating System	Qualcomm	Msm8917 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8917 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8920	-	All	All	All
Hardware  	Qualcomm	Msm8920	-	All	All	All
Operating System	Qualcomm	Msm8920 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8920 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8937	-	All	All	All
Hardware  	Qualcomm	Msm8937	-	All	All	All
Operating System	Qualcomm	Msm8937 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8937 Firmware	-	All	All	All

Hardware  	Qualcomm	Msm8940	-	All	All	All
Hardware  	Qualcomm	Msm8940	-	All	All	All
Operating System	Qualcomm	Msm8940 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8940 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8953	-	All	All	All
Hardware  	Qualcomm	Msm8953	-	All	All	All
Operating System	Qualcomm	Msm8953 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8953 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8996au	-	All	All	All
Hardware  	Qualcomm	Msm8996au	-	All	All	All
Operating System	Qualcomm	Msm8996au Firmware	-	All	All	All
Operating System	Qualcomm	Msm8996au Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8998	-	All	All	All
Hardware  	Qualcomm	Msm8998	-	All	All	All
Operating System	Qualcomm	Msm8998 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8998 Firmware	-	All	All	All
Hardware  	Qualcomm	Nicobar	-	All	All	All
Hardware  	Qualcomm	Nicobar	-	All	All	All
Operating System	Qualcomm	Nicobar Firmware	-	All	All	All
Operating System	Qualcomm	Nicobar Firmware	-	All	All	All
Hardware  	Qualcomm	Qcm2150	-	All	All	All
Hardware  	Qualcomm	Qcm2150	-	All	All	All
Operating System	Qualcomm	Qcm2150 Firmware	-	All	All	All
Operating System	Qualcomm	Qcm2150 Firmware	-	All	All	All
Hardware  	Qualcomm	Qcs605	-	All	All	All
Hardware  	Qualcomm	Qcs605	-	All	All	All
Operating	Qualcomm	Qcs605 Firmware	-	All	All	All

System						
Operating System	Qualcomm	Qcs605 Firmware	-	All	All	All
Hardware  	Qualcomm	Qm215	-	All	All	All
Hardware  	Qualcomm	Qm215	-	All	All	All
Operating System	Qualcomm	Qm215 Firmware	-	All	All	All
Operating System	Qualcomm	Qm215 Firmware	-	All	All	All
Hardware  	Qualcomm	Rennell	-	All	All	All
Hardware  	Qualcomm	Rennell	-	All	All	All
Operating System	Qualcomm	Rennell Firmware	-	All	All	All
Operating System	Qualcomm	Rennell Firmware	-	All	All	All
Hardware  	Qualcomm	Sc7180	-	All	All	All
Hardware  	Qualcomm	Sc7180	-	All	All	All
Operating System	Qualcomm	Sc7180 Firmware	-	All	All	All
Operating System	Qualcomm	Sc7180 Firmware	-	All	All	All
Hardware  	Qualcomm	Sc8180x	-	All	All	All
Hardware  	Qualcomm	Sc8180x	-	All	All	All
Operating System	Qualcomm	Sc8180x Firmware	-	All	All	All
Operating System	Qualcomm	Sc8180x Firmware	-	All	All	All
Hardware  	Qualcomm	Sda660	-	All	All	All
Hardware  	Qualcomm	Sda660	-	All	All	All
Operating System	Qualcomm	Sda660 Firmware	-	All	All	All
Operating System	Qualcomm	Sda660 Firmware	-	All	All	All
Hardware  	Qualcomm	Sda845	-	All	All	All
Hardware  	Qualcomm	Sda845	-	All	All	All
Operating System	Qualcomm	Sda845 Firmware	-	All	All	All
Operating System	Qualcomm	Sda845 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm429	-	All	All	All

Hardware  	Qualcomm	Sdm429	-	All	All	All
Hardware  	Qualcomm	Sdm429w	-	All	All	All
Hardware  	Qualcomm	Sdm429w	-	All	All	All
Operating System	Qualcomm	Sdm429w Firmware	-	All	All	All
Operating System	Qualcomm	Sdm429w Firmware	-	All	All	All
Operating System	Qualcomm	Sdm429 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm429 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm439	-	All	All	All
Hardware  	Qualcomm	Sdm439	-	All	All	All
Operating System	Qualcomm	Sdm439 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm439 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm450	-	All	All	All
Hardware  	Qualcomm	Sdm450	-	All	All	All
Operating System	Qualcomm	Sdm450 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm450 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm630	-	All	All	All
Hardware  	Qualcomm	Sdm630	-	All	All	All
Operating System	Qualcomm	Sdm630 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm630 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm632	-	All	All	All
Hardware  	Qualcomm	Sdm632	-	All	All	All
Operating System	Qualcomm	Sdm632 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm632 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm636	-	All	All	All
Hardware  	Qualcomm	Sdm636	-	All	All	All
Operating System	Qualcomm	Sdm636 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm636 Firmware	-	All	All	All

Operating System	Qualcomm	Sdm636 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm660	-	All	All	All
Hardware  	Qualcomm	Sdm660	-	All	All	All
Operating System	Qualcomm	Sdm660 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm660 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm670	-	All	All	All
Hardware  	Qualcomm	Sdm670	-	All	All	All
Operating System	Qualcomm	Sdm670 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm670 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm710	-	All	All	All
Hardware  	Qualcomm	Sdm710	-	All	All	All
Operating System	Qualcomm	Sdm710 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm710 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm845	-	All	All	All
Hardware  	Qualcomm	Sdm845	-	All	All	All
Operating System	Qualcomm	Sdm845 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm845 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm850	-	All	All	All
Hardware  	Qualcomm	Sdm850	-	All	All	All
Operating System	Qualcomm	Sdm850 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm850 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdx20	-	All	All	All
Hardware  	Qualcomm	Sdx20	-	All	All	All
Operating System	Qualcomm	Sdx20 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx20 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdx24	-	All	All	All
Hardware  	Qualcomm	Sdx24	-	All	All	All

Operating System	Qualcomm	Sdx24 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx24 Firmware	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sdx55	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sdx55	-	All	All	All
Operating System	Qualcomm	Sdx55 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx55 Firmware	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sm6150	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sm6150	-	All	All	All
Operating System	Qualcomm	Sm6150 Firmware	-	All	All	All
Operating System	Qualcomm	Sm6150 Firmware	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sm7150	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sm7150	-	All	All	All
Operating System	Qualcomm	Sm7150 Firmware	-	All	All	All
Operating System	Qualcomm	Sm7150 Firmware	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sm8150	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sm8150	-	All	All	All
Operating System	Qualcomm	Sm8150 Firmware	-	All	All	All
Operating System	Qualcomm	Sm8150 Firmware	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sxr1130	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sxr1130	-	All	All	All
Operating System	Qualcomm	Sxr1130 Firmware	-	All	All	All
Operating System	Qualcomm	Sxr1130 Firmware	-	All	All	All
cpe:2.3:h:qualcomm:apq8009:-:~::~:						
cpe:2.3:h:qualcomm:apq8009:-:~::~:						
cpe:2.3:o:qualcomm:apq8009_firmware:-:~::~:						
cpe:2.3:o:qualcomm:apq8009_firmware:-:~::~:						

cpe:2.3:h:qualcomm:apq8017:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:apq8017:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:apq8017_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:apq8017_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:apq8053:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:apq8053:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:apq8053_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:apq8053_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:apq8076:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:apq8076:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:apq8076_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:apq8076 firmware:-.*:.*.*.*.*.*.*.*
```

cpe:2.3:h:qualcomm:apq8096:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:apq8096:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:apq8096au:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:apq8096au:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:apq8096au firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:apq8096au_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:apq8096_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:apq8096_firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:qualcomm:apq8098:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:apq8098:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:apq8098_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:apq8098_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:mdm9150:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9150:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9150_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:mdm9150_firmware:-:*:*:*:*:*
```

cpe:2.3:h:qualcomm:mdm9206:-:*:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:mdm9206:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:qualcomm:mdm9615:-:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:mdm9615:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9615 firmware:-:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:mdm9615_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:mdm9625:-:*:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:mdm9625:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9625_firmware:-:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:mdm9625_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:h:qualcomm:mdm9635m:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:mdm9635m:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9635m_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:mdm9635m_firmware:-:*:*:*:*:*.*
```

cpe:2.3:h:qualcomm:mdm9640:-:*:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:mdm9640:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9640_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9640_firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:qualcomm:mdm9645:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9645:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9645_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:mdm9645_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:h:qualcomm:mdm9650:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:mdm9650:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*:*:*
```

cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9655:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9655:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9655_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9655_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8905:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:msm8905:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:msm8905_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8905_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8909:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:msm8909:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:msm8909w:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:msm8909w:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:msm8909w_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8909w_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8909_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8909_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:msm8917:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8917:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:msm8917_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8917_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:msm8920:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:msm8920:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8920_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8920_firmware:-:*:*:*:*:*
```

cpe:2.3:h:qualcomm:msm8937:-:*:*:*:*:*:

0907 3'h'001010mm'msm8937_*.*,*,*,*,*,*,*.

cpe:2.3:h:qualcomm:msm8937:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:msm8937_firmware:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:msm8940:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:msm8940:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:msm8940_firmware:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:msm8940_firmware:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:msm8953:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:msm8953:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:msm8953_firmware:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:msm8953_firmware:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:msm8996au:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:msm8996au:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:msm8996au_firmware:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:msm8996au_firmware:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:msm8998:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:msm8998:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:msm8998_firmware:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:msm8998_firmware:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:nicobar:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:nicobar:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:nicobar_firmware:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:nicobar_firmware:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:qcm2150:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:qcm2150:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:qcm2150_firmware:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:qcm2150_firmware:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:qcs605:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:qcs605:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qcs605_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:qcs605_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:qm215:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:qm215:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qm215 firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qm215 firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:qualcomm:rennell:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:rennell:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:rennell firmware:-.*:.*:.*:.*:.*:.*:.*
```

```
cpe:2.3:o:qualcomm:rennell_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sc7180:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sc7180:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sc7180_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sc7180 firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sc8180x:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sc8180x:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sc8180x_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sc8180x_firmware:-:*:*:*:*:*
```

```
cpe:2.3:h:qualcomm:sda660:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sda660:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sda660_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sda660_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sda845:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sda845:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sda845_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sda845_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm429:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdm429:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdm429w:-:::~::~:

cpe:2.3:h:qualcomm:sdm429w:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdm429w_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm429w_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm429_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm429_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm439:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdm439:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdm439_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm439_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm450:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdm450:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdm450_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm450_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm630:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm630:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm630_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm630_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm632:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm632:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdm632_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm632_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm636:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm636:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm636_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm636_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm660:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm660:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm660_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm660_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm670:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm670:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm670_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm670_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm710:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm710:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdm710_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:sdm710_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm845:-:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:sdm845:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm845_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm845_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:h:qualcomm:sdm850:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm850:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm850_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm850_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdx20:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdx20:-:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sdx20_firmware:-:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sdx20_firmware:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdx24:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdx24:-:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sdx24_firmware:-:*:*:*:*:*

cpe:2.3:o:qualcomm:sdx24_firmware:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdx55:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdx55:-:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sdx55_firmware:-:*:*:*:*:*:

cpe:2.3:o:qualcomm:sdx55_firmware:-:~::~:
cpe:2.3:h:qualcomm:sm6150:-:~::~:
cpe:2.3:h:qualcomm:sm6150:-:~::~:
cpe:2.3:o:qualcomm:sm6150_firmware:-:~::~:
cpe:2.3:o:qualcomm:sm6150_firmware:-:~::~:
cpe:2.3:h:qualcomm:sm7150:-:~::~:
cpe:2.3:h:qualcomm:sm7150:-:~::~:
cpe:2.3:o:qualcomm:sm7150_firmware:-:~::~:
cpe:2.3:o:qualcomm:sm7150_firmware:-:~::~:
cpe:2.3:h:qualcomm:sm8150:-:~::~:
cpe:2.3:h:qualcomm:sm8150:-:~::~:
cpe:2.3:o:qualcomm:sm8150_firmware:-:~::~:
cpe:2.3:o:qualcomm:sm8150_firmware:-:~::~:
cpe:2.3:h:qualcomm:sxr1130:-:~::~:
cpe:2.3:h:qualcomm:sxr1130:-:~::~:
cpe:2.3:o:qualcomm:sxr1130_firmware:-:~::~:
cpe:2.3:o:qualcomm:sxr1130_firmware:-:~::~:

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)

© CVE.report 2023  |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](#)