



# CVE-2019-11983

[MITRE](#)[NVD](#)[CVE.ORG](#)[Print: PDF !\[\]\(e3f8612927870f2e0f9f5989e6dd3064\_img.jpg\)](#)

## Summary

|                        |   |
|------------------------|---|
| <b>CVE</b>             | CVE-2019-11983  |
| <b>State</b>           | PUBLIC  |
| <b>Assigner</b>        | security-alert@hpe.com  |
| <b>Source Priority</b> | CVE Program / NVD first with legacy fallback  |
| <b>Published</b>       | 2019-06-05 17:29:00 UTC   |
| <b>Updated</b>         | 2019-06-07 18:53:00 UTC   |
| <b>Description</b>     | A remote buffer overflow vulnerability was identified in HPE Integrated Lights-Out 4 (iLO 4) earlier than v2.61b for Gen9 ser |

## Risk And Classification

**Problem Types:** CWE-119

## NVD Known Affected Configurations (CPE 2.3)

| Type             | Vendor             | Product  | Version | Update | Edition | Language |
|------------------|--------------------|--|---------|--------|---------|----------|
| Operating System | <a href="#">Hp</a> | <a href="#">Integrated Lights-out 4 Firmware</a> | All     | All    | All     | All      |
| Operating System | <a href="#">Hp</a> | <a href="#">Integrated Lights-out 5 Firmware</a> | All     | All    | All     | All      |
| Hardware         | <a href="#">Hp</a> | <a href="#">Proliant BI460c Gen10</a>            | -       | All    | All     | All      |
| Hardware         | <a href="#">Hp</a> | <a href="#">Proliant BI460c Gen10</a>            | -       | All    | All     | All      |
| Hardware         | <a href="#">Hp</a> | <a href="#">Proliant BI460c Gen9</a>             | -       | All    | All     | All      |
| Hardware         | <a href="#">Hp</a> | <a href="#">Proliant BI460c Gen9</a>             | -       | All    | All     | All      |
| Hardware         | <a href="#">Hp</a> | <a href="#">Proliant DI120 Gen10</a>             | -       | All    | All     | All      |
| Hardware         | <a href="#">Hp</a> | <a href="#">Proliant DI120 Gen10</a>             | -       | All    | All     | All      |
| Hardware         | <a href="#">Hp</a> | <a href="#">Proliant DI120 Gen9</a>              | -       | All    | All     | All      |
| Hardware         | <a href="#">Hp</a> | <a href="#">Proliant DI120 Gen9</a>              | -       | All    | All     | All      |
| Hardware         | <a href="#">Hp</a> | <a href="#">Proliant DI160 Gen10</a>             | -       | All    | All     | All      |
| Hardware         | <a href="#">Hp</a> | <a href="#">Proliant DI160 Gen10</a>             | -       | All    | All     | All      |
| Hardware         | <a href="#">Hp</a> | <a href="#">Proliant DI180 Gen10</a>             | -       | All    | All     | All      |
| Hardware         | <a href="#">Hp</a> | <a href="#">Proliant DI180 Gen10</a>             | -       | All    | All     | All      |
| Hardware         | <a href="#">Hp</a> | <a href="#">Proliant DI180 Gen9</a>              | -       | All    | All     | All      |
| Hardware         | <a href="#">Hp</a> | <a href="#">Proliant DI180 Gen9</a>              | -       | All    | All     | All      |
| Hardware         | <a href="#">Hp</a> | <a href="#">Proliant DI20 Gen10</a>              | -       | All    | All     | All      |

|          |    |                            |   |     |     |     |
|----------|----|----------------------------|---|-----|-----|-----|
| Hardware | Hp | Proliant DI20 Gen10        | - | All | All | All |
| Hardware | Hp | Proliant DI325 Gen10       | - | All | All | All |
| Hardware | Hp | Proliant DI325 Gen10       | - | All | All | All |
| Hardware | Hp | Proliant DI360 Gen10       | - | All | All | All |
| Hardware | Hp | Proliant DI360 Gen10       | - | All | All | All |
| Hardware | Hp | Proliant DI360 Gen9        | - | All | All | All |
| Hardware | Hp | Proliant DI360 Gen9        | - | All | All | All |
| Hardware | Hp | Proliant DI380 Gen10       | - | All | All | All |
| Hardware | Hp | Proliant DI380 Gen10       | - | All | All | All |
| Hardware | Hp | Proliant DI380 Gen9        | - | All | All | All |
| Hardware | Hp | Proliant DI380 Gen9        | - | All | All | All |
| Hardware | Hp | Proliant DI385 Gen10       | - | All | All | All |
| Hardware | Hp | Proliant DI385 Gen10       | - | All | All | All |
| Hardware | Hp | Proliant DI560 Gen10       | - | All | All | All |
| Hardware | Hp | Proliant DI560 Gen10       | - | All | All | All |
| Hardware | Hp | Proliant DI580 Gen10       | - | All | All | All |
| Hardware | Hp | Proliant DI580 Gen10       | - | All | All | All |
| Hardware | Hp | Proliant DI580 Gen9        | - | All | All | All |
| Hardware | Hp | Proliant DI580 Gen9        | - | All | All | All |
| Hardware | Hp | Proliant Microserver Gen10 | - | All | All | All |
| Hardware | Hp | Proliant Microserver Gen10 | - | All | All | All |
| Hardware | Hp | Proliant MI10 Gen9         | 2 | All | All | All |
| Hardware | Hp | Proliant MI10 Gen9         | 2 | All | All | All |
| Hardware | Hp | Proliant MI110 Gen10       | - | All | All | All |
| Hardware | Hp | Proliant MI110 Gen10       | - | All | All | All |
| Hardware | Hp | Proliant MI110 Gen9        | - | All | All | All |
| Hardware | Hp | Proliant MI110 Gen9        | - | All | All | All |
| Hardware | Hp | Proliant MI150 Gen9        | - | All | All | All |
| Hardware | Hp | Proliant MI150 Gen9        | - | All | All | All |
| Hardware | Hp | Proliant MI30 Gen9         | 2 | All | All | All |
| Hardware | Hp | Proliant MI30 Gen9         | 2 | All | All | All |
| Hardware | Hp | Proliant MI350 Gen10       | - | All | All | All |
| Hardware | Hp | Proliant MI350 Gen10       | - | All | All | All |
| Hardware | Hp | Proliant MI350 Gen9        | - | All | All | All |
| Hardware | Hp | Proliant MI350 Gen9        | - | All | All | All |

|          |    |                       |     |     |     |     |
|----------|----|-----------------------|-----|-----|-----|-----|
| Hardware | Hp | Proliant Ws460c Gen9  | -   | All | All | All |
| Hardware | Hp | Proliant Ws460c Gen9  | -   | All | All | All |
| Hardware | Hp | Proliant XI170r Gen10 | -   | All | All | All |
| Hardware | Hp | Proliant XI170r Gen10 | -   | All | All | All |
| Hardware | Hp | Proliant XI170r Gen9  | -   | All | All | All |
| Hardware | Hp | Proliant XI170r Gen9  | -   | All | All | All |
| Hardware | Hp | Proliant XI190r Gen10 | -   | All | All | All |
| Hardware | Hp | Proliant XI190r Gen10 | -   | All | All | All |
| Hardware | Hp | Proliant XI190r Gen9  | -   | All | All | All |
| Hardware | Hp | Proliant XI190r Gen9  | -   | All | All | All |
| Hardware | Hp | Proliant XI230a Gen9  | -   | All | All | All |
| Hardware | Hp | Proliant XI230a Gen9  | -   | All | All | All |
| Hardware | Hp | Proliant XI230k Gen10 | -   | All | All | All |
| Hardware | Hp | Proliant XI230k Gen10 | -   | All | All | All |
| Hardware | Hp | Proliant XI250a Gen9  | -   | All | All | All |
| Hardware | Hp | Proliant XI250a Gen9  | -   | All | All | All |
| Hardware | Hp | Proliant XI450 Gen10  | -   | All | All | All |
| Hardware | Hp | Proliant XI450 Gen10  | -   | All | All | All |
| Hardware | Hp | Proliant XI730f Gen9  | All | All | All | All |
| Hardware | Hp | Proliant XI730f Gen9  | All | All | All | All |
| Hardware | Hp | Proliant XI740f Gen9  | -   | All | All | All |
| Hardware | Hp | Proliant XI740f Gen9  | -   | All | All | All |
| Hardware | Hp | Proliant XI750f Gen9  | -   | All | All | All |
| Hardware | Hp | Proliant XI750f Gen9  | -   | All | All | All |

## References

| Reference                             | Source  | Link  | Tags                |
|---------------------------------------|---------|---|---------------------|
| Document Display   HPE Support Center | CONFIRM | <a href="https://support.hpe.com">support.hpe.com</a> | Vendor Advisory     |
| CVE Program record                    | CVE.ORG | <a href="https://www.cve.org">www.cve.org</a>         | canonical           |
| NVD vulnerability detail              | NVD     | <a href="https://nvd.nist.gov">nvd.nist.gov</a>       | canonical, analysis |

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

**CVE.report and Source URL Uptime Status [status.cve.report](#)**