



CVE-2019-14031

Published on: 03/05/2020 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:27:57 PM UTC


CVE-2019-14031

Source: Mitre

Source: NIST

CVE.ORG

Print: PDF



Certain versions of [Apq8009](#) from [Qualcomm](#) contain the following vulnerability:

Buffer overflow can occur while parsing RSN IE containing list of PMK ID's which are more than the buffer size in Snapdragon Auto, Snapdragon Compute, Snapdragon Connectivity, Snapdragon Consumer Electronics Connectivity, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon IoT, Snapdragon Mobile,

Snapdragon Voice & Music, Snapdragon Wired Infrastructure and Networking in APQ8009, APQ8017, APQ8053, APQ8064, APQ8096, APQ8096AU, APQ8098, IPQ6018, IPQ8074, MDM9206, MDM9207C, MDM9607, MDM9640, MDM9650, MSM8996, MSM8996AU, MSM8998, Nicobar, QCA4531, QCA6174A, QCA6564, QCA6574, QCA6574AU, QCA6584, QCA6584AU, QCA8081, QCA9377, QCA9379, QCA9886, QCN7605, QCS405, QCS605, SA6155P, SC8180X, SDA660, SDA845, SDM630, SDM636, SDM660, SDM670, SDM710, SDM845, SDM850, SDX20, SDX24, SM6150, SM7150, SM8150, SM8250, SXR1130, SXR2130

CVE-2019-14031 has been assigned by [Q](#) product-security@qualcomm.com to track the vulnerability - currently rated as **CRITICAL** severity.

Affected Vendor/Software: [Q](#) Qualcomm, Inc. - Snapdragon Auto, Snapdragon Compute, Snapdragon Connectivity, Snapdragon Consumer Electronics Connectivity, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon IoT, Snapdragon Mobile, Snapdragon Voice & Music, Snapdragon Wired Infrastructure and Networking version APQ8009, APQ8017, APQ8053, APQ8064, APQ8096, APQ8096AU, APQ8098, IPQ6018, IPQ8074, MDM9206, MDM9207C, MDM9607, MDM9640, MDM9650, MSM8996, MSM8996AU, MSM8998, Nicobar, QCA4531, QCA6174A, QCA6564, QCA6574, QCA6574AU, QCA6584, QCA6584AU, QCA8081, QCA9377, QCA9379, QCA9886, QCN7605, QCS405, QCS605, SA6155P, SC8180X, SDA660, SDA845, SDM630, SDM636, SDM660, SDM670, SDM710, SDM845, SDM850, SDX20, SDX24, SM6150, SM7150, SM8150, SM8250, SXR1130, SXR2130

CVSS3 Score: **9.8 - CRITICAL**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact

UNCHANGED

HIGH

HIGH

HIGH

CVSS2 Score: 10 - HIGH

Access Vector	Access Complexity	Authentication
NETWORK	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
COMPLETE	COMPLETE	COMPLETE

CVE References

Description	Tags	Link
March 2020 Security Bulletin Qualcomm	Vendor Advisory www.qualcomm.com text/html	Q CONFIRM www.qualcomm.com/company/product-security/bulletins/march-2020-bulletin

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware  	Qualcomm	Apq8009	-	All	All	All
Hardware  	Qualcomm	Apq8009	-	All	All	All
Operating System	Qualcomm	Apq8009 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8009 Firmware	-	All	All	All
Hardware  	Qualcomm	Apq8017	-	All	All	All
Hardware  	Qualcomm	Apq8017	-	All	All	All
Operating System	Qualcomm	Apq8017 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8017 Firmware	-	All	All	All
Hardware  	Qualcomm	Apq8053	-	All	All	All
Hardware  	Qualcomm	Apq8053	-	All	All	All
Operating System	Qualcomm	Apq8053 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8053 Firmware	-	All	All	All

Hardware  	Qualcomm	Apq8064	-	All	All	All
Hardware  	Qualcomm	Apq8064	-	All	All	All
Operating System	Qualcomm	Apq8064 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8064 Firmware	-	All	All	All
Hardware  	Qualcomm	Apq8096	-	All	All	All
Hardware  	Qualcomm	Apq8096	-	All	All	All
Hardware  	Qualcomm	Apq8096au	-	All	All	All
Hardware  	Qualcomm	Apq8096au	-	All	All	All
Operating System	Qualcomm	Apq8096au Firmware	-	All	All	All
Operating System	Qualcomm	Apq8096au Firmware	-	All	All	All
Operating System	Qualcomm	Apq8096 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8096 Firmware	-	All	All	All
Hardware  	Qualcomm	Apq8098	-	All	All	All
Hardware  	Qualcomm	Apq8098	-	All	All	All
Operating System	Qualcomm	Apq8098 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8098 Firmware	-	All	All	All
Hardware  	Qualcomm	Ipq6018	-	All	All	All
Hardware  	Qualcomm	Ipq6018	-	All	All	All
Operating System	Qualcomm	Ipq6018 Firmware	-	All	All	All
Operating System	Qualcomm	Ipq6018 Firmware	-	All	All	All
Hardware  	Qualcomm	Ipq8074	-	All	All	All
Hardware  	Qualcomm	Ipq8074	-	All	All	All
Operating System	Qualcomm	Ipq8074 Firmware	-	All	All	All
Operating System	Qualcomm	Ipq8074 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9206	-	All	All	All
Hardware  	Qualcomm	Mdm9206	-	All	All	All
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All

System						
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9207c	-	All	All	All
Hardware  	Qualcomm	Mdm9207c	-	All	All	All
Operating System	Qualcomm	Mdm9207c Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9207c Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9607	-	All	All	All
Hardware  	Qualcomm	Mdm9607	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9640	-	All	All	All
Hardware  	Qualcomm	Mdm9640	-	All	All	All
Operating System	Qualcomm	Mdm9640 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9640 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9650	-	All	All	All
Hardware  	Qualcomm	Mdm9650	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8996	-	All	All	All
Hardware  	Qualcomm	Msm8996	-	All	All	All
Hardware  	Qualcomm	Msm8996au	-	All	All	All
Hardware  	Qualcomm	Msm8996au	-	All	All	All
Operating System	Qualcomm	Msm8996au Firmware	-	All	All	All
Operating System	Qualcomm	Msm8996au Firmware	-	All	All	All
Operating System	Qualcomm	Msm8996 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8996 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8998	-	All	All	All

Hardware  	Qualcomm	Msm8998	-	All	All	All
Operating System	Qualcomm	Msm8998 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8998 Firmware	-	All	All	All
Hardware  	Qualcomm	Nicobar	-	All	All	All
Hardware  	Qualcomm	Nicobar	-	All	All	All
Operating System	Qualcomm	Nicobar Firmware	-	All	All	All
Operating System	Qualcomm	Nicobar Firmware	-	All	All	All
Hardware  	Qualcomm	Qca4531	-	All	All	All
Hardware  	Qualcomm	Qca4531	-	All	All	All
Operating System	Qualcomm	Qca4531 Firmware	-	All	All	All
Operating System	Qualcomm	Qca4531 Firmware	-	All	All	All
Hardware  	Qualcomm	Qca6174a	-	All	All	All
Hardware  	Qualcomm	Qca6174a	-	All	All	All
Operating System	Qualcomm	Qca6174a Firmware	-	All	All	All
Operating System	Qualcomm	Qca6174a Firmware	-	All	All	All
Hardware  	Qualcomm	Qca6564	-	All	All	All
Hardware  	Qualcomm	Qca6564	-	All	All	All
Operating System	Qualcomm	Qca6564 Firmware	-	All	All	All
Operating System	Qualcomm	Qca6564 Firmware	-	All	All	All
Hardware  	Qualcomm	Qca6574	-	All	All	All
Hardware  	Qualcomm	Qca6574	-	All	All	All
Hardware  	Qualcomm	Qca6574au	-	All	All	All
Hardware  	Qualcomm	Qca6574au	-	All	All	All
Operating System	Qualcomm	Qca6574au Firmware	-	All	All	All
Operating System	Qualcomm	Qca6574au Firmware	-	All	All	All
Operating System	Qualcomm	Qca6574 Firmware	-	All	All	All
Operating System	Qualcomm	Qca6574 Firmware	-	All	All	All

Operating System	Qualcomm	Qualcomm Firmware		All	All	All
Hardware  	Qualcomm	Qca6584	-	All	All	All
Hardware  	Qualcomm	Qca6584	-	All	All	All
Hardware  	Qualcomm	Qca6584au	-	All	All	All
Hardware  	Qualcomm	Qca6584au	-	All	All	All
Operating System	Qualcomm	Qca6584au Firmware	-	All	All	All
Operating System	Qualcomm	Qca6584au Firmware	-	All	All	All
Operating System	Qualcomm	Qca6584 Firmware	-	All	All	All
Operating System	Qualcomm	Qca6584 Firmware	-	All	All	All
Hardware  	Qualcomm	Qca8081	-	All	All	All
Hardware  	Qualcomm	Qca8081	-	All	All	All
Operating System	Qualcomm	Qca8081 Firmware	-	All	All	All
Operating System	Qualcomm	Qca8081 Firmware	-	All	All	All
Hardware  	Qualcomm	Qca9377	-	All	All	All
Hardware  	Qualcomm	Qca9377	-	All	All	All
Operating System	Qualcomm	Qca9377 Firmware	-	All	All	All
Operating System	Qualcomm	Qca9377 Firmware	-	All	All	All
Hardware  	Qualcomm	Qca9379	-	All	All	All
Hardware  	Qualcomm	Qca9379	-	All	All	All
Operating System	Qualcomm	Qca9379 Firmware	-	All	All	All
Operating System	Qualcomm	Qca9379 Firmware	-	All	All	All
Hardware  	Qualcomm	Qca9886	-	All	All	All
Hardware  	Qualcomm	Qca9886	-	All	All	All
Operating System	Qualcomm	Qca9886 Firmware	-	All	All	All
Operating System	Qualcomm	Qca9886 Firmware	-	All	All	All
Hardware  	Qualcomm	Qcn7605	-	All	All	All
Hardware  	Qualcomm	Qcn7605	-	All	All	All

Operating System	Qualcomm	Qcn7605 Firmware	-	All	All	All
Operating System	Qualcomm	Qcn7605 Firmware	-	All	All	All
Hardware  	Qualcomm	Qcs405	-	All	All	All
Hardware  	Qualcomm	Qcs405	-	All	All	All
Operating System	Qualcomm	Qcs405 Firmware	-	All	All	All
Operating System	Qualcomm	Qcs405 Firmware	-	All	All	All
Hardware  	Qualcomm	Qcs605	-	All	All	All
Hardware  	Qualcomm	Qcs605	-	All	All	All
Operating System	Qualcomm	Qcs605 Firmware	-	All	All	All
Operating System	Qualcomm	Qcs605 Firmware	-	All	All	All
Hardware  	Qualcomm	Sa6155p	-	All	All	All
Hardware  	Qualcomm	Sa6155p	-	All	All	All
Operating System	Qualcomm	Sa6155p Firmware	-	All	All	All
Operating System	Qualcomm	Sa6155p Firmware	-	All	All	All
Hardware  	Qualcomm	Sc8180x	-	All	All	All
Hardware  	Qualcomm	Sc8180x	-	All	All	All
Operating System	Qualcomm	Sc8180x Firmware	-	All	All	All
Operating System	Qualcomm	Sc8180x Firmware	-	All	All	All
Hardware  	Qualcomm	Sda660	-	All	All	All
Hardware  	Qualcomm	Sda660	-	All	All	All
Operating System	Qualcomm	Sda660 Firmware	-	All	All	All
Operating System	Qualcomm	Sda660 Firmware	-	All	All	All
Hardware  	Qualcomm	Sda845	-	All	All	All
Hardware  	Qualcomm	Sda845	-	All	All	All
Operating System	Qualcomm	Sda845 Firmware	-	All	All	All
Operating System	Qualcomm	Sda845 Firmware	-	All	All	All

Hardware  	Qualcomm	Sdm630	-	All	All	All
Hardware  	Qualcomm	Sdm630	-	All	All	All
Operating System	Qualcomm	Sdm630 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm630 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm636	-	All	All	All
Hardware  	Qualcomm	Sdm636	-	All	All	All
Operating System	Qualcomm	Sdm636 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm636 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm660	-	All	All	All
Hardware  	Qualcomm	Sdm660	-	All	All	All
Operating System	Qualcomm	Sdm660 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm660 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm670	-	All	All	All
Hardware  	Qualcomm	Sdm670	-	All	All	All
Operating System	Qualcomm	Sdm670 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm670 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm710	-	All	All	All
Hardware  	Qualcomm	Sdm710	-	All	All	All
Operating System	Qualcomm	Sdm710 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm710 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm845	-	All	All	All
Hardware  	Qualcomm	Sdm845	-	All	All	All
Operating System	Qualcomm	Sdm845 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm845 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm850	-	All	All	All
Hardware  	Qualcomm	Sdm850	-	All	All	All
Operating System	Qualcomm	Sdm850 Firmware	-	All	All	All

System						
Operating System	Qualcomm	Sdm850 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdx20	-	All	All	All
Hardware  	Qualcomm	Sdx20	-	All	All	All
Operating System	Qualcomm	Sdx20 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx20 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdx24	-	All	All	All
Hardware  	Qualcomm	Sdx24	-	All	All	All
Operating System	Qualcomm	Sdx24 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx24 Firmware	-	All	All	All
Hardware  	Qualcomm	Sm6150	-	All	All	All
Hardware  	Qualcomm	Sm6150	-	All	All	All
Operating System	Qualcomm	Sm6150 Firmware	-	All	All	All
Operating System	Qualcomm	Sm6150 Firmware	-	All	All	All
Hardware  	Qualcomm	Sm7150	-	All	All	All
Hardware  	Qualcomm	Sm7150	-	All	All	All
Operating System	Qualcomm	Sm7150 Firmware	-	All	All	All
Operating System	Qualcomm	Sm7150 Firmware	-	All	All	All
Hardware  	Qualcomm	Sm8150	-	All	All	All
Hardware  	Qualcomm	Sm8150	-	All	All	All
Operating System	Qualcomm	Sm8150 Firmware	-	All	All	All
Operating System	Qualcomm	Sm8150 Firmware	-	All	All	All
Hardware  	Qualcomm	Sm8250	-	All	All	All
Hardware  	Qualcomm	Sm8250	-	All	All	All
Operating System	Qualcomm	Sm8250 Firmware	-	All	All	All
Operating System	Qualcomm	Sm8250 Firmware	-	All	All	All
Hardware  	Qualcomm	Sxr1130	-	All	All	All

Hardware		Sxr1130	-	All	All	All
Operating System	Qualcomm	Sxr1130 Firmware	-	All	All	All
Operating System	Qualcomm	Sxr1130 Firmware	-	All	All	All
Hardware		Sxr2130	-	All	All	All
Hardware		Sxr2130	-	All	All	All
Operating System	Qualcomm	Sxr2130 Firmware	-	All	All	All
Operating System	Qualcomm	Sxr2130 Firmware	-	All	All	All
cpe:2.3:h:qualcomm:apq8009:-:~::~:						
cpe:2.3:h:qualcomm:apq8009:-:~::~:						
cpe:2.3:o:qualcomm:apq8009_firmware:-:~::~:						
cpe:2.3:o:qualcomm:apq8009_firmware:-:~::~:						
cpe:2.3:h:qualcomm:apq8017:-:~::~:						
cpe:2.3:h:qualcomm:apq8017:-:~::~:						
cpe:2.3:o:qualcomm:apq8017_firmware:-:~::~:						
cpe:2.3:o:qualcomm:apq8017_firmware:-:~::~:						
cpe:2.3:h:qualcomm:apq8053:-:~::~:						
cpe:2.3:h:qualcomm:apq8053:-:~::~:						
cpe:2.3:o:qualcomm:apq8053_firmware:-:~::~:						
cpe:2.3:o:qualcomm:apq8053_firmware:-:~::~:						
cpe:2.3:h:qualcomm:apq8064:-:~::~:						
cpe:2.3:h:qualcomm:apq8064:-:~::~:						
cpe:2.3:o:qualcomm:apq8064_firmware:-:~::~:						
cpe:2.3:o:qualcomm:apq8064_firmware:-:~::~:						
cpe:2.3:h:qualcomm:apq8096:-:~::~:						
cpe:2.3:h:qualcomm:apq8096:-:~::~:						
cpe:2.3:h:qualcomm:apq8096au:-:~::~:						
cpe:2.3:h:qualcomm:apq8096au:-:~::~:						
cpe:2.3:o:qualcomm:apq8096au_firmware:-:~::~:						

```
cpe:2.3:o:qualcomm:apq8096au_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:apq8096_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:apq8096_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:apq8098:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:apq8098:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:apq8098_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:apq8098_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:ipq6018:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:ipq6018:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:ipq6018_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:ipq6018_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:ipq8074:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:ipq8074:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:ipq8074_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:ipq8074_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:mdm9206:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9206:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:qualcomm:mdm9207c:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9207c:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9207c_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9207c_firmware:-:*:*:*:*:*
```

cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:mdm9640:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9640:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9640_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:mdm9640_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:mdm9650:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9650:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8996:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:msm8996:-:*:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:msm8996au:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8996au:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:msm8996au_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8996au_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8996_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8996_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8998:-:*:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:msm8998:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8998_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8998_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:nicobar:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:nicobar:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:nicobar_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:nicobar_firmware:-:*:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:qca4531:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qca4531:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qca4531_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qca4531_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:gca6174a:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:qca6174a:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qca6174a_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:qca6174a_firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:qualcomm:qca6564:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qca6564:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:gca6564_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:gca6564_firmware:-:*:*:*:*:*.*
```

cpe:2.3:h:qualcomm:gca6574:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:gca6574:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:qca6574au:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qca6574au:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qca6574au_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qca6574au_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:gca6574_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qca6574_firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:qualcomm:gca6584:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:gca6584:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qca6584au:-:*:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:qca6584au:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qca6584au_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qca6584au_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:gca6584_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:qca6584_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:gca8081:-:*~::~:

```
cpe:2.3:h:qualcomm:gca8081:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:gca8081_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:gca8081_firmware:-:~::~~::~~::~~::~~::~::
```

cpe:2.3:h:qualcomm:gca9377:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:gca9377:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:gca9377_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:gca9377_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:gca9379:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:gca9379:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:gca9379_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:gca9379_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:gca9886:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qca9886:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:gca9886 firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qca9886_firmware:-:*:*:*:*:*.*
```

cpe:2.3:h:qualcomm:qcn7605:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qcn7605:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qcn7605 firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qcn7605_firmware:-:*:*:*:*:*.*
```

cpe:2.3:h:qualcomm:gcs405:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:qcs405:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qcs405 firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:qcs405_firmware:-:*:*:*:*:*
```

cpe:2.3:h:qualcomm:qcs605:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qcs605:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qcs605_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qcs605_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sa6155p:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:sa6155p:-:~::~::~:

```
cpe:2.3:o:qualcomm:sa6155p_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sa6155p_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sc8180x:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sc8180x:-:*:*:*:*:*:*:

```
one:2.3.0:qualcomm:sc8180x_firmware-*.*.*.*.*.*.*.*
```

0p0.2.0.0.qn41001111.000100X_1111111110.

```
cpe:2.3:o:qualcomm:sc8180x firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sda660:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sda660:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sda660 firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:sda660 firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:h:qualcomm:sda845:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sda845:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sda845_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sda845 firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:h:qualcomm:sdm630:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm630:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm630 firmware:-.*:.*:.*:.*:.*:.*
```

```
cpe:2.3:o:qualcomm:sdm630_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm636:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm636:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdm636 firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm636_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm660:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm660:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm660_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:sdm660_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:h:qualcomm:sdm670:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm670:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdm670 firmware:-.*:.*:.*:.*:.*:.*:.*:.*
```

```
cpe:2.3:o:qualcomm:sdm670 firmware:-.*:.*:.*:.*:.*:.*:.*:.*
```

```
cpe:2.3:h:qualcomm:sdm710:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm710:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdm710_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm710_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm845:-:*:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:sdm845:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm845_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm845_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm850:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm850:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm850_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm850_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdx20:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdx20:-:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sdx20_firmware:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdx20_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdx24:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdx24:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdx24_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdx24_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sm6150:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sm6150:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sm6150_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sm6150_firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:qualcomm:sm7150:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sm7150:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sm7150_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sm7150_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sm8150:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sm8150:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sm8150_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:o:qualcomm:sm8150_firmware:-:~::~::~:
cpe:2.3:h:qualcomm:sm8250:-:~::~::~:
cpe:2.3:h:qualcomm:sm8250:-:~::~::~:
cpe:2.3:o:qualcomm:sm8250_firmware:-:~::~::~:
cpe:2.3:o:qualcomm:sm8250_firmware:-:~::~::~:
cpe:2.3:h:qualcomm:sxr1130:-:~::~::~:
cpe:2.3:h:qualcomm:sxr1130:-:~::~::~:
cpe:2.3:o:qualcomm:sxr1130_firmware:-:~::~::~:
cpe:2.3:o:qualcomm:sxr1130_firmware:-:~::~::~:
cpe:2.3:h:qualcomm:sxr2130:-:~::~::~:
cpe:2.3:h:qualcomm:sxr2130:-:~::~::~:
cpe:2.3:o:qualcomm:sxr2130_firmware:-:~::~::~:
cpe:2.3:o:qualcomm:sxr2130_firmware:-:~::~::~:

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID→](#)