



CVE-2019-14076

Published on: 06/22/2020 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:27:58 PM UTC

CVE-2019-14076

Source: Mitre

Source: NIST

CVE.ORG

Print: PDF



Certain versions of [Apq8009](#) from [Qualcomm](#) contain the following vulnerability:

Buffer overflow occurs while processing an subsample data length out of range due to lack of user input validation in Snapdragon Auto, Snapdragon Compute, Snapdragon Connectivity, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon Mobile, Snapdragon Voice & Music, Snapdragon Wired Infrastructure and

Networking in APQ8009, APQ8098, Kamorta, MDM9150, MDM9205, MDM9206, MDM9607, MDM9650, MSM8905, MSM8909, MSM8998, Nicobar, QCS404, QCS405, QCS605, Rennell, SA415M, SC7180, SC8180X, SDA845, SDM670, SDM710, SDM845, SDM850, SDX24, SDX55, SM6150, SM7150, SM8150, SM8250, SXR1130, SXR2130

CVE-2019-14076 has been assigned by [Q](#) product-security@qualcomm.com to track the vulnerability - currently rated as **HIGH** severity.

Affected Vendor/Software: [Q](#) Qualcomm, Inc. - Snapdragon Auto, Snapdragon Compute, Snapdragon Connectivity, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon Mobile, Snapdragon Voice & Music, Snapdragon Wired Infrastructure and Networking version APQ8009, APQ8098, Kamorta, MDM9150, MDM9205, MDM9206, MDM9607, MDM9650, MSM8905, MSM8909, MSM8998, Nicobar, QCS404, QCS405, QCS605, Rennell, SA415M, SC7180, SC8180X, SDA845, SDM670, SDM710, SDM845, SDM850, SDX24, SDX55, SM6150, SM7150, SM8150, SM8250, SXR1130, SXR2130

CVSS3 Score: **7.8 - HIGH**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
LOCAL	LOW	LOW	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: **4.6 - MEDIUM**

Access Vector	Access Complexity	Authentication
LOCAL	LOW	NONE

Confidentiality Impact	Integrity Impact	Availability Impact
PARTIAL	PARTIAL	PARTIAL

CVE References

Description	Tags	Link
June 2020 Security Bulletin Qualcomm	Vendor Advisory www.qualcomm.com text/html	Q MISC www.qualcomm.com/company/product-security/bulletins/june-2020-security-bulletin
Page not found	Broken Link www.qualcomm.com text/html Inactive Link Not Archived	Q CONFIRM www.qualcomm.com/company/product-security/bulletins/june-2020-bulletin

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Qualcomm	Apq8009	-	All	All	All
Hardware 	Qualcomm	Apq8009	-	All	All	All
Operating System	Qualcomm	Apq8009 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8009 Firmware	-	All	All	All
Hardware 	Qualcomm	Apq8098	-	All	All	All
Hardware 	Qualcomm	Apq8098	-	All	All	All
Operating System	Qualcomm	Apq8098 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8098 Firmware	-	All	All	All
Hardware 	Qualcomm	Kamorta	-	All	All	All
Hardware 	Qualcomm	Kamorta	-	All	All	All
Operating System	Qualcomm	Kamorta Firmware	-	All	All	All
Operating System	Qualcomm	Kamorta Firmware	-	All	All	All
Hardware 	Qualcomm	Mdm9150	-	All	All	All
Hardware 	Qualcomm	Mdm9150	-	All	All	All

Hardware  	Qualcomm	Mdm9150	-	All	All	All
Operating System	Qualcomm	Mdm9150 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9150 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9205	-	All	All	All
Hardware  	Qualcomm	Mdm9205	-	All	All	All
Operating System	Qualcomm	Mdm9205 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9205 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9206	-	All	All	All
Hardware  	Qualcomm	Mdm9206	-	All	All	All
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9607	-	All	All	All
Hardware  	Qualcomm	Mdm9607	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9650	-	All	All	All
Hardware  	Qualcomm	Mdm9650	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8905	-	All	All	All
Hardware  	Qualcomm	Msm8905	-	All	All	All
Operating System	Qualcomm	Msm8905 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8905 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8909	-	All	All	All
Hardware  	Qualcomm	Msm8909	-	All	All	All
Operating System	Qualcomm	Msm8909 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8909 Firmware	-	All	All	All

System						
Hardware  	Qualcomm	Msm8998	-	All	All	All
Hardware  	Qualcomm	Msm8998	-	All	All	All
Operating System	Qualcomm	Msm8998 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8998 Firmware	-	All	All	All
Hardware  	Qualcomm	Nicobar	-	All	All	All
Hardware  	Qualcomm	Nicobar	-	All	All	All
Operating System	Qualcomm	Nicobar Firmware	-	All	All	All
Operating System	Qualcomm	Nicobar Firmware	-	All	All	All
Hardware  	Qualcomm	Qcs404	-	All	All	All
Hardware  	Qualcomm	Qcs404	-	All	All	All
Operating System	Qualcomm	Qcs404 Firmware	-	All	All	All
Operating System	Qualcomm	Qcs404 Firmware	-	All	All	All
Hardware  	Qualcomm	Qcs405	-	All	All	All
Hardware  	Qualcomm	Qcs405	-	All	All	All
Operating System	Qualcomm	Qcs405 Firmware	-	All	All	All
Operating System	Qualcomm	Qcs405 Firmware	-	All	All	All
Hardware  	Qualcomm	Qcs605	-	All	All	All
Hardware  	Qualcomm	Qcs605	-	All	All	All
Operating System	Qualcomm	Qcs605 Firmware	-	All	All	All
Operating System	Qualcomm	Qcs605 Firmware	-	All	All	All
Hardware  	Qualcomm	Rennell	-	All	All	All
Hardware  	Qualcomm	Rennell	-	All	All	All
Operating System	Qualcomm	Rennell Firmware	-	All	All	All
Operating System	Qualcomm	Rennell Firmware	-	All	All	All
Hardware  	Qualcomm	Sa415m	-	All	All	All
Hardware  	Qualcomm	Sa415m	-	All	All	All
Operating System	Qualcomm	Sa415m Firmware	-	All	All	All

Operating System	Qualcomm	Custom Firmware	-	All	All	All
Operating System	Qualcomm	Sa415m Firmware	-	All	All	All
Hardware  	Qualcomm	Sc7180	-	All	All	All
Hardware  	Qualcomm	Sc7180	-	All	All	All
Operating System	Qualcomm	Sc7180 Firmware	-	All	All	All
Operating System	Qualcomm	Sc7180 Firmware	-	All	All	All
Hardware  	Qualcomm	Sc8180x	-	All	All	All
Hardware  	Qualcomm	Sc8180x	-	All	All	All
Operating System	Qualcomm	Sc8180x Firmware	-	All	All	All
Operating System	Qualcomm	Sc8180x Firmware	-	All	All	All
Hardware  	Qualcomm	Sda845	-	All	All	All
Hardware  	Qualcomm	Sda845	-	All	All	All
Operating System	Qualcomm	Sda845 Firmware	-	All	All	All
Operating System	Qualcomm	Sda845 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm670	-	All	All	All
Hardware  	Qualcomm	Sdm670	-	All	All	All
Operating System	Qualcomm	Sdm670 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm670 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm710	-	All	All	All
Hardware  	Qualcomm	Sdm710	-	All	All	All
Operating System	Qualcomm	Sdm710 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm710 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm845	-	All	All	All
Hardware  	Qualcomm	Sdm845	-	All	All	All
Operating System	Qualcomm	Sdm845 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm845 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm850	-	All	All	All

							
Hardware  	Qualcomm	Sdm850	-	All	All	All	
Operating System	Qualcomm	Sdm850 Firmware	-	All	All	All	
Operating System	Qualcomm	Sdm850 Firmware	-	All	All	All	
Hardware  	Qualcomm	Sdx24	-	All	All	All	
Hardware  	Qualcomm	Sdx24	-	All	All	All	
Operating System	Qualcomm	Sdx24 Firmware	-	All	All	All	
Operating System	Qualcomm	Sdx24 Firmware	-	All	All	All	
Hardware  	Qualcomm	Sdx55	-	All	All	All	
Hardware  	Qualcomm	Sdx55	-	All	All	All	
Operating System	Qualcomm	Sdx55 Firmware	-	All	All	All	
Operating System	Qualcomm	Sdx55 Firmware	-	All	All	All	
Hardware  	Qualcomm	Sm6150	-	All	All	All	
Hardware  	Qualcomm	Sm6150	-	All	All	All	
Operating System	Qualcomm	Sm6150 Firmware	-	All	All	All	
Operating System	Qualcomm	Sm6150 Firmware	-	All	All	All	
Hardware  	Qualcomm	Sm7150	-	All	All	All	
Hardware  	Qualcomm	Sm7150	-	All	All	All	
Operating System	Qualcomm	Sm7150 Firmware	-	All	All	All	
Operating System	Qualcomm	Sm7150 Firmware	-	All	All	All	
Hardware  	Qualcomm	Sm8150	-	All	All	All	
Hardware  	Qualcomm	Sm8150	-	All	All	All	
Operating System	Qualcomm	Sm8150 Firmware	-	All	All	All	
Operating System	Qualcomm	Sm8150 Firmware	-	All	All	All	
Hardware  	Qualcomm	Sm8250	-	All	All	All	
Hardware  	Qualcomm	Sm8250	-	All	All	All	
Operating System	Qualcomm	Sm8250 Firmware	-	All	All	All	

Operating System	Qualcomm	Sm8250 Firmware	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sxr1130	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sxr1130	-	All	All	All
Operating System	Qualcomm	Sxr1130 Firmware	-	All	All	All
Operating System	Qualcomm	Sxr1130 Firmware	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sxr2130	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sxr2130	-	All	All	All
Operating System	Qualcomm	Sxr2130 Firmware	-	All	All	All
Operating System	Qualcomm	Sxr2130 Firmware	-	All	All	All
cpe:2.3:h:qualcomm:apq8009:-:~::~:						
cpe:2.3:h:qualcomm:apq8009:-:~::~:						
cpe:2.3:o:qualcomm:apq8009_firmware:-:~::~:						
cpe:2.3:o:qualcomm:apq8009_firmware:-:~::~:						
cpe:2.3:h:qualcomm:apq8098:-:~::~:						
cpe:2.3:h:qualcomm:apq8098:-:~::~:						
cpe:2.3:o:qualcomm:apq8098_firmware:-:~::~:						
cpe:2.3:o:qualcomm:apq8098_firmware:-:~::~:						
cpe:2.3:h:qualcomm:kamorta:-:~::~:						
cpe:2.3:h:qualcomm:kamorta:-:~::~:						
cpe:2.3:o:qualcomm:kamorta_firmware:-:~::~:						
cpe:2.3:o:qualcomm:kamorta_firmware:-:~::~:						
cpe:2.3:h:qualcomm:mdm9150:-:~::~:						
cpe:2.3:h:qualcomm:mdm9150:-:~::~:						
cpe:2.3:o:qualcomm:mdm9150_firmware:-:~::~:						
cpe:2.3:o:qualcomm:mdm9150_firmware:-:~::~:						
cpe:2.3:h:qualcomm:mdm9205:-:~::~:						
cpe:2.3:h:qualcomm:mdm9205:-:~::~:						
cpe:2.3:o:qualcomm:mdm9205_firmware:-:~::~:						

```
cpe:2.3:o:qualcomm:mdm9205_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:mdm9206:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9206:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*:*:*
```

cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9650:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9650:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:msm8905:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8905:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:msm8905_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8905_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:msm8909:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8909:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:msm8909_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8909_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8998:-:*:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:msm8998:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8998_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8998_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:nicobar:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:nicobar:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:nicobar_firmware:-:*:*:*:*:*:*:
```



```
cpe:2.3:o:qualcomm:nicobar_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:qcs404:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:gcs404:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qcs404_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qcs404_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:qcs405:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qcs405:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qcs405 firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:qcs405 firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:qcs605:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qcs605:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qcs605_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qcs605_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:rennell:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:rennell:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:rennell_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:rennell_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sa415m:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sa415m:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sa415m_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sa415m_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sc7180:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:sc7180:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sc7180_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sc7180_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sc8180x:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sc8180x:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sc8180x_firmware:-:*:*:*:*:*:*
```

```
one23.qualcomm.com8180v firmware:*.*.*.*.*.*.*.*
```

```
cpw.z.o.o.qualcomm.secrootx_mimware.7. . . . .
```

```
cpe:2.3:h:qualcomm:sda845:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sda845:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sda845_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sda845_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm670:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm670:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm670_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm670_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm710:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm710:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm710_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm710_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm845:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm845:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm845_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm845_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm850:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm850:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm850_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm850_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdx24:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdx24:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdx24_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdx24_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdx55:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdx55:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdx55_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdx55_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sm6150:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sm6150:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sm6150_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sm6150_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sm7150:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:sm7150:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sm7150_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sm7150 firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sm8150:-:*~::~:

cpe:2.3:h:qualcomm:sm8150:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sm8150_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sm8150_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sm8250:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sm8250:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sm8250_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sm8250_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sxr1130:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sxr1130:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sxr1130_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sxr1130_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sxr2130:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sxr2130:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sxr2130_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sxr2130_firmware:-:*:*:*:*:*:
```

No vendor comments have been submitted for this CVE

[← Previous ID](#)

Next ID→

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](#)