




CVE-2019-14092

Published on: 06/22/2020 12:00:00 AM UTC

Last Modified on: 07/21/2021 11:39:00 AM UTC

CVE-2019-14092

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [Mdm9206](#) from [Qualcomm](#) contain the following vulnerability:

System Services exports services without permission protect and can lead to information exposure in Snapdragon Industrial IOT, Snapdragon Mobile in MDM9206, MDM9207C, MDM9607, Rennell, Saipan, SM8150, SM8250, SXR2130

CVE-2019-14092 has been assigned by [Q](#) product-security@qualcomm.com to track the vulnerability - currently rated as **MEDIUM** severity.

Affected Vendor/Software: [Q](#) **Qualcomm, Inc. - Snapdragon Industrial IOT, Snapdragon Mobile** version **MDM9206, MDM9207C, MDM9607, Rennell, Saipan, SM8150, SM8250, SXR2130**

CVSS3 Score: **5.5 - MEDIUM**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
LOCAL	LOW	LOW	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	NONE	NONE

CVSS2 Score: **2.1 - LOW**

Access Vector	Access Complexity	Authentication
LOCAL	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
PARTIAL	NONE	NONE

CVE References

Description	Tags	Link
June 2020 Security Bulletin I	Vendor Advisory	MISC www.qualcomm.com/company/product-security/bulletins/june-2020

June 2020 Security Bulletin |
Qualcomm

Vendor Advisory
[www.qualcomm.com
text/html](http://www.qualcomm.com/text/html)

Q www.qualcomm.com/company/product-security/bulletins/june-2020-security-bulletin

Page not found

Broken Link
[www.qualcomm.com
text/html](http://www.qualcomm.com/text/html)
Inactive Link Not Archived

Q CONFIRM www.qualcomm.com/company/product-security/bulletins/june-2020-bulletin

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Qualcomm	Mdm9206	-	All	All	All
Hardware 	Qualcomm	Mdm9206	-	All	All	All
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All
Hardware 	Qualcomm	Mdm9207c	-	All	All	All
Hardware 	Qualcomm	Mdm9207c	-	All	All	All
Operating System	Qualcomm	Mdm9207c Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9207c Firmware	-	All	All	All
Hardware 	Qualcomm	Mdm9607	-	All	All	All
Hardware 	Qualcomm	Mdm9607	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Hardware 	Qualcomm	Rennell	-	All	All	All
Hardware 	Qualcomm	Rennell	-	All	All	All
Operating System	Qualcomm	Rennell Firmware	-	All	All	All
Operating System	Qualcomm	Rennell Firmware	-	All	All	All
Hardware 	Qualcomm	Saipan	-	All	All	All
Hardware 	Qualcomm	Saipan	-	All	All	All

Operating System	Qualcomm	Saipan Firmware	-	All	All	All
Operating System	Qualcomm	Saipan Firmware	-	All	All	All
Hardware 🇵🇪🔗	Qualcomm	Sm8150	-	All	All	All
Hardware 🇵🇪🔗	Qualcomm	Sm8150	-	All	All	All
Operating System	Qualcomm	Sm8150 Firmware	-	All	All	All
Operating System	Qualcomm	Sm8150 Firmware	-	All	All	All
Hardware 🇵🇪🔗	Qualcomm	Sm8250	-	All	All	All
Hardware 🇵🇪🔗	Qualcomm	Sm8250	-	All	All	All
Operating System	Qualcomm	Sm8250 Firmware	-	All	All	All
Operating System	Qualcomm	Sm8250 Firmware	-	All	All	All
Hardware 🇵🇪🔗	Qualcomm	Sxr2130	-	All	All	All
Hardware 🇵🇪🔗	Qualcomm	Sxr2130	-	All	All	All
Operating System	Qualcomm	Sxr2130 Firmware	-	All	All	All
Operating System	Qualcomm	Sxr2130 Firmware	-	All	All	All
cpe:2.3:h:qualcomm:mdm9206:-:*:*:*:*:*:						
cpe:2.3:h:qualcomm:mdm9206:-:*:*:*:*:*:						
cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*:						
cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*:						
cpe:2.3:h:qualcomm:mdm9207c:-:*:*:*:*:*:						
cpe:2.3:h:qualcomm:mdm9207c:-:*:*:*:*:*:						
cpe:2.3:o:qualcomm:mdm9207c_firmware:-:*:*:*:*:*:						
cpe:2.3:o:qualcomm:mdm9207c_firmware:-:*:*:*:*::~:						
cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*:*:						
cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*:*:						
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*:*:						
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*::~:						
cpe:2.3:h:qualcomm:rennell:-:*:*:*:*:*:						

```
cpe:2.3:h:qualcomm:rennell:-:*.***.***.***.
cpe:2.3:o:qualcomm:rennell_firmware:-:*.***.***.***.
cpe:2.3:o:qualcomm:rennell_firmware:-:*.***.***.***.
cpe:2.3:h:qualcomm:saipan:-:*.***.***.***.
cpe:2.3:h:qualcomm:saipan:-:*.***.***.***.
cpe:2.3:o:qualcomm:saipan_firmware:-:*.***.***.***.
cpe:2.3:o:qualcomm:saipan_firmware:-:*.***.***.***.
cpe:2.3:h:qualcomm:sm8150:-:*.***.***.***.
cpe:2.3:h:qualcomm:sm8150:-:*.***.***.***.
cpe:2.3:o:qualcomm:sm8150_firmware:-:*.***.***.***.
cpe:2.3:o:qualcomm:sm8150_firmware:-:*.***.***.***.
cpe:2.3:h:qualcomm:sm8250:-:*.***.***.***.
cpe:2.3:h:qualcomm:sm8250:-:*.***.***.***.
cpe:2.3:o:qualcomm:sm8250_firmware:-:*.***.***.***.
cpe:2.3:o:qualcomm:sm8250_firmware:-:*.***.***.***.
cpe:2.3:h:qualcomm:sxr2130:-:*.***.***.***.
cpe:2.3:h:qualcomm:sxr2130:-:*.***.***.***.
cpe:2.3:o:qualcomm:sxr2130_firmware:-:*.***.***.***.
cpe:2.3:o:qualcomm:sxr2130_firmware:-:*.***.***.***.
```

No vendor comments have been submitted for this CVE

[← Previous ID](#)

Next ID→