



CVE-2019-2336

Published on: 11/21/2019 12:00:00 AM UTC

Last Modified on: 07/21/2021 11:39:00 AM UTC


CVE-2019-2336

[Source: Mitre](#)

[Source: NIST](#)

[CVE.ORG](#)

[Print: PDF](#)



Certain versions of [Mdm9205](#) from [Qualcomm](#) contain the following vulnerability:

Subsequent use of the CBO listener may result in further memory corruption due to use after free issue. in Snapdragon Auto, Snapdragon Compute, Snapdragon Connectivity, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon Mobile, Snapdragon Voice & Music, Snapdragon Wired Infrastructure and Networking in MDM9205, QCS404, SDX55, SM6150, SM7150, SM8150, SXR2130

CVE-2019-2336 has been assigned by [Q](#) product-security@qualcomm.com to track the vulnerability - currently rated as **MEDIUM** severity.

Affected Vendor/Software: [Q](#) **Qualcomm, Inc. - Snapdragon Auto, Snapdragon Compute, Snapdragon Connectivity, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon Mobile, Snapdragon Voice & Music, Snapdragon Wired Infrastructure and Networking** version **MDM9205, QCS404, SDX55, SM6150, SM7150, SM8150, SXR2130**

CVSS3 Score: **5.5 - MEDIUM**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
LOCAL	LOW	LOW	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	NONE	NONE	HIGH

CVSS2 Score: **4.9 - MEDIUM**

Access Vector	Access Complexity	Authentication
LOCAL	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
NONE	NONE	COMPLETE

CVE References

Description

Tags

Link

October Security Bulletin 2019 | Qualcomm

[Vendor Advisory](#)
[www.qualcomm.com](http://www.qualcomm.com/text/html)
[text/html](#)

[CONFIRM](#) www.qualcomm.com/company/product-security/bulletins/october-2019-bulletin

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Qualcomm	Mdm9205	-	All	All	All
Hardware 	Qualcomm	Mdm9205	-	All	All	All
Operating System	Qualcomm	Mdm9205 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9205 Firmware	-	All	All	All
Hardware 	Qualcomm	Qcs404	-	All	All	All
Hardware 	Qualcomm	Qcs404	-	All	All	All
Operating System	Qualcomm	Qcs404 Firmware	-	All	All	All
Operating System	Qualcomm	Qcs404 Firmware	-	All	All	All
Hardware 	Qualcomm	Sdx55	-	All	All	All
Hardware 	Qualcomm	Sdx55	-	All	All	All
Operating System	Qualcomm	Sdx55 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx55 Firmware	-	All	All	All
Hardware 	Qualcomm	Sm6150	-	All	All	All
Hardware 	Qualcomm	Sm6150	-	All	All	All
Operating System	Qualcomm	Sm6150 Firmware	-	All	All	All
Operating System	Qualcomm	Sm6150 Firmware	-	All	All	All
Hardware 	Qualcomm	Sm7150	-	All	All	All
Hardware 	Qualcomm	Sm7150	-	All	All	All

Operating System	Qualcomm	Sm7150 Firmware	-	All	All	All
Operating System	Qualcomm	Sm7150 Firmware	-	All	All	All
Hardware	Qualcomm	Sm8150	-	All	All	All
Hardware	Qualcomm	Sm8150	-	All	All	All
Operating System	Qualcomm	Sm8150 Firmware	-	All	All	All
Operating System	Qualcomm	Sm8150 Firmware	-	All	All	All
Hardware	Qualcomm	Sxr2130	-	All	All	All
Hardware	Qualcomm	Sxr2130	-	All	All	All
Operating System	Qualcomm	Sxr2130 Firmware	-	All	All	All
Operating System	Qualcomm	Sxr2130 Firmware	-	All	All	All
cpe:2.3:h:qualcomm:mdm9205:-:*~::~:						
cpe:2.3:h:qualcomm:mdm9205:-:*~::~:						
cpe:2.3:o:qualcomm:mdm9205_firmware:-:*~::~:						
cpe:2.3:o:qualcomm:mdm9205_firmware:-:*~::~:						
cpe:2.3:h:qualcomm:qcs404:-:*~::~:						
cpe:2.3:h:qualcomm:qcs404:-:*~::~:						
cpe:2.3:o:qualcomm:qcs404_firmware:-:*~::~:						
cpe:2.3:o:qualcomm:qcs404_firmware:-:*~::~:						
cpe:2.3:h:qualcomm:sdx55:-:*~::~:						
cpe:2.3:h:qualcomm:sdx55:-:*~::~:						
cpe:2.3:o:qualcomm:sdx55_firmware:-:*~::~:						
cpe:2.3:o:qualcomm:sdx55_firmware:-:*~::~:						
cpe:2.3:h:qualcomm:sm6150:-:*~::~:						
cpe:2.3:h:qualcomm:sm6150:-:*~::~:						
cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~:						
cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~:						
cpe:2.3:h:qualcomm:sm7150:-:*~::~:						
cpe:2.3:h:qualcomm:sm7150:-:*~::~:						

cpe:2.3:n:qualcomm:sm7150:-:*****:
cpe:2.3:o:qualcomm:sm7150_firmware:-:*****:
cpe:2.3:o:qualcomm:sm7150_firmware:-:*****:
cpe:2.3:h:qualcomm:sm8150:-:*****:
cpe:2.3:h:qualcomm:sm8150:-:*****:
cpe:2.3:o:qualcomm:sm8150_firmware:-:*****:
cpe:2.3:o:qualcomm:sm8150_firmware:-:*****:
cpe:2.3:h:qualcomm:sxr2130:-:*****:
cpe:2.3:h:qualcomm:sxr2130:-:*****:
cpe:2.3:o:qualcomm:sxr2130_firmware:-:*****:
cpe:2.3:o:qualcomm:sxr2130_firmware:-:*****:

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)