




CVE-2020-15061

Published on: 08/07/2020 12:00:00 AM UTC

Last Modified on: 07/21/2021 11:39:00 AM UTC

CVE-2020-15061

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of 42633 from [Lindy-international](#) contain the following vulnerability:

Lindy 42633 4-Port USB 2.0 Gigabit Network Server 2.078.000 devices allow an attacker on the same network to denial-of-service the device via long input values.

CVE-2020-15061 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **MEDIUM** severity.

CVSS3 Score: **6.5 - MEDIUM**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
ADJACENT_NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	NONE	NONE	HIGH

CVSS2 Score: **6.1 - MEDIUM**

Access Vector	Access Complexity	Authentication
ADJACENT_NETWORK	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
NONE	NONE	COMPLETE

CVE References

Description	Tags	Link
High-Impact Vulnerabilities In Multiple USB Network Servers – HiSolutions Research	Broken Link Third Party Advisory research.hisolutions.com text/html	MISC research.hisolutions.com/2020/05/critical-vulnerabilities-in-multiple-usb-network-servers/

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Lindy-international	42633	-	All	All	All
Hardware 	Lindy-international	42633	-	All	All	All
Operating System	Lindy-international	42633 Firmware	2.078.000	All	All	All
Operating System	Lindy-international	42633 Firmware	2.078.000	All	All	All
cpe:2.3:h:lindy-international:42633:-:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:h:lindy-international:42633:-:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:lindy-international:42633_firmware:2.078.000:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:lindy-international:42633_firmware:2.078.000:~::~~::~~::~~::~~::~~::~~::						

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)