




CVE-2020-26732

Published on: 01/14/2021 12:00:00 AM UTC

Last Modified on: 02/03/2023 06:55:00 PM UTC

CVE-2020-26732

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [Gn542vf Boa](#) from [Skyworth](#) contain the following vulnerability:

SKYWORTH GN542VF Boa version 0.94.13 does not set the Secure flag for the session cookie in an HTTPS session, which makes it easier for remote attackers to capture this cookie by intercepting its transmission within an HTTP session.

CVE-2020-26732 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **HIGH** severity.

CVSS3 Score: **7.5 - HIGH**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	NONE	NONE

CVSS2 Score: **5 - MEDIUM**

Access Vector	Access Complexity	Authentication
NETWORK	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
PARTIAL	NONE	NONE

CVE References

Description	Tags	Link
GitHub - swzhouu/CVE-2020-26732: Skyworth GN542VF Boa version 0.94.13 does not set the Secure flag for the session cookie in an HTTPS session	Third Party Advisory github.com text/html	MISC github.com/swzhouu/CVE-2020-26732

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that

would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Exploit/POC from Github

SKYWORTH GN542VF Hardware Version 2.0 and Software Version 2.0.0.16 does not set the Secure flag for the session cook...

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Skyworth	Gn542vf Boa	-	All	All	All
Hardware	Skyworth	Gn542vf Boa	-	All	All	All
Operating System	Skyworth	Gn542vf Boa Firmware	0.94.13	All	All	All
Operating System	Skyworth	Gn542vf Boa Firmware	0.94.13	All	All	All
cpe:2.3:h:skyworth:gn542vf_boa:-:~::~~::~~::~~::~~::~~::~~:::						
cpe:2.3:h:skyworth:gn542vf_boa:-:~::~~::~~::~~::~~::~~::~~:::						
cpe:2.3:o:skyworth:gn542vf_boa_firmware:0.94.13:~::~~::~~::~~::~~::~~::~~:::						
cpe:2.3:o:skyworth:gn542vf_boa_firmware:0.94.13:~::~~::~~::~~::~~::~~::~~:::						

No vendor comments have been submitted for this CVE

Social Mentions

Source	Title	Posted (UTC)
@RemotelyAlerts	Severity: ?? SKYWORTH GN542VF Boa version 0.94.13 doe... CVE-2020-26732 Link for more: alerts.remotelyrmm.com/CVE-2020-26732	2022-07-05 18:29:44

← Previous ID

Next ID →

