




CVE-2020-35827

Published on: 12/29/2020 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:23:48 PM UTC

CVE-2020-35827

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of **D7800** from **Netgear** contain the following vulnerability:

Certain NETGEAR devices are affected by stored XSS. This affects D7800 before 1.0.1.56, RBK50 before 2.3.5.30, RBR50 before 2.3.5.30, RBS50 before 2.3.5.30, R7800 before 1.0.2.74, R8900 before 1.0.4.28, R9000 before 1.0.4.28, XR500 before 2.3.2.56, XR700 before 1.0.1.10, and RAX120 before 1.0.0.78.

CVE-2020-35827 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **MEDIUM** severity.

CVSS3 Score: **4.8 - MEDIUM**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	HIGH	REQUIRED
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
CHANGED	LOW	LOW	NONE

CVSS2 Score: **3.5 - LOW**

Access Vector	Access Complexity	Authentication
NETWORK	MEDIUM	SINGLE
Confidentiality Impact	Integrity Impact	Availability Impact
NONE	PARTIAL	NONE

CVE References

Description	Tags	Link
Security Advisory for Stored Cross Site Scripting on Some Routers and WiFi Systems, PSV-2018-0504 Answer NETGEAR Support	Vendor Advisory kb.netgear.com text/html	N MISC kb.netgear.com/000062653/Security-Advisory-for-Stored-Cross-Site-Scripting-on-Some-Routers-and-WiFi-Systems-PSV-2018-0504

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Netgear	D7800	-	All	All	All
Hardware 	Netgear	D7800	-	All	All	All
Operating System	Netgear	D7800 Firmware	All	All	All	All
Operating System	Netgear	D7800 Firmware	All	All	All	All
Hardware 	Netgear	R7800	-	All	All	All
Hardware 	Netgear	R7800	-	All	All	All
Operating System	Netgear	R7800 Firmware	All	All	All	All
Operating System	Netgear	R7800 Firmware	All	All	All	All
Hardware 	Netgear	R8900	-	All	All	All
Hardware 	Netgear	R8900	-	All	All	All
Operating System	Netgear	R8900 Firmware	All	All	All	All
Operating System	Netgear	R8900 Firmware	All	All	All	All
Hardware 	Netgear	R9000	-	All	All	All
Hardware 	Netgear	R9000	-	All	All	All
Operating System	Netgear	R9000 Firmware	All	All	All	All
Operating System	Netgear	R9000 Firmware	All	All	All	All
Hardware 	Netgear	Rax120	-	All	All	All
Hardware 	Netgear	Rax120	-	All	All	All
Operating System	Netgear	Rax120 Firmware	All	All	All	All
Operating System	Netgear	Rax120 Firmware	All	All	All	All
Hardware 	Netgear	Rbk50	-	All	All	All

Hardware		Rbk50	-	All	All	All
Operating System	Netgear	Rbk50 Firmware	All	All	All	All
Operating System	Netgear	Rbk50 Firmware	All	All	All	All
Hardware		Rbr50	-	All	All	All
Hardware		Rbr50	-	All	All	All
Operating System	Netgear	Rbr50 Firmware	All	All	All	All
Operating System	Netgear	Rbr50 Firmware	All	All	All	All
Hardware		Rbs50	-	All	All	All
Hardware		Rbs50	-	All	All	All
Operating System	Netgear	Rbs50 Firmware	All	All	All	All
Operating System	Netgear	Rbs50 Firmware	All	All	All	All
Hardware		Xr500	-	All	All	All
Hardware		Xr500	-	All	All	All
Operating System	Netgear	Xr500 Firmware	All	All	All	All
Operating System	Netgear	Xr500 Firmware	All	All	All	All
Hardware		Xr700	-	All	All	All
Hardware		Xr700	-	All	All	All
Operating System	Netgear	Xr700 Firmware	All	All	All	All
Operating System	Netgear	Xr700 Firmware	All	All	All	All
cpe:2.3:h:netgear:d7800:-:~::~:						
cpe:2.3:h:netgear:d7800:-:~::~:						
cpe:2.3:o:netgear:d7800_firmware:~::~:						
cpe:2.3:o:netgear:d7800_firmware:~::~:						
cpe:2.3:h:netgear:r7800:-:~::~:						
cpe:2.3:h:netgear:r7800:-:~::~:						
cpe:2.3:o:netgear:r7800_firmware:~::~:						
cpe:2.3:o:netgear:r7800_firmware:~::~:						

cpe:2.3:0:netgear:r8900_firmware:~::~:
cpe:2.3:h:netgear:r8900:~::~:
cpe:2.3:h:netgear:r8900:~::~:
cpe:2.3:o:netgear:r8900_firmware:~::~:
cpe:2.3:o:netgear:r8900_firmware:~::~:
cpe:2.3:h:netgear:r9000:~::~:
cpe:2.3:h:netgear:r9000:~::~:
cpe:2.3:o:netgear:r9000_firmware:~::~:
cpe:2.3:o:netgear:r9000_firmware:~::~:
cpe:2.3:h:netgear:rax120:~::~:
cpe:2.3:h:netgear:rax120:~::~:
cpe:2.3:o:netgear:rax120_firmware:~::~:
cpe:2.3:o:netgear:rax120_firmware:~::~:
cpe:2.3:h:netgear:rbk50:~::~:
cpe:2.3:h:netgear:rbk50:~::~:
cpe:2.3:o:netgear:rbk50_firmware:~::~:
cpe:2.3:o:netgear:rbk50_firmware:~::~:
cpe:2.3:h:netgear:rbr50:~::~:
cpe:2.3:h:netgear:rbr50:~::~:
cpe:2.3:o:netgear:rbr50_firmware:~::~:
cpe:2.3:o:netgear:rbr50_firmware:~::~:
cpe:2.3:h:netgear:rbs50:~::~:
cpe:2.3:h:netgear:rbs50:~::~:
cpe:2.3:o:netgear:rbs50_firmware:~::~:
cpe:2.3:o:netgear:rbs50_firmware:~::~:
cpe:2.3:h:netgear:xr500:~::~:
cpe:2.3:h:netgear:xr500:~::~:
cpe:2.3:o:netgear:xr500_firmware:~::~:
cpe:2.3:o:netgear:xr500_firmware:~::~:

cpe:2.3:h:netgear:xr700:-:*:*:*:*:*:
cpe:2.3:h:netgear:xr700:-:*:*:*:*:*:
cpe:2.3:o:netgear:xr700_firmware:*:*:*:*:*:
cpe:2.3:o:netgear:xr700_firmware:*:*:*:*:*:

No vendor comments have been submitted for this CVE

← Previous ID

Next ID→