



# CVE-2021-0006

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

## Summary

<b>CVE</b>	CVE-2021-0006
<b>State</b>	PUBLIC
<b>Assigner</b>	secure@intel.com
<b>Source Priority</b>	CVE Program / NVD first with legacy fallback
<b>Published</b>	2021-08-11 13:15:00 UTC
<b>Updated</b>	2021-09-14 18:35:00 UTC
<b>Description</b>	Improper conditions check in firmware for Intel(R) Ethernet Adapters 800 Series Controllers and associated adapters before

## Risk And Classification

**Problem Types:** CWE-755

## NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Intel	Ethernet Controller E810	-	All	All	All
Operating System	Intel	Ethernet Controller E810 Firmware	All	All	All	All

## References

Reference	Source	Link	Tags
INTEL-SA-00479	MISC	<a href="http://www.intel.com">www.intel.com</a>	
Intel SA-00479 Ethernet Controller Vulnerabilities in NetApp Products   NetApp Product Security	CONFIRM	<a href="http://security.netapp.com">security.netapp.com</a>	
CVE Program record	CVE.ORG	<a href="http://www.cve.org">www.cve.org</a>	canoni
NVD vulnerability detail	NVD	<a href="http://nvd.nist.gov">nvd.nist.gov</a>	canoni

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

**Free CVE JSON API** [cve.report/api](https://cve.report/api)

**CVE.report and Source URL Uptime Status** [status.cve.report](https://status.cve.report)