




CVE-2021-20070

Published on: 02/16/2021 12:00:00 AM UTC

Last Modified on: 08/17/2021 05:22:00 PM UTC

CVE-2021-20070

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of **M!dge** from **Racom** contain the following vulnerability:

Racom's MIDGE Firmware 4.4.40.105 contains an issue that allows attackers to conduct cross-site scriptings attacks via the virtualization.php dialogs.

CVE-2021-20070 has been assigned by vulnreport@tenable.com to track the vulnerability - currently rated as **MEDIUM** severity.

CVSS3 Score: **4.8 - MEDIUM**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	HIGH	REQUIRED
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
CHANGED	LOW	LOW	NONE

CVSS2 Score: **3.5 - LOW**

Access Vector	Access Complexity	Authentication
NETWORK	MEDIUM	SINGLE
Confidentiality Impact	Integrity Impact	Availability Impact
NONE	PARTIAL	NONE

CVE References

Description	Tags	Link
Racom MIDGE Firmware Multiple Vulnerabilities - Research Advisory Tenable®	Third Party Advisory www.tenable.com text/html	MISC www.tenable.com/security/research/tra-2021-04

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that

would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Racom	M!dge	-	All	All	All
Hardware 	Racom	M!dge Cellular Router	-	All	All	All
Hardware 	Racom	M!dge Cellular Router	-	All	All	All
Hardware 	Racom	M!dge Cellular Router	-	All	All	All
Operating System	Racom	M!dge Cellular Router Firmware	4.4.40.105	All	All	All
Operating System	Racom	M!dge Cellular Router Firmware	4.4.40.105	All	All	All
Operating System	Racom	M!dge Firmware	4.4.40.105	All	All	All
cpe:2.3:h:racom:m\ldge:-:*~::~:						
cpe:2.3:h:racom:m\ldge_cellular_router:-:*~::~:						
cpe:2.3:h:racom:m\ldge_cellular_router:-:*~::~:						
cpe:2.3:h:racom:m\ldge_cellular_router:-:*~::~:						
cpe:2.3:o:racom:m\ldge_cellular_router_firmware:4.4.40.105:*~::~:						
cpe:2.3:o:racom:m\ldge_cellular_router_firmware:4.4.40.105:*~::~:						
cpe:2.3:o:racom:m\ldge_firmware:4.4.40.105:*~::~:						

No vendor comments have been submitted for this CVE

Social Mentions

Source	Title	Posted (UTC)
← Previous ID Next ID→		

site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](#)