



Description	Tags	Link
Type Confusion in 802154 ACK Frames Handling · Advisory · zephyrproject-rtos/zephyr · GitHub	github.com text/html	 MISC github.com/zephyrproject-rtos/zephyr/security/advisories/GHSA-27r3-rxch-2hm7

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Operating System	Zephyrproject	Zephyr	All	All	All	All
cpe:2.3:o:zephyrproject:zephyr:*:*:*:*:*:						

No vendor comments have been submitted for this CVE

Social Mentions

Source	Title	Posted (UTC)
 @CVEreport	CVE-2021-3320 : Type Confusion in 802154 ACK Frames Handling. Zephyr versions >= v2.4.0 contain NULL Pointer Derefe... twitter.com/i/web/status/1...	2021-05-24 22:43:02
 /r/netcve	CVE-2021-3320	2021-05-24 23:41:35

[← Previous ID](#)

[Next ID→](#)