



CVE-2021-43284

Published on: Not Yet Published

Last Modified on: 12/03/2021 03:53:00 PM UTC

CVE-2021-43284

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [Wr1200](#) from [Govicture](#) contain the following vulnerability:

An issue was discovered on Victure WR1200 devices through 1.0.3. The root SSH password never gets updated from its default value of admin. This enables an attacker to gain control of the device through SSH (regardless of whether the admin password was changed on the web interface).

CVE-2021-43284 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **HIGH** severity.

CVSS3 Score: **7.8 - HIGH**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
LOCAL	LOW	LOW	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: **7.2 - HIGH**

Access Vector	Access Complexity	Authentication
LOCAL	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
COMPLETE	COMPLETE	COMPLETE

CVE References

Description	Tags	Link
No Description Provided	www.nccgroup.trust text/html	MISC www.nccgroup.trust/us/our-research/?research=Technical+advisories
Technical Advisory – Multiple Vulnerabilities in Victure	research.nccgroup.com	MISC

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Govicture	Wr1200	-	All	All	All
Operating System	Govicture	Wr1200 Firmware	All	All	All	All
cpe:2.3:h:govicture:wr1200:-:~::~~::~~::~~::~~::~~::~~:::						
cpe:2.3:o:govicture:wr1200_firmware:~::~~::~~::~~::~~::~~::~~:::						

No vendor comments have been submitted for this CVE

Social Mentions

Source	Title	Posted (UTC)
 @CyberIQs_	Technical Advisory – Multiple Vulnerabilities in Victure WR1200 cyberiqs.com/technical-adv... #infosec #infosecurity... twitter.com/i/web/status/1...	2021-11-12 16:10:27
 @Gate_15_Analyst	#CyberSecurity research.nccgroup.com/2021/11/12/tec...	2021-11-15 14:41:43
 @CVEreport	CVE-2021-43284 : An issue was discovered on Victure WR1200 devices through 1.0.3. The root SSH password never gets... twitter.com/i/web/status/1...	2021-11-30 19:07:54
 @Robo_Alerts	Potentially Critical CVE Detected! CVE-2021-43284 Description: An issue was discovered on Victure WR1200 devices th... twitter.com/i/web/status/1...	2021-11-30 20:00:36
 /r/blueteamsec	Technical Advisory – Multiple Vulnerabilities in Victure WR1200 WiFi Router (CVE-2021-43282, CVE-2021-43283, CVE-2021-43284)	2021-11-12 17:28:34

[← Previous ID](#)

[Next ID →](#)

