



# CVE-2021-45529

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF !\[\]\(003082e50e3009141f59bd5df831749f\_img.jpg\)](#)

## Summary

<b>CVE</b>	CVE-2021-45529
<b>State</b>	PUBLIC
<b>Assigner</b>	cve@mitre.org
<b>Source Priority</b>	CVE Program / NVD first with legacy fallback
<b>Published</b>	2021-12-26 01:15:00 UTC
<b>Updated</b>	2022-01-06 20:14:00 UTC
<b>Description</b>	Certain NETGEAR devices are affected by a buffer overflow by an authenticated user. This affects CBR40 before 2.3.5.12,

## Risk And Classification

**Problem Types:** CWE-120

## NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	<a href="#">Netgear</a>	<a href="#">Cbr40</a>	-	All	All	All
Operating System	<a href="#">Netgear</a>	<a href="#">Cbr40 Firmware</a>	All	All	All	All
Hardware	<a href="#">Netgear</a>	<a href="#">D7000v2</a>	-	All	All	All
Operating System	<a href="#">Netgear</a>	<a href="#">D7000v2 Firmware</a>	All	All	All	All
Hardware	<a href="#">Netgear</a>	<a href="#">D8500</a>	-	All	All	All
Operating System	<a href="#">Netgear</a>	<a href="#">D8500 Firmware</a>	All	All	All	All
Hardware	<a href="#">Netgear</a>	<a href="#">R6400</a>	-	All	All	All
Operating System	<a href="#">Netgear</a>	<a href="#">R6400 Firmware</a>	All	All	All	All
Hardware	<a href="#">Netgear</a>	<a href="#">R6900p</a>	-	All	All	All
Operating System	<a href="#">Netgear</a>	<a href="#">R6900p Firmware</a>	All	All	All	All
Hardware	<a href="#">Netgear</a>	<a href="#">R7000</a>	-	All	All	All
Hardware	<a href="#">Netgear</a>	<a href="#">R7000p</a>	-	All	All	All
Operating System	<a href="#">Netgear</a>	<a href="#">R7000p Firmware</a>	All	All	All	All
Operating System	<a href="#">Netgear</a>	<a href="#">R7000 Firmware</a>	All	All	All	All
Hardware	<a href="#">Netgear</a>	<a href="#">R7900</a>	-	All	All	All
Operating System	<a href="#">Netgear</a>	<a href="#">R7900 Firmware</a>	All	All	All	All
Hardware	<a href="#">Netgear</a>	<a href="#">R8000</a>	-	All	All	All

Operating System	<a href="#">Netgear</a>	<a href="#">R8000 Firmware</a>	All	All	All	All
Hardware	<a href="#">Netgear</a>	<a href="#">Wnr3500lv2</a>	-	All	All	All
Operating System	<a href="#">Netgear</a>	<a href="#">Wnr3500lv2 Firmware</a>	All	All	All	All

## References

Reference	Source	Li
Security Advisory for Post-Authentication Buffer Overflow on Some Routers, PSV-2019-0077   Answer   NETGEAR Support	MISC	<a href="#">kt</a>
CVE Program record	CVE.ORG	<a href="#">w</a>
NVD vulnerability detail	NVD	<a href="#">n</a>

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

© [CVE.report](#) 2026 |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

**Free CVE JSON API** [cve.report/api](#)

**CVE.report and Source URL Uptime Status** [status.cve.report](#)