



CVE-2021-45986

Published on: Not Yet Published

Last Modified on: 07/12/2022 05:42:00 PM UTC

CVE-2021-45986

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [G1](#) from [Tendacn](#) contain the following vulnerability:

Tenda routers G1 and G3 v15.11.0.17(9502)_CN were discovered to contain a command injection vulnerability in the function formSetUSBShareInfo. This vulnerability allows attackers to execute arbitrary commands via the usbOrdinaryUserName parameter.

CVE-2021-45986 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **CRITICAL** severity.

CVSS3 Score: **9.8 - CRITICAL**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: **7.5 - HIGH**

Access Vector	Access Complexity	Authentication
NETWORK	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
PARTIAL	PARTIAL	PARTIAL

CVE References

Description	Tags	Link
my_vuln/2.md at main · pjqwudi/my_vuln · GitHub	github.com text/html	MISC github.com/pjqwudi/my_vuln/blob/main/Tenda/vuln_2/2.md
IBM X-Force Exchange	Third Party Advisory exchange.xforce.ibmcloud.com	MISC exchange.xforce.ibmcloud.com/vulnerabilities/218962

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Tendacn	G1	-	All	All	All
Operating System	Tendacn	G1 Firmware	15.11.0.17(9502\)_cn	All	All	All
Hardware 	Tendacn	G3	-	All	All	All
Operating System	Tendacn	G3 Firmware	15.11.0.17(9502\)_cn	All	All	All
cpe:2.3:h:tendacn:g1:-:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:tendacn:g1_firmware:15.11.0.17(9502\)_cn:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:h:tendacn:g3:-:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:tendacn:g3_firmware:15.11.0.17(9502\)_cn:~::~~::~~::~~::~~::~~::~~::						

No vendor comments have been submitted for this CVE

Social Mentions

Source	Title	Posted (UTC)
 @CVEreport	CVE-2021-45986 : Tenda routers G1 and G3 v15.11.0.17 9502 _CN were discovered to contain a command injection vulner... twitter.com/i/web/status/1...	2022-02-04 02:23:10

[← Previous ID](#)

[Next ID →](#)