



CVE-2021-45996

[MITRE](#)[NVD](#)[CVE.ORG](#)[Print: PDF](#)

Summary

CVE	CVE-2021-45996
State	PUBLIC
Assigner	cve@mitre.org
Source Priority	CVE Program / NVD first with legacy fallback
Published	2022-02-04 02:15:00 UTC
Updated	2022-02-08 16:10:00 UTC
Description	Tenda routers G1 and G3 v15.11.0.17(9502)_CN were discovered to contain a stack overflow in the function formSetPortM

Risk And Classification

Problem Types: CWE-787

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Tendacn	G1	-	All	All	All
Operating System	Tendacn	G1 Firmware	15.11.0.17(9502\)_cn	All	All	All
Hardware	Tendacn	G3	-	All	All	All
Operating System	Tendacn	G3 Firmware	15.11.0.17(9502\)_cn	All	All	All

References

Reference	Source	Link	Tags
my_vuln/Tenda/vuln_8 at main · pjqwudi/my_vuln · GitHub	MISC	github.com	
CVE Program record	CVE.ORG	www.cve.org	canonical
NVD vulnerability detail	NVD	nvd.nist.gov	canonical, analysis

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](#)