



# CVE-2022-29644

[MITRE](#)[NVD](#)[CVE.ORG](#)[Print: PDF](#)

## Summary

<b>CVE</b>	CVE-2022-29644
<b>State</b>	PUBLIC
<b>Assigner</b>	cve@mitre.org
<b>Source Priority</b>	CVE Program / NVD first with legacy fallback
<b>Published</b>	2022-05-18 12:15:00 UTC
<b>Updated</b>	2022-05-26 19:08:00 UTC
<b>Description</b>	TOTOLINK A3100R V4.1.2cu.5050_B20200504 and V4.1.2cu.5247_B20211129 were discovered to contain a hard coded

## Risk And Classification

**Problem Types:** CWE-798

## NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	<a href="#">Totolink</a>	<a href="#">A3100r</a>	-	All	All	All
Operating System	<a href="#">Totolink</a>	<a href="#">A3100r Firmware</a>	4.1.2cu.5050_b20200504	All	All	All
Operating System	<a href="#">Totolink</a>	<a href="#">A3100r Firmware</a>	4.1.2cu.5247_b20211129	All	All	All

## References

Reference	Source	Link	Tags
IOT/7.md at master · shijin0925/IOT · GitHub	MISC	<a href="#">github.com</a>	
CVE Program record	CVE.ORG	<a href="#">www.cve.org</a>	canonical
NVD vulnerability detail	NVD	<a href="#">nvd.nist.gov</a>	canonical, analysis

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

**CVE.report and Source URL Uptime Status [status.cve.report](#)**