



CVE-2022-30317

[MITRE](#)[NVD](#)[CVE.ORG](#)[Print: PDF](#)

Summary

CVE	CVE-2022-30317
State	PUBLIC
Assigner	cve@mitre.org
Source Priority	CVE Program / NVD first with legacy fallback
Published	2022-08-31 16:15:00 UTC
Updated	2022-09-09 03:41:00 UTC
Description	Honeywell Experion LX through 2022-05-06 has Missing Authentication for a Critical Function. According to FSCT-2022-00

Risk And Classification

Problem Types: CWE-306

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Honeywell	Experion Lx	-	All	All	All
Operating System	Honeywell	Experion Lx Firmware	All	All	All	All

References

Reference	Source	Link	Tags
Honeywell Experion LX CISA	MISC	www.cisa.gov	
Blog - Forescout	MISC	www.forescout.com	
CVE Program record	CVE.ORG	www.cve.org	canonical
NVD vulnerability detail	NVD	nvd.nist.gov	canonical, analysis

No vendor comments have been submitted for this CVE.

Legacy QID Mappings

[591319](#) [Honeywell Experion LX Missing Authentication for Critical Function Vulnerability \(ICSA-22-242-07\)](#)

completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](#)