



CVE-2022-32053

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF !\[\]\(003082e50e3009141f59bd5df831749f_img.jpg\)](#)

Summary

CVE	CVE-2022-32053
State	PUBLIC
Assigner	cve@mitre.org
Source Priority	CVE Program / NVD first with legacy fallback
Published	2022-07-01 18:15:00 UTC
Updated	2023-08-08 14:21:00 UTC
Description	TOTOLINK T6 V4.1.9cu.5179_B20201015 was discovered to contain a stack overflow via the cloneMac parameter in the fu

Risk And Classification

Problem Types: CWE-787

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Totolink	T6	-	All	All	All
Operating System	Totolink	T6 Firmware	4.1.9cu.5179_b20201015	All	All	All

References

Reference	Source	Link	Tags
IoT-vuln/Totolink/T6-v2/6.setWizardCfg at main · d1tto/IoT-vuln · GitHub	MISC	github.com	
CVE Program record	CVE.ORG	www.cve.org	canonical
NVD vulnerability detail	NVD	nvd.nist.gov	canonical, analysis

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

Free CVE JSON API cve.report/api

CVE.report and Source URL Uptime Status status.cve.report