



CVE-2022-36307

[MITRE](#)[NVD](#)[CVE.ORG](#)[Print: PDF](#)

Summary

CVE	CVE-2022-36307
State	PUBLIC
Assigner	cve-assign@fb.com
Source Priority	CVE Program / NVD first with legacy fallback
Published	2022-08-16 01:15:00 UTC
Updated	2022-08-17 14:11:00 UTC
Description	The AirVelocity 1500 prints SNMP credentials on its physically accessible serial port during boot. This was fixed in AirVeloc

Risk And Classification

Problem Types: CWE-522

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Airspan	Airvelocity 1500	-	All	All	All
Operating System	Airspan	Airvelocity 1500 Firmware	All	All	All	All

References

Reference	Source	Link
Airspan AirVelocity 1500 SNMP credentials printed on debug port · Advisory · metaredteam/external-disclosures · GitHub	MISC	github
Log in - Airspan JIRA	CONFIRM	help
CVE Program record	CVE.ORG	www
NVD vulnerability detail	NVD	nvd.i

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](#)