



CVE-2022-36571

Published on: Not Yet Published

Last Modified on: 09/02/2022 10:29:00 PM UTC

CVE-2022-36571

[Source: Mitre](#)

[Source: NIST](#)

[CVE.ORG](#)

[Print: PDF](#)



Certain versions of [Ac9](#) from [Tenda](#) contain the following vulnerability:

Tenda AC9 V15.03.05.19 was discovered to contain a stack overflow via the mask parameter at /goform/WanParameterSetting.

CVE-2022-36571 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **HIGH** severity.

CVSS3 Score: **7.2 - HIGH**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	HIGH	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVE References

Description	Tags	Link
IoTvuln/tenda_ac9_WanParameterSetting.md at main · CyberUnicornIoT/IoTvuln · GitHub	github.com text/html	MISC github.com/CyberUnicornIoT/IoTvuln/blob/main/Tenda_ac9/2/tenda_ac9_WanF

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to [comment@cve.report](#).

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Tenda	Ac9	-	All	All	All
Operating System	Tenda	Ac9 Firmware	15.03.05.19	All	All	All
cpe:2.3:h:tenda:ac9:-:*:*:*:*:*:						
cpe:2.3:o:tenda:ac9_firmware:15.03.05.19:*:*:*:*:*:						
No vendor comments have been submitted for this CVE						
Social Mentions						
Source	Title					Posted (UTC)
 @CVEreport	CVE-2022-36571 : Tenda AC9 V15.03.05.19 was discovered to contain a stack overflow via the mask parameter at /gofor... twitter.com/i/web/status/1...					2022-08-31 20:08:08
 /r/netcve	CVE-2022-36571					2022-08-31 20:38:46

[← Previous ID](#)[Next ID →](#)