



CVE-2022-39094

Published on: Not Yet Published

Last Modified on: 01/10/2023 06:48:00 PM UTC

CVE-2022-39094

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [Android](#) from [Google](#) contain the following vulnerability:

In power management service, there is a missing permission check. This could lead to set up power management service with no additional execution privileges needed.

CVE-2022-39094 has been assigned by [security@unisoc.com](#) to track the vulnerability - currently rated as **HIGH** severity.

Affected Vendor/Software: [Unisoc \(Shanghai\) Technologies Co., Ltd.](#) -
SC9863A/SC9832E/SC7731E/T610/T310/T606/T760/T618/T606/T612/T616/T760/T770/T820/S8000 version
Android10/Android11/Android12

CVSS3 Score: **7.8 - HIGH**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
LOCAL	LOW	LOW	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVE References

Description	Tags	Link
Latest News	www.unisoc.com text/html	MISC www.unisoc.com/en_us/secy/announcementDetail/1599588060988411006
Latest News	www.unisoc.com text/html	MISC www.unisoc.com/en_us/secy/announcementDetail/1610118225591336001

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to [comment@cve.report](#).

cpe:2.3:h:unisoc:t610:-:*****:.*.*
cpe:2.3:h:unisoc:t612:-:*****:.*.*
cpe:2.3:h:unisoc:t616:-:*****:.*.*
cpe:2.3:h:unisoc:t618:-:*****:.*.*
cpe:2.3:h:unisoc:t760:-:*****:.*.*
cpe:2.3:h:unisoc:t770:-:*****:.*.*
cpe:2.3:h:unisoc:t820:-:*****:.*.*

No vendor comments have been submitted for this CVE

Social Mentions

Source	Title	Posted (UTC)
 @CVEreport	CVE-2022-39094 : In power management service, there is a missing permission check. This could lead to set up power... twitter.com/i/web/status/1...	2022-12-06 07:08:22
 /r/netcve	CVE-2022-39094	2022-12-06 07:39:26

[← Previous ID](#)

Next ID→

© CVE.report 2023   |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status status.cve.report