



CVE-2022-40101

[MITRE](#)[NVD](#)[CVE.ORG](#)[Print: PDF](#)

Summary

CVE	CVE-2022-40101
State	PUBLIC
Assigner	cve@mitre.org
Source Priority	CVE Program / NVD first with legacy fallback
Published	2022-09-23 19:15:00 UTC
Updated	2022-09-27 05:00:00 UTC
Description	Tenda i9 v1.0.0.8(3828) was discovered to contain a buffer overflow via the formWifiMacFilterSet function. This vulnerability

Risk And Classification

Problem Types: CWE-787

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Tenda	I9	-	All	All	All
Operating System	Tenda	I9 Firmware	1.0.0.8(3828)	All	All	All

References

Reference	Source
IOT_Vulnerability_Discovery/buffer_overflow_formWifiMacFilterSet.md at main · splashsc/IOT_Vulnerability_Discovery · GitHub	MISC
CVE Program record	CVE.ORG
NVD vulnerability detail	NVD

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](#)