



CVE-2022-44362

Published on: Not Yet Published

Last Modified on: 12/05/2022 06:28:00 PM UTC


CVE-2022-44362

[Source: Mitre](#)

[Source: NIST](#)

[CVE.ORG](#)

[Print: PDF](#)



Certain versions of [i21](#) from [Tenda](#) contain the following vulnerability:

Tenda i21 V1.0.0.14(4656) is vulnerable to Buffer Overflow via /goform/AddSysLogRule.

CVE-2022-44362 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **CRITICAL** severity.

CVSS3 Score: **9.8 - CRITICAL**

Attack
Vector

Attack
Complexity

Privileges
Required

User
Interaction

NETWORK

LOW

NONE

NONE

Scope

Confidentiality
Impact

Integrity
Impact

Availability
Impact

UNCHANGED

HIGH

HIGH

HIGH

CVE References

Description

Tags

Link

CVE-vulns/readme.md at main · Double-q1015/CVE-vulns · GitHub

[github.com](#)
[text/html](#)

[MISC github.com/Double-q1015/CVE-vulns/blob/main/Tenda/i21/formAddSysLogRule/readme.md](#)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Exploit/POC from Github

Tenda i21 V1.0.0.14(4656) is vulnerable to Buffer Overflow via /goform/AddSysLogRule. CVE

Tenda i21 V1.0.0.14(4656) is vulnerable to Buffer Overflow via /goform/AddSysLogRule. CVE project by @Sn0wAlice

Known Affected Configurations (CPE V2.3)						
Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Tenda	I21	-	All	All	All
Operating System	Tenda	I21 Firmware	1.0.0.14\ (4656\)	All	All	All
cpe:2.3:h:tenda:i21:-:*:*:*:*:*:						
cpe:2.3:o:tenda:i21_firmware:1.0.0.14\ (4656\):*:*:*:*:*:						

No vendor comments have been submitted for this CVE

Social Mentions		
Source	Title	Posted (UTC)
@CVEreport	CVE-2022-44362 : Tenda i21 V1.0.0.14 4656 is vulnerable to Buffer Overflow via /goform/AddSysLogRule.... cve.report/CVE-2022-44362	2022-12-02 17:05:36
@threatmeter	CVE-2022-44362 Tenda i21 V1.0.0.14(4656) is vulnerable to Buffer Overflow via /goform/AddSysLogRule. (CVSS:0.0) (La... twitter.com/i/web/status/1...	2022-12-02 23:14:46
/r/netcve	CVE-2022-44362	2022-12-02 17:39:36