




# CVE-2022-44363

Published on: Not Yet Published

Last Modified on: 12/05/2022 06:27:00 PM UTC

## CVE-2022-44363

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#)

Certain versions of [i21](#) from [Tenda](#) contain the following vulnerability:

Tenda i21 V1.0.0.14(4656) is vulnerable to Buffer Overflow via /goform/setSnmpInfo.

CVE-2022-44363 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **CRITICAL** severity.

CVSS3 Score: **9.8 - CRITICAL**

| Attack Vector    | Attack Complexity      | Privileges Required | User Interaction    |
|------------------|------------------------|---------------------|---------------------|
| <b>NETWORK</b>   | <b>LOW</b>             | <b>NONE</b>         | <b>NONE</b>         |
| Scope            | Confidentiality Impact | Integrity Impact    | Availability Impact |
| <b>UNCHANGED</b> | <b>HIGH</b>            | <b>HIGH</b>         | <b>HIGH</b>         |

## CVE References

| Description                                                   | Tags                                                    | Link                                                                                                 |
|---------------------------------------------------------------|---------------------------------------------------------|------------------------------------------------------------------------------------------------------|
| CVE-vulns/readme.md at main · Double-q1015/CVE-vulns · GitHub | <a href="#">github.com</a><br><a href="#">text/html</a> | <a href="#">MISC github.com/Double-q1015/CVE-vulns/blob/main/Tenda/i21/formSetSnmpInfo/readme.md</a> |

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to [comment@cve.report](mailto:comment@cve.report).

There are currently no QIDs associated with this CVE

## Exploit/POC from Github

Tenda i21 V1 0 0 14(4656) is vulnerable to Buffer Overflow via /goform/setSnmpInfo CVE

Tenda i21 V1.0.0.14(4656) is vulnerable to Buffer Overflow via /goform/setSnmpInfo. CVE project by @Sn0wAlice

| Known Affected Configurations (CPE V2.3)           |                       |                              |                |        |         |          |
|----------------------------------------------------|-----------------------|------------------------------|----------------|--------|---------|----------|
| Type                                               | Vendor                | Product                      | Version        | Update | Edition | Language |
| Hardware                                           | <a href="#">Tenda</a> | <a href="#">I21</a>          | -              | All    | All     | All      |
| Operating System                                   | <a href="#">Tenda</a> | <a href="#">I21 Firmware</a> | 1.0.0.14(4656) | All    | All     | All      |
| cpe:2.3:h:tenda:i21:-:*****:                       |                       |                              |                |        |         |          |
| cpe:2.3:o:tenda:i21_firmware:1.0.0.14(4656):*****: |                       |                              |                |        |         |          |

No vendor comments have been submitted for this CVE

| Social Mentions |                                                                                                                                                                      |                     |
|-----------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|
| Source          | Title                                                                                                                                                                | Posted (UTC)        |
| @CVEreport      | CVE-2022-44363 : Tenda i21 V1.0.0.14 4656 is vulnerable to Buffer Overflow via /goform/setSnmpInfo.... <a href="#">cve.report/CVE-2022-44363</a>                     | 2022-12-02 17:05:58 |
| @threatmeter    | CVE-2022-44363 Tenda i21 V1.0.0.14(4656) is vulnerable to Buffer Overflow via /goform/setSnmpInfo. (CVSS:0.0) (Last... <a href="#">twitter.com/i/web/status/1...</a> | 2022-12-02 23:14:46 |
| /r/netcve       | <a href="#">CVE-2022-44363</a>                                                                                                                                       | 2022-12-02 17:39:36 |