



CVE-2022-45670

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

Summary

CVE	CVE-2022-45670
State	PUBLIC
Assigner	cve@mitre.org
Source Priority	CVE Program / NVD first with legacy fallback
Published	2022-12-02 18:15:00 UTC
Updated	2022-12-06 00:48:00 UTC
Description	Tenda i22 V1.0.0.3(4687) was discovered to contain a buffer overflow via the ping1 parameter in the formSetAutoPing func

Risk And Classification

Problem Types: CWE-120

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Tenda	I22	-	All	All	All
Operating System	Tenda	I22 Firmware	1.0.0.3\ (4687\)	All	All	All

References

Reference	Source	Link
VulnerabilityProjectRecords/formSetAutoPing_ping1.md at main · iceyjchen/VulnerabilityProjectRecords · GitHub	MISC	github.com
CVE Program record	CVE.ORG	www.cve.org
NVD vulnerability detail	NVD	nvd.nist.gov

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

Free CVE JSON API cve.report/api

CVE.report and Source URL Uptime Status status.cve.report