




CVE-2023-1262

Published on: Not Yet Published

Last Modified on: 03/30/2023 07:33:00 PM UTC

CVE-2023-1262

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#)

Certain versions of [Wireless Smart Ubiquitous Network Linux Border Router](#) from [Silabs](#) contain the following vulnerability:

Missing MAC layer security in Silicon Labs Wi-SUN Linux Border Router v1.5.2 and earlier allows malicious node to route malicious messages through network.

CVE-2023-1262 has been assigned by [Silabs](#) product-security@silabs.com to track the vulnerability - currently rated as **MEDIUM** severity.

Affected Vendor/Software: [Silabs](#) **silabs.com - Wi-SUN Linux Border Router** version **<= 1.5.2**

CVSS3 Score: **5.3 - MEDIUM**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	NONE	LOW	NONE

CVE References

Description	Tags	Link
No Description Provided	community.silabs.com text/html	Silabs MISC community.silabs.com/sfc/servlet.shepherd/document/download/0698Y00000SMYfRQAT?operationContext=S1
GitHub - SiliconLabs/wisun-br-linux: Silicon Labs Wi-SUN Linux border router reference implementation	github.com text/html	Silabs MISC github.com/SiliconLabs/wisun-br-linux

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further,

CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Silabs	Wireless Smart Ubiquitous Network Linux Border Router	-	All	All	All
Operating System	Silabs	Wireless Smart Ubiquitous Network Linux Border Router Firmware	All	All	All	All
cpe:2.3:h:silabs:wireless_smart_ubiquitous_network_linux_border_router:-:*:*:*:*:*:						
cpe:2.3:o:silabs:wireless_smart_ubiquitous_network_linux_border_router_firmware:*:*:*:*:*:						

No vendor comments have been submitted for this CVE

Social Mentions

Source	Title	Posted (UTC)
 @CVEreport	CVE-2023-1262 : Missing MAC layer security in Silicon Labs Wi-SUN #Linux Border Router v1.5.2 and earlier allows ma... twitter.com/i/web/status/1...	2023-03-21 21:06:25
 @safelabsbr	CVE-2023-1262 Missing MAC layer security in Silicon Labs Wi-SUN Linux Border Router v1.5.2... twitter.com/i/web/status/1...	2023-03-21 22:10:19
 /r/netcve	CVE-2023-1262	2023-03-21 22:38:27

[← Previous ID](#)

[Next ID →](#)