



CVE-2023-23150


Published on: Not Yet Published

Last Modified on: 03/22/2023 03:58:00 PM UTC

CVE-2023-23150

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#)

CVSS:31/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H



Certain versions of [Sa-wr915nd](#) from [Lancombg](#) contain the following vulnerability:

SA-WR915ND router firmware v17.35.1 was discovered to be vulnerable to code execution.

CVE-2023-23150 has been assigned by [M](#) [cve@mitre.org](#) to track the vulnerability - currently rated as **CRITICAL** severity.

CVSS3 Score: **9.8 - CRITICAL**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVE References

Description	Tags	Link
CVE-2023-23150 · GitHub	gist.github.com text/html	MISC gist.github.com/yinfei6/f7099835e9abbe16a29744430ea76a37#file-cve-2023-23150
No Description Provided	reference14.example.com	MISC reference14.example.com
	Inactive Link Not Archived	

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to [comment@cve.report](#).

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)						
Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Lancombg	Sa-wr915nd	-	All	All	All
Operating System	Lancombg	Sa-wr915nd Firmware	17.35.1	All	All	All
cpe:2.3:h:lancombg:sa-wr915nd:-:~::~~::~~::~~::~~::~~::~:						
cpe:2.3:o:lancombg:sa-wr915nd_firmware:17.35.1:~::~~::~~::~~::~~::~~::~:						
No vendor comments have been submitted for this CVE						
Social Mentions						
Source	Title					Posted (UTC)
 @CVEreport	CVE-2023-23150 : SA-WR915ND router firmware v17.35.1 was discovered to be vulnerable to code execution.... cve.report/CVE-2023-23150					2023-03-16 02:06:23
 @Robo_Alerts	Potentially Critical CVE Detected! CVE-2023-23150 SA-WR915ND router firmware v17.35.1 was discovered to be vulnerab... twitter.com/i/web/status/1...					2023-03-16 03:56:00
 /r/netcve	CVE-2023-23150					2023-03-16 03:38:47
← Previous ID			Next ID →			