



CVE-2023-26616

Published on: Not Yet Published

Last Modified on: 07/06/2023 06:45:00 PM UTC

CVE-2023-26616

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#)

Certain versions of [Dir-823g](#) from [Dlink](#) contain the following vulnerability:

D-Link DIR-823G firmware version 1.02B05 has a buffer overflow vulnerability, which originates from the URL field in SetParentsControllInfo.

CVE-2023-26616 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **CRITICAL** severity.

CVSS3 Score: **9.8 - CRITICAL**

Attack
Vector

Attack
Complexity

Privileges
Required

User
Interaction

NETWORK

LOW

NONE

NONE

Scope

Confidentiality
Impact

Integrity
Impact

Availability
Impact

UNCHANGED

HIGH

HIGH

HIGH

CVE References

Description

Tags

Link

VulloT/D-Link/DIR823G
V1.0.2B05/HNAP1/SetParentsControllInfo at main ·
726232111/VulloT · GitHub

[github.com](#)
[text/html](#)

[MISC github.com/726232111/VulloT/tree/main/D-Link/DIR823G%20V1.0.2B05/HNAP1/SetParentsControllInfo](#)

Security Bulletin | D-Link

[www.dlink.com](#)
[text/html](#)

[D MISC www.dlink.com/en/security-bulletin/](#)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Dlink	Dir-823g	-	All	All	All
Operating System	Dlink	Dir-823g Firmware	1.02b05	All	All	All
cpe:2.3:h:dlink:dir-823g:-:*:*:*:*:*:						
cpe:2.3:o:dlink:dir-823g_firmware:1.02b05:*:*:*:*:*:						

No vendor comments have been submitted for this CVE

Social Mentions

Source	Title	Posted (UTC)
 @CVEreport	CVE-2023-26616 : D-Link DIR-823G firmware version 1.02B05 has a buffer overflow vulnerability, which originates fro... twitter.com/i/web/status/1...	2023-06-29 16:03:38
 @Robo_Alerts	Potentially Critical CVE Detected! CVE-2023-26616 D-Link DIR-823G firmware version 1.02B05 has a buffer overflow vu... twitter.com/i/web/status/1...	2023-06-29 16:11:02
 @ThreatFeed	CVE-2023-26616 dlvr.it/SrgXFt	2023-07-04 17:37:13

← Previous ID

Next ID →