



CVE-2023-31587

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

Summary

CVE	CVE-2023-31587
State	PUBLIC
Assigner	cve@mitre.org
Source Priority	CVE Program / NVD first with legacy fallback
Published	2023-05-16 15:15:00 UTC
Updated	2023-05-22 17:20:00 UTC
Description	Tenda AC5 router V15.03.06.28 was discovered to contain a remote code execution (RCE) vulnerability via the Mac param

Risk And Classification

Problem Types: NVD-CWE-noinfo

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Tenda	Ac5	-	All	All	All
Operating System	Tenda	Ac5 Firmware	15.03.06.28	All	All	All

References

Reference	Source	Link	Tags
腾达AC5升级软件 下载,腾达升级软件,腾达路由器软件_腾达(Tenda)官网	MISC	www.tenda.com.cn	
CVE/TendaAC5.md at main · yanbushuang/CVE · GitHub	MISC	github.com	
腾达(Tenda) AC5 1200M中小户型双频智能路由AC5_腾达(Tenda)官网	MISC	www.tenda.com.cn	
CVE Program record	CVE.ORG	www.cve.org	canonical
NVD vulnerability detail	NVD	nvd.nist.gov	canonical, analysis

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

Free CVE JSON API cve.report/api

CVE.report and Source URL Uptime Status status.cve.report