



CVE-2023-34570

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

Summary

CVE	CVE-2023-34570
State	PUBLIC
Assigner	cve@mitre.org
Source Priority	CVE Program / NVD first with legacy fallback
Published	2023-06-08 15:15:00 UTC
Updated	2023-11-07 04:15:00 UTC
Description	Tenda AC10 v4 US_AC10V4.0si_V16.03.10.13_cn was discovered to contain a stack overflow via parameter devName at /

Risk And Classification

Problem Types: CWE-787

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Tenda	Ac10	4.0	All	All	All
Operating System	Tenda	Ac10 Firmware	us_ac10v4.0si_v16.03.10.13_cn	All	All	All

References

Reference	Source	Link
Tenda AC10 v4 was discovered stack overflow via parameter devName at url /goform/SetOnlineDevName - HackMD	MISC	hackmd.
Tenda AC10 v4 was discovered stack overflow via parameter devName at url /goform/SetOnlineDevName - HackMD		hackmd.
CVE Program record	CVE.ORG	www.cve
NVD vulnerability detail	NVD	nvd.nist.

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

Free CVE JSON API cve.report/api

CVE.report and Source URL Uptime Status status.cve.report