



# CVE-2023-34934

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF !\[\]\(003082e50e3009141f59bd5df831749f\_img.jpg\)](#)

## Summary

<b>CVE</b>	CVE-2023-34934
<b>State</b>	PUBLIC
<b>Assigner</b>	cve@mitre.org
<b>Source Priority</b>	CVE Program / NVD first with legacy fallback
<b>Published</b>	2023-06-28 15:15:00 UTC
<b>Updated</b>	2023-07-05 18:48:00 UTC
<b>Description</b>	A stack overflow in the Edit_BasicSSID_5G function of H3C Magic B1STV100R012 allows attackers to cause a Denial of S

## Risk And Classification

**Problem Types: CWE-787**

## NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	H3c	Magic B1st	-	All	All	All
Operating System	H3c	Magic B1st Firmware	100r012	All	All	All

## References

Reference	Source	Link	Tags
vuln/H3C_B1STW/CVE-2023-34934.md at main · h4kuy4/vuln · GitHub	MISC	<a href="https://github.com">github.com</a>	
CVE Program record	CVE.ORG	<a href="https://www.cve.org">www.cve.org</a>	canonical
NVD vulnerability detail	NVD	<a href="https://nvd.nist.gov">nvd.nist.gov</a>	canonical, analysis

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

**Free CVE JSON API** [cve.report/api](https://cve.report/api)

**CVE.report and Source URL Uptime Status** [status.cve.report](https://status.cve.report)