



# CVE-2023-39750

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

## Summary

<b>CVE</b>	CVE-2023-39750
<b>State</b>	PUBLIC
<b>Assigner</b>	cve@mitre.org
<b>Source Priority</b>	CVE Program / NVD first with legacy fallback
<b>Published</b>	2023-08-21 03:15:00 UTC
<b>Updated</b>	2023-08-24 21:24:00 UTC
<b>Description</b>	D-Link DAP-2660 v1.13 was discovered to contain a buffer overflow via the f_ipv6_enable parameter at /bsc_ipv6. This vuln

## Risk And Classification

**Problem Types:** CWE-120

## NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Dlink	Dap-2660	-	All	All	All
Operating System	Dlink	Dap-2660 Firmware	1.13	All	All	All

## References

Reference	Source	Link	Tags
D-Link DAP-2660 wireless router /bsc_ipv6 buffer read out-of-bounds vulnerability	MISC	<a href="#">github.com</a>	
Security Bulletin   D-Link	MISC	<a href="#">www.dlink.com</a>	
CVE Program record	CVE.ORG	<a href="#">www.cve.org</a>	canonical
NVD vulnerability detail	NVD	<a href="#">nvd.nist.gov</a>	canonical, analysis

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

**Free CVE JSON API** [cve.report/api](https://cve.report/api)

**CVE.report and Source URL Uptime Status** [status.cve.report](https://status.cve.report)