



CVE-2023-40844

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

Summary

| | |
|------------------------|---------------------------------------------------------------------------------------------------------------------|
| CVE | CVE-2023-40844 |
| State | PUBLIC |
| Assigner | cve@mitre.org |
| Source Priority | CVE Program / NVD first with legacy fallback |
| Published | 2023-08-30 17:15:00 UTC |
| Updated | 2023-09-07 14:15:00 UTC |
| Description | Tenda AC6 US_AC6V1.0BR_V15.03.05.16_multi_TD01.bin is vulnerable to Buffer Overflow via function 'formWifiBasicSet. |

Risk And Classification

Problem Types: CWE-787

NVD Known Affected Configurations (CPE 2.3)

| Type | Vendor | Product | Version | Update | Edition | Language |
|------------------|-----------------------|------------------------------|-------------|--------|---------|----------|
| Hardware | Tenda | Ac6 | 1.0 | All | All | All |
| Operating System | Tenda | Ac6 Firmware | 15.03.05.16 | All | All | All |

References

| Reference | Source | Link | Tags |
|-------------------------------|---------|------------------------------|---------------------|
| 0, Vulnerability Introduction | MISC | github.com | |
| CVE Program record | CVE.ORG | www.cve.org | canonical |
| NVD vulnerability detail | NVD | nvd.nist.gov | canonical, analysis |

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

Free CVE JSON API cve.report/api

CVE.report and Source URL Uptime Status status.cve.report