



# CVE-2023-44013

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF !\[\]\(003082e50e3009141f59bd5df831749f\_img.jpg\)](#)

## Summary

<b>CVE</b>	CVE-2023-44013
<b>State</b>	PUBLIC
<b>Assigner</b>	cve@mitre.org
<b>Source Priority</b>	CVE Program / NVD first with legacy fallback
<b>Published</b>	2023-09-27 15:19:00 UTC
<b>Updated</b>	2023-09-27 18:45:00 UTC
<b>Description</b>	Tenda AC10U v1.0 US_AC10UV1.0RTL_V15.03.06.49_multi_TDE01 was discovered to contain a stack overflow via the lis

## Risk And Classification

**Problem Types:** CWE-119

## NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	<a href="#">Tendacn</a>	<a href="#">Ac10u</a>	1.0	All	All	All
Operating System	<a href="#">Tendacn</a>	<a href="#">Ac10u Firmware</a>	15.03.06.49_multi_tde01	All	All	All

## References

### Reference

- Tenda AC10U v1.0 US\_AC10UV1.0RTL\_V15.03.06.49\_multi\_TDE01 were discovered to contain a stack overflow via the list parameter in the CVE Program record
- NVD vulnerability detail

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

**Free CVE JSON API** [cve.report/api](https://cve.report/api)

**CVE.report and Source URL Uptime Status** [status.cve.report](https://status.cve.report)