



# CVE-2023-44020

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

## Summary

<b>CVE</b>	CVE-2023-44020
<b>State</b>	PUBLIC
<b>Assigner</b>	cve@mitre.org
<b>Source Priority</b>	CVE Program / NVD first with legacy fallback
<b>Published</b>	2023-09-27 15:19:00 UTC
<b>Updated</b>	2023-09-27 18:45:00 UTC
<b>Description</b>	Tenda AC10U v1.0 US_AC10UV1.0RTL_V15.03.06.49_multi_TDE01 was discovered to contain a stack overflow via the se

## Risk And Classification

**Problem Types:** CWE-119

## NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	<a href="#">Tendacn</a>	<a href="#">Ac10u</a>	1.0	All	All	All
Operating System	<a href="#">Tendacn</a>	<a href="#">Ac10u Firmware</a>	15.03.06.49_multi_tde01	All	All	All

## References

### Reference

Tenda AC10U v1.0 US\_AC10UV1.0RTL\_V15.03.06.49\_multi\_TDE01 were discovered to contain a stack overflow via the security parameter i

[CVE Program record](#)

[NVD vulnerability detail](#)

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

**Free CVE JSON API** [cve.report/api](https://cve.report/api)

**CVE.report and Source URL Uptime Status** [status.cve.report](https://status.cve.report)