



Ericsson Indoor Connect 8855 - Insufficiently Protected Credentials Vulnerability

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

Summary

CVE	CVE-2025-40838
State	PUBLISHED
Assigner	ERIC
Source Priority	CVE Program / NVD first with legacy fallback
Published	2025-09-25 15:16:11 UTC
Updated	2026-04-29 01:00:01 UTC
Description	Ericsson Indoor Connect 8855 contains a vulnerability where server-side security can be bypassed in the client which if exp

Risk And Classification

Primary CVSS: v4.0 5.1 MEDIUM from 85b1779b-6ecd-4f52-bcc5-73eac4659dcf

CVSS:4.0/AV:N/AC:L/AT:N/PR:H/UI:N/VC:N/VI:N/VA:N/SC:L/SI:N/SA:N/E:X/CR:X/IR:X/AR:X/MAV:X/MAC:X/MAT:X/MPR:X/MUI:X/MVC:X/MVI:X/MVA:X/MSX/MSI:X/MSA:X/S:X/AU:X/R:X/V:X/RE:X/U:X

Problem Types: CWE-522 | CWE-522 CWE-522 Insufficiently Protected Credentials

Version	Source	Type	Score	Severity	Vector
4.0	85b1779b-6ecd-4f52-bcc5-73eac4659dcf	Secondary	5.1	MEDIUM	CVSS:4.0/AV:N/AC:L/AT:N/PR:H/UI:N/VC:N/VI:N/VA:N/SC:L/SI:N/SA:N/E:X/CR:X/IR:X/AR:X/MAV:X/MAC:X/MAT:X/MPR:X/MUI:X/MVC:X/MVI:X/MVA:X/MSX/MSI:X/MSA:X/S:X/AU:X/R:X/V:X/RE:X/U:X
4.0	CNA	CVSS	5.1	MEDIUM	CVSS:4.0/AV:N/AC:L/AT:N/PR:H/UI:N/VC:N/VI:N/VA:N/SC:L/SI:N/SA:N/E:X/CR:X/IR:X/AR:X/MAV:X/MAC:X/MAT:X/MPR:X/MUI:X/MVC:X/MVI:X/MVA:X/MSX/MSI:X/MSA:X/S:X/AU:X/R:X/V:X/RE:X/U:X
3.1	nvd@nist.gov	Primary	7.5	HIGH	CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:N/A:N

CVSS v4.0 Breakdown

Attack Vector

Network

Attack Complexity

Low

Attack Requirements

None

Privileges Required

High

User Interaction

None

Confidentiality

None

Integrity

None

Availability

None

Sub Conf.

Low

Sub Integrity

None

Sub Availability

None

CVSS:4.0/AV:N/AC:L/AT:N/PR:H/UI:N/VC:N/VI:N/VA:N/SC:L/SI:N/SA:N/E:X/CR:X/IR:X/AR:X/MAV:X/MAC:X/MAT:X/MPR:X/MUI:X/MVC:X/MVI:X/MVA:X/MSX/MSI:X/MSA:X/S:X/AU:X/R:X/V:X/RE:X/U:X

CVSS v3.1 Breakdown

Attack Vector

Network

Attack Complexity

Low

Privileges Required

None

User Interaction

None

Scope

Unchanged

Confidentiality

High

Integrity

None

Availability

None

CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:N/A:N

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Ericsson	Indoor Connect 8855	-	All	All	All
Operating System	Ericsson	Indoor Connect 8855 Firmware	All	All	All	All

Vendor Declared Affected Products

Source	Vendor	Product	Version	Platforms
CNA	Ericsson	Indoor Connect 8855	affected 2025.Q2 Indoor Connect 8855	Not specified

Reference	Source	Link	Tags
www.ericsson.com/en/about-us/security/psirt/e2025-09-25	85b1779b-6ecd-4f52-bcc5-73eac4659dcf	www.ericsson.com	Vendor Advisor
CVE Program record	CVE.ORG	www.cve.org	canonical
NVD vulnerability detail	NVD	nvd.nist.gov	canonical, anal

Vendor Comments And Credit

Discovery Credit
CNA: Telstra (en)

There are currently no legacy QID mappings associated with this CVE.

© CVE.report 2026 |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

Free CVE JSON API cve.report/api

CVE.report and Source URL Uptime Status status.cve.report