



CVE-2026-25786

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

Summary

CVE	CVE-2026-25786
State	PUBLISHED
Assigner	siemens
Source Priority	CVE Program / NVD first with legacy fallback
Published	2026-05-12 10:16:44 UTC
Updated	2026-05-12 14:19:41 UTC
Description	Affected devices do not properly validate and sanitize PLC/station name rendered on the "communication" parameters page

Risk And Classification

Primary CVSS: v4.0 9.3 CRITICAL from productcert@siemens.com

CVSS:4.0/AV:N/AC:L/AT:N/PR:H/UI:P/VC:H/VI:H/VA:H/SC:H/SI:H/SA:H/E:X/CR:X/IR:X/AR:X/MAV:X/MAC:X/MAT:X/MPR:X/MUI:X/MVC:X/MVI:X/MVA:X/MSX/MSI:X/MSA:X/S:X/AU:X/R:X/V:X/RE:X/U:X

EPSS: 0.000440000 probability, percentile 0.133910000 (date 2026-05-12)

Problem Types: CWE-79 | CWE-79 CWE-79: Improper Neutralization of Input During Web Page Generation ('Cross-site Scripting')

Version	Source	Type	Score	Severity	Vector
4.0	productcert@siemens.com	Secondary	9.3	CRITICAL	CVSS:4.0/AV:N/AC:L/AT:N/PR:H/UI:P/VC:H/VI:H/VA:H/SC:H/SI:H/SA:H/E:X/CR:X/IR:X/AR:X/MAV:X/MAC:X/MAT:X/MPR:X/MUI:X/MVC:X/MVI:X/MVA:X/MSX/MSI:X/MSA:X/S:X/AU:X/R:X/V:X/RE:X/U:X
4.0	CNA	DECLARED	9.3	CRITICAL	CVSS:4.0/AV:N/AC:L/AT:N/PR:H/UI:P/VC:H/VI:H/VA:H/SC:H/SI:H/SA:H/E:X/CR:X/IR:X/AR:X/MAV:X/MAC:X/MAT:X/MPR:X/MUI:X/MVC:X/MVI:X/MVA:X/MSX/MSI:X/MSA:X/S:X/AU:X/R:X/V:X/RE:X/U:X
3.1	productcert@siemens.com	Primary	9.1	CRITICAL	CVSS:3.1/AV:N/AC:L/PR:H/UI:N/S:C/H/I:H/A:H
3.1	CNA	DECLARED	9.1	CRITICAL	CVSS:3.1/AV:N/AC:L/PR:H/UI:N/S:C/H/I:H/A:H

CVSS v4.0 Breakdown

Attack Vector

Network

Attack Complexity

Low

Attack Requirements

None

Privileges Required

High

User Interaction

Passive

Confidentiality

High

Integrity

High

Availability

High

Sub Conf.

High

Sub Integrity

High

Sub Availability

High

CVSS:4.0/AV:N/AC:L/AT:N/PR:H/UI:P/VC:H/VI:H/VA:H/SC:H/SI:H/SA:H/E:X/CR:X/IR:X/AR:X/MAV:X/MAC:X/MAT:X/MPR:X/MUI:X/MVC:X/MVI:X/MVA:X/MSX/MSI:X/MSA:X/S:X/AU:X/R:X/V:X/RE:X/U:X

CVSS v3.1 Breakdown

Attack Vector

Network

Attack Complexity

Low

Privileges Required

High

User Interaction

None

Scope

Changed

Confidentiality

High

Integrity

High

Availability

High

CVSS:3.1/AV:N/AC:L/PR:H/UI:N/S:C/C:H/I:H/A:H

Vendor Declared Affected Products

Source	Vendor	Product	Version	Pla
CNA	Siemens	SIMATIC Drive Controller CPU 1504D TF	affected V3.1.6 custom	Not
CNA	Siemens	SIMATIC Drive Controller CPU 1507D TF	affected V3.1.6 custom	Not
CNA	Siemens	SIMATIC ET 200SP CPU 1510SP F-1 PN	affected * custom	Not

CNA	Siemens	SIMATIC ET 200SP CPU 1510SP F-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC ET 200SP CPU 1510SP F-1 PN	affected * custom	Not
CNA	Siemens	SIMATIC ET 200SP CPU 1510SP-1 PN	affected * custom	Not
CNA	Siemens	SIMATIC ET 200SP CPU 1510SP-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC ET 200SP CPU 1510SP-1 PN	affected * custom	Not
CNA	Siemens	SIMATIC ET 200SP CPU 1512SP F-1 PN	affected * custom	Not
CNA	Siemens	SIMATIC ET 200SP CPU 1512SP F-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC ET 200SP CPU 1512SP F-1 PN	affected * custom	Not
CNA	Siemens	SIMATIC ET 200SP CPU 1512SP-1 PN	affected * custom	Not
CNA	Siemens	SIMATIC ET 200SP CPU 1512SP-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC ET 200SP CPU 1512SP-1 PN	affected * custom	Not
CNA	Siemens	SIMATIC ET 200SP CPU 1514SP F-2 PN	affected * custom	Not
CNA	Siemens	SIMATIC ET 200SP CPU 1514SP-2 PN	affected * custom	Not
CNA	Siemens	SIMATIC ET 200SP CPU 1514SPT F-2 PN	affected * custom	Not
CNA	Siemens	SIMATIC ET 200SP CPU 1514SPT-2 PN	affected * custom	Not
CNA	Siemens	SIMATIC ET 200SP Open Controller CPU 1515SP PC Incl. SIPLUS Variants	affected * custom	Not
CNA	Siemens	SIMATIC ET 200SP Open Controller CPU 1515SP PC2 Incl. SIPLUS Variants V2 CPUs	affected * custom	Not
CNA	Siemens	SIMATIC ET 200SP Open Controller CPU 1515SP PC2 Incl. SIPLUS Variants V3 CPUs	affected * custom	Not
CNA	Siemens	SIMATIC ET 200SP Open Controller CPU 1515SP PC3 V4 CPUs	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1511-1 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1511-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1511-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1511-1 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1511C-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1511C-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1511C-1 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1511F-1 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1511F-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1511F-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1511F-1 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1511T-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1511T-1 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1511TF-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1511TF-1 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1512C-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1512C-1 PN	affected V2.9.9 custom	Not

CNA	Siemens	SIMATIC S7-1500 CPU 1512C-1 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1513-1 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1513-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1513-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1513-1 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1513F-1 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1513F-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1513F-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1513F-1 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1513pro F-2 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1513pro-2 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1515-2 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1515-2 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1515-2 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1515-2 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1515F-2 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1515F-2 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1515F-2 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1515F-2 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1515T-2 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1515T-2 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1515TF-2 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1515TF-2 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1516-3 PN/DP	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1516-3 PN/DP	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1516-3 PN/DP	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1516-3 PN/DP	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1516F-3 PN/DP	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1516F-3 PN/DP	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1516F-3 PN/DP	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1516F-3 PN/DP	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1516pro F-2 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1516pro-2 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1516T-3 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1516T-3 PN/DP	affected V3.1.6 custom	Not

CNA	Siemens	SIMATIC S7-1500 CPU 1516TF-3 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1516TF-3 PN/DP	affected V3.1.6 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1517-3 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1517-3 PN/DP	affected V3.1.6 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1517F-3 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1517F-3 PN/DP	affected V3.1.6 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1517F-3 PN/DP	affected V3.1.6 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1517T-3 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1517T-3 PN/DP	affected V3.1.6 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1517TF-3 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1517TF-3 PN/DP	affected V3.1.6 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1518-3 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1518-4 PN/DP	affected V3.1.6 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1518-4 PN/DP MFP	affected V3.1.6 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1518-4 PN/DP MFP	affected V3.1.6 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1518F-3 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1518F-4 PN/DP	affected V3.1.6 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1518F-4 PN/DP MFP	affected V3.1.6 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1518F-4 PN/DP MFP	affected V3.1.6 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1518T-3 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1518T-4 PN/DP	affected V3.1.6 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1518TF-3 PN	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU 1518TF-4 PN/DP	affected V3.1.6 custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU S7-1518-4 PN/DP ODK	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 CPU S7-1518F-4 PN/DP ODK	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 ET 200pro CPU 1513PRO F-2 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 ET 200pro CPU 1513PRO-2 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 ET 200pro CPU 1516PRO F-2 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 ET 200pro CPU 1516PRO-2 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIMATIC S7-1500 Software Controller CPU 1507S F V2	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 Software Controller CPU 1507S F V3	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 Software Controller CPU 1507S F V4	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 Software Controller CPU 1507S V2	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 Software Controller CPU 1507S V3	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 Software Controller CPU 1507S V4	affected * custom	Not

CNA	Siemens	SIMATIC S7-1500 Software Controller CPU 1508S F V2	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 Software Controller CPU 1508S F V3	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 Software Controller CPU 1508S F V4	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 Software Controller CPU 1508S T V3	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 Software Controller CPU 1508S TF V3	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 Software Controller CPU 1508S V2	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 Software Controller CPU 1508S V3	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 Software Controller CPU 1508S V4	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 Software Controller Linux V2	affected * custom	Not
CNA	Siemens	SIMATIC S7-1500 Software Controller Linux V3	affected * custom	Not
CNA	Siemens	SIMATIC S7-PLCSIM Advanced	affected * custom	Not
CNA	Siemens	SIPLUS ET 200SP CPU 1510SP F-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS ET 200SP CPU 1510SP F-1 PN RAIL	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS ET 200SP CPU 1510SP-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS ET 200SP CPU 1510SP-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS ET 200SP CPU 1510SP-1 PN RAIL	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS ET 200SP CPU 1510SP-1 PN RAIL	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS ET 200SP CPU 1512SP F-1 PN	affected * custom	Not
CNA	Siemens	SIPLUS ET 200SP CPU 1512SP F-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS ET 200SP CPU 1512SP F-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS ET 200SP CPU 1512SP F-1 PN RAIL	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS ET 200SP CPU 1512SP F-1 PN RAIL	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS ET 200SP CPU 1512SP-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS ET 200SP CPU 1512SP-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS ET 200SP CPU 1512SP-1 PN RAIL	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS ET 200SP CPU 1512SP-1 PN RAIL	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1511-1 PN	affected * custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1511-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1511-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1511-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1511-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1511-1 PN T1 RAIL	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1511-1 PN T1 RAIL	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1511-1 PN TX RAIL	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1511-1 PN TX RAIL	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1511F-1 PN	affected * custom	Not

CNA	Siemens	SIPLUS S7-1500 CPU 1511F-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1511F-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1513-1 PN	affected * custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1513-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1513-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1513-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1513-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1513F-1 PN	affected * custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1513F-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1513F-1 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1515F-2 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1515F-2 PN	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1515F-2 PN RAIL	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1515F-2 PN T2 RAIL	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1516-3 PN/DP	affected * custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1516-3 PN/DP	affected * custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1516-3 PN/DP	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1516-3 PN/DP	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1516-3 PN/DP	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1516-3 PN/DP	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1516-3 PN/DP RAIL	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1516-3 PN/DP TX RAIL	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1516F-3 PN/DP	affected * custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1516F-3 PN/DP	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1516F-3 PN/DP	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1516F-3 PN/DP RAIL	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1516F-3 PN/DP RAIL	affected V2.9.9 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1518-4 PN/DP	affected V3.1.6 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1518-4 PN/DP MFP	affected V3.1.6 custom	Not
CNA	Siemens	SIPLUS S7-1500 CPU 1518F-4 PN/DP	affected V3.1.6 custom	Not

References

Reference	Source	Link	Tags
cert-portal.siemens.com/productcert/html/ssa-688146.html	productcert@siemens.com	cert-portal.siemens.com	
CVE Program record	CVE.ORG	www.cve.org	canonical

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

© [CVE.report](https://cve.report) 2026 |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](https://mitre.org) and the authoritative source of CVE content is [MITRE's CVE web site](https://mitre.org/cve). This site includes MITRE data granted under the following [license](https://mitre.org/licenses).

Free CVE JSON API cve.report/api

CVE.report and Source URL Uptime Status status.cve.report