



# Milesight Cameras OS Command Injection

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF !\[\]\(003082e50e3009141f59bd5df831749f\_img.jpg\)](#)

## Summary

<b>CVE</b>	CVE-2026-32649
<b>State</b>	PUBLISHED
<b>Assigner</b>	icscert
<b>Source Priority</b>	CVE Program / NVD first with legacy fallback
<b>Published</b>	2026-04-28 01:16:00 UTC
<b>Updated</b>	2026-04-28 20:11:56 UTC
<b>Description</b>	A command injection vulnerability exists in the web server of specific firmware versions of Milesight cameras.

## Risk And Classification

**Primary CVSS:** v4.0 7.3 HIGH from ics-cert@hq.dhs.gov

**CVSS:** 4.0/AV:N/AC:L/AT:P/PR:H/UI:P/VC:H/VI:H/VA:H/SC:N/SI:N/SA:N/E:X/CR:X/IR:X/AR:X/MAV:X/MAC:X/MAT:X/MPR:X/MUI:X/MVC:X/MVI:X/MVA:X/MSX/MSI:X/MSA:X/S:X/AU:X/R:X/V:X/RE:X/U:X

**EPSS:** 0.000780000 probability, percentile 0.230630000 (date 2026-04-28)

**Problem Types:** CWE-78 | CWE-78 CWE-78

Version	Source	Type	Score	Severity	Vector
4.0	ics-cert@hq.dhs.gov	Secondary	7.3	HIGH	CVSS:4.0/AV:N/AC:L/AT:P/PR:H/UI:P/VC:H/VI:H/VA:H/SC:N/SI:N/SA:N/E:X
4.0	CNA	CVSS	7.3	HIGH	CVSS:4.0/AV:N/AC:L/AT:P/PR:H/UI:P/VC:H/VI:H/VA:H/SC:N/SI:N/SA:N
3.1	ics-cert@hq.dhs.gov	Secondary	6.8	MEDIUM	CVSS:3.1/AV:N/AC:L/PR:H/UI:R/S:U/C:H/I:H/A:H
3.1	CNA	CVSS	6.8	MEDIUM	CVSS:3.1/AV:N/AC:L/PR:H/UI:R/S:U/C:H/I:H/A:H

## CVSS v4.0 Breakdown

Attack Vector

Network

Attack Complexity

Low

Attack Requirements

Present

Privileges Required

High

User Interaction

Passive

Confidentiality

High

Integrity

High

Availability

High

Sub Conf.

None

Sub Integrity

None

Sub Availability

None

CVSS:4.0/AV:N/AC:L/AT:P/PR:H/UI:P/VC:H/VI:H/VA:H/SC:N/SI:N/SA:N/E:X/CR:X/IR:X/AR:X/MAV:X/MAC:X/MAT:X/MPR:X/MUI:X/MVC:X/MVI:X/MVA:X/MSX/MSI:X/MSA:X/S:X/AU:X/R:X/V:X/RE:X/U:X

### CVSS v3.1 Breakdown

Attack Vector

Network

Attack Complexity

Low

Privileges Required

High

User Interaction

Required

Scope

Unchanged

Confidentiality

High

Integrity

High

Availability

High

CVSS:3.1/AV:N/AC:L/PR:H/UI:R/S:U/C:H/I:H/A:H

### Vendor Declared Affected Products

Source	Vendor	Product	Version	Platforms
CNA	Milesight	MS-Cxx63-PD	affected 51.7.0.77-r12 custom	Not specified
CNA	Milesight	MS-Cxx64-xPD	affected 51.7.0.77-r12 custom	Not specified
CNA	Milesight	MS-Cxx73-xPD	affected 51.7.0.77-r12 custom	Not specified
CNA	Milesight	MS-Cxx75-xxPD	affected 51.7.0.77-r12 custom	Not specified
CNA	Milesight	MS-Cxx82-xPD	affected 51.7.0.77-r12 custom	Not specified

CNA	<a href="#">Milesight</a>	<a href="#">MS-Cxx65-FPE</a>	affected 31.7.0.77-r12 custom	not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Cxx74-PA</a>	affected 3x.8.0.3-r11 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-C8477-HPG1</a>	affected 63.8.0.4-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-C8477-PC</a>	affected 48.8.0.4-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-C5321-FPE</a>	affected 62.8.0.4-r5 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Cxx72-xxxPE</a>	affected 61.8.0.5-r2 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Cxx62-xxxPE</a>	affected 61.8.0.5-r2 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Cxx52-xxxPE</a>	affected 61.8.0.5-r2 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Cxx66-xxxPE</a>	affected 61.8.0.5-r2 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Cxx66-xxxGPE</a>	affected 61.8.0.5-r2 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Cxx61-xxxPE</a>	affected 61.8.0.5-r2 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Cxx67-xxxPE</a>	affected 61.8.0.5-r2 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Cxx71-xxxPE</a>	affected 61.8.0.5-r2 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Cxx41-xxxPE</a>	affected 61.8.0.5-r2 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Cxx76-PE</a>	affected 61.8.0.5-r2 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Cxx65-PE</a>	affected 61.8.0.5-r2 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Cxx66-xxxG1</a>	affected 63.8.0.5-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Cxx62-xxxG1</a>	affected 63.8.0.5-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Cxx72-xxxG1</a>	affected 63.8.0.5-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-CQxx31-xxxG1</a>	affected CQ_63.8.0.5-r1 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-CQxx68-xxxG1</a>	affected CQ_63.8.0.5-r1 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-CQxx72-xxxG1</a>	affected CQ_63.8.0.5-r1 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Nxxxx-NxE</a>	affected 7x.9.0.19-r5 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Nxxxx-xxC</a>	affected 7x.9.0.19-r5 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Nxxxx-xxE</a>	affected 7x.9.0.19-r5 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Nxxxx-xxG</a>	affected 7x.9.0.19-r5 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Nxxxx-xxH</a>	affected 7x.9.0.19-r5 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Nxxxx-xxT</a>	affected 7x.9.0.19-r5 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">PMC8266-FPE</a>	affected PO_61.8.0.4_LPR custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">PMC8266-FGPE</a>	affected PO_61.8.0.4_LPR custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">PM3322-E</a>	affected PI_61.8.0.3_LPR-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS4466-X4RIPG1</a>	affected T_63.8.0.4_LPR-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS5366-X12RIPG1</a>	affected T_63.8.0.4_LPR-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS8266-X4RIPG1</a>	affected T_63.8.0.4_LPR-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS4466-X4RIVPG1</a>	affected T_63.8.0.4_LPR-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS4466-RFIVPG1</a>	affected T_63.8.0.4_LPR-r3 custom	Not specified

CNA	<a href="#">Milesight</a>	<a href="#">TS8266-X4RIVPG1</a>	affected T_63.8.0.4_LPR-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS8266-RFIVPG1</a>	affected T_63.8.0.4_LPR-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS4466-X4RIWG1</a>	affected T_63.8.0.4_LPR-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS8266-X4RIWG1</a>	affected T_63.8.0.4_LPR-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS5510-GVH</a>	affected T_47.8.0.4_LPR-r7 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS5510-GH</a>	affected T_47.8.0.4_LPR-r6 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS5511-GVH</a>	affected T_47.8.0.4_LPR-r6 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS2966-X12TPE</a>	affected T_61.8.0.4_LPR-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS4466-X4RPE</a>	affected T_61.8.0.4_LPR-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS5366-X12PE</a>	affected T_61.8.0.4_LPR-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS8266-X4PE</a>	affected T_61.8.0.4_LPR-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS2966-X12TVPE</a>	affected T_61.8.0.4_LPR-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS4466-X4RVPE</a>	affected T_61.8.0.4_LPR-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS5366-X12VPE</a>	affected T_61.8.0.4_LPR-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS8266-X4VPE</a>	affected T_61.8.0.4_LPR-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS4441-X36RPE</a>	affected T_61.8.0.4_LPR-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS4441-X36RE</a>	affected T_61.8.0.4_LPR-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS4466-X4RWE</a>	affected T_61.8.0.4_LPR-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS8266-X4WE</a>	affected T_61.8.0.4_LPR-r3 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-C2964-RFLPC</a>	affected T_45.8.0.3-r9 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-C2972-RFLPC</a>	affected T_45.8.0.3-r9 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-C2966-RFLWPC</a>	affected T_45.8.0.3-r9 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS2866-X4TPC</a>	affected T_45.8.0.3-r9 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS2866-X4TVPC</a>	affected T_45.8.0.3-r9 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS2866-X4TGPC</a>	affected T_45.8.0.3-r9 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS2841-X36TPC</a>	affected T_45.8.0.3-r9 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS2841-X36TPC/W</a>	affected T_45.8.0.3-r9 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS2867-X5TPC</a>	affected T_45.8.0.3-r9 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS2961-X12TPC</a>	affected T_45.8.0.3-r9 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">TS8266-FPC/P</a>	affected T_45.8.0.3-r9 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-C2966-X12RLPC</a>	affected T_45.8.0.3-r9 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-C2966-X12RLVPC</a>	affected T_45.8.0.3-r9 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-C5366-X12LPC</a>	affected T_45.8.0.3-r9 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-C5366-X12LVPC</a>	affected T_45.8.0.3-r9 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-C5361-X12LPC</a>	affected T_45.8.0.3-r9 custom	Not specified

CNA	<a href="#">Milesight</a>	<a href="#">MS-Cxx66-xxxxGOPC</a>	affected 45.8.0.2-AIoT-r4 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">SC211</a>	affected C_21.1.0.8-r4 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">SP111</a>	affected 52.8.0.4-r5 custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Cxx66-RFIPKG1</a>	affected 63.8.0.4-r1-NX custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Cxx72-RFIPKG1</a>	affected 63.8.0.4-r1-NX custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Cxx66-FIPKG1</a>	affected 63.8.0.4-r1-NX custom	Not specified
CNA	<a href="#">Milesight</a>	<a href="#">MS-Cxx72-FIPKG1</a>	affected 63.8.0.4-r1-NX custom	Not specified

## References

Reference	Source	Link	Tags
<a href="http://www.milesight.com/support/download/firmware">www.milesight.com/support/download/firmware</a>	ics-cert@hq.dhs.gov	<a href="http://www.milesight.com">www.milesight.com</a>	
<a href="http://www.cisa.gov/news-events/ics-advisories/icsa-26-113-03">www.cisa.gov/news-events/ics-advisories/icsa-26-113-03</a>	ics-cert@hq.dhs.gov	<a href="http://www.cisa.gov">www.cisa.gov</a>	
<a href="https://github.com/cisagov/CSAF/blob/develop/csaf_files/OT/white/2026/icsa-26-11...">github.com/cisagov/CSAF/blob/develop/csaf_files/OT/white/2026/icsa-26-11...</a>	ics-cert@hq.dhs.gov	<a href="https://github.com">github.com</a>	
CVE Program record	CVE.ORG	<a href="http://www.cve.org">www.cve.org</a>	canonical
NVD vulnerability detail	NVD	<a href="http://nvd.nist.gov">nvd.nist.gov</a>	canonical, analy

## Vendor Comments And Credit

### Discovery Credit

**CNA:** Souvik Kandar reported these vulnerabilities to CISA (en)

## Additional Advisory Data

### Solutions

**CNA:** Milesight advises all users to update their device to the latest firmware versions of PE/PC/PA found at <https://www.milesight.com/support/download/firmware>.

<https://www.milesight.com/support/download/firmware> MS-Cxx63-PD: Update to 51.7.0.77-r13  
 MS-Cxx64-xPD: Update to 51.7.0.77-r13 MS-Cxx73-xPD: Update to 51.7.0.77-r13 MS-Cxx75-xxPD: Update to 51.7.0.77-r13 MS-Cxx83-xPD: Update to 51.7.0.77-r13 MS-Cxx74-PA: Update to 3x.8.0.3-r13 MS-C8477-HPG1: Update to 63.8.0.4-r4 MS-C8477-PC: Update to 48.8.0.4-r4 MS-C5321-FPE: Update to 62.8.0.4-r6 MS-Cxx72-xxxPE: Update to 61.8.0.5-r2 MS-Cxx62-xxxPE: Update to 61.8.0.5-r2 MS-Cxx52-xxxPE: Update to 61.8.0.5-r2 MS-Cxx66-xxxPE: Update to 61.8.0.5-r2 MS-Cxx66-xxxGPE: Update to 61.8.0.5-r2 MS-Cxx61-xxxPE: Update to 61.8.0.5-r2 MS-Cxx67-xxxPE: Update to 61.8.0.5-r2 MS-Cxx71-xxxPE: Update to 61.8.0.5-r2 MS-Cxx41-xxxPE: Update to 61.8.0.5-r2 MS-Cxx76-PE: Update to 61.8.0.5-r2 MS-Cxx65-PE: Update to 61.8.0.5-r2 MS-Cxx66-xxxG1: Update to 63.8.0.5-r4 MS-Cxx62-xxxG1: Update to 63.8.0.5-r4 MS-Cxx72-xxxG1: Update to 63.8.0.5-r4 MS-CQxx31-xxxG1: Update to CQ\_63.8.0.5-r2 MS-CQxx68-xxxG1: Update to CQ\_63.8.0.5-r2 MS-CQxx72-xxxG1: Update to CQ\_63.8.0.5-r2 MS-Nxxxx-NxE: Update to 7x.9.0.19-r6 MS-Nxxxx-xxC: Update to 7x.9.0.19-r6 MS-Nxxxx-xxE: Update to 7x.9.0.19-r6 MS-Nxxxx-xxG: Update to 7x.9.0.19-r6 MS-Nxxxx-xxH: Update to 7x.9.0.19-r6 MS-Nxxxx-xxT: Update to 7x.9.0.19-r6

Update to 7.8.0.10-10 MS-Cxxx66-X4T: Update to 7.8.0.10-10 MS-Cxxx66-X4T: Update to 7.8.0.10-10  
PMC8266-FPE: Update to PO\_61.8.0.4-r1 PMC8266-FGPE: Update to PO\_61.8.0.4-r1  
PM3322-E: Update to PI\_61.8.0.3-r5 TS4466-X4RIPG1: Update to T\_63.8.0.4-r4 TS5366-  
X12RIPG1: Update to T\_63.8.0.4-r4 TS8266-X4RIPG1: Update to T\_63.8.0.4-r4 TS4466-  
X4RIVPG1: Update to T\_63.8.0.4-r4 TS4466-RFIVPG1: Update to T\_63.8.0.4-r4 TS8266-  
X4RIVPG1: Update to T\_63.8.0.4-r4 TS8266-RFIVPG1: Update to T\_63.8.0.4-r4 TS4466-  
X4RIWG1: Update to T\_63.8.0.4-r4 TS8266-X4RIWG1: Update to T\_63.8.0.4-r4 TS5510-  
GVH: Update to T\_47.8.0.4-r8 TS5510-GH: Update to T\_47.8.0.4-r8 TS5511-GVH: Update to  
T\_47.8.0.4-r8 TS2966-X12TPE: Update to T\_61.8.0.4-r4 TS4466-X4RPE: Update to  
T\_61.8.0.4-r4 TS5366-X12PE: Update to T\_61.8.0.4-r4 TS8266-X4PE: Update to T\_61.8.0.4-  
r4 TS2966-X12TVPE: Update to T\_61.8.0.4-r4 TS4466-X4RVPE: Update to T\_61.8.0.4-r4  
TS5366-X12VPE: Update to T\_61.8.0.4-r4 TS8266-X4VPE: Update to T\_61.8.0.4-r4 TS4441-  
X36RPE: Update to T\_61.8.0.4-r4 TS4441-X36RE: Update to T\_61.8.0.4-r4 TS4466-X4RWE:  
Update to T\_61.8.0.4-r4 TS8266-X4WE: Update to T\_61.8.0.4-r4 MS-C2964-RFLPC: Update  
to T\_45.8.0.3-r10 MS-C2972-RFLPC: Update to T\_45.8.0.3-r10 MS-C2966-RFLWPC: Update  
to T\_45.8.0.3-r10 TS2866-X4TPC: Update to T\_45.8.0.3-r10 TS2866-X4TVPC: Update to  
T\_45.8.0.3-r10 TS2866-X4TGPC: Update to T\_45.8.0.3-r10 TS2841-X36TPC: Update to  
T\_45.8.0.3-r10 TS2841-X36TPC/W: Update to T\_45.8.0.3-r10 TS2867-X5TPC: Update to  
T\_45.8.0.3-r10 TS2961-X12TPC: Update to T\_45.8.0.3-r10 TS8266-FPC/P: Update to  
T\_45.8.0.3-r10 MS-C2966-X12RLPC: Update to T\_45.8.0.3-r10 MS-C2966-X12RLVPC:  
Update to T\_45.8.0.3-r10 MS-C5366-X12LPC: Update to T\_45.8.0.3-r10 MS-C5366-  
X12LVPC: Update to T\_45.8.0.3-r10 MS-C5361-X12LPC: Update to T\_45.8.0.3-r10 MS-  
Cxx66-xxxxGOPC: Update to 45.8.0.2-AIoT-r5 SC211: Update to C\_21.1.0.8-r5 SP111:  
Update to 52.8.0.4-r6 MS-Cxx66-RFIPKG1: Update to 63.8.0.5-r2-NX MS-Cxx72-RFIPKG1:  
Update to 63.8.0.5-r2-NX MS-Cxx66-FIPKG1: Update to 63.8.0.5-r2-NX MS-Cxx72-FIPKG1:  
Update to 63.8.0.5-r2-NX

**CNA:** Mulesight asks all users to report potential security vulnerabilities to [security@mulesight.com](mailto:security@mulesight.com). <mailto:security@mulesight.com> Learn more: Mulesight Vulnerability Reporting Policy <https://www.mulesight.com/legal/vulnerability-report>

There are currently no legacy QID mappings associated with this CVE.

© [CVE.report](https://cve.report) 2026 |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](https://www.mitre.org) and the authoritative source of CVE content is [MITRE's CVE web site](https://www.mitre.org/cve). This site includes MITRE data granted under the following [license](https://www.mitre.org/cve).

Free CVE JSON API [cve.report/api](https://cve.report/api)

CVE.report and Source URL Uptime Status [status.cve.report](https://status.cve.report)