CVE-2015-5609

Published on: 05/22/2017 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:26:14 PM UTC

CVE-2015-5609

Source: Mitre | Source: NIST | CVE.ORG | Print: PDF



Certain versions of Image-export from Image-export Project contain the following vulnerability:

Absolute path traversal vulnerability in the Image Export plugin 1.1 for WordPress allows remote attackers to read and delete arbitrary files via a full pathname in the file parameter to download.php.

CVE-2015-5609 has been assigned by cve@mitre.org to track the vulnerability - currently rated as CRITICAL severity.

CVSS3 Score: 9.1 - CRITICAL

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	**Confidentiality Impact**	**Integrity Impact**	**Availability Impact**
UNCHANGED	HIGH	HIGH	NONE

CVSS2 Score: 6.4 - MEDIUM

Access Vector	Access Complexity	Authentication
NETWORK	LOW	NONE
Confidentiality Impact	**Integrity Impact**	**Availability Impact**
PARTIAL	PARTIAL	NONE

CVE References

Description	Tags	Link
oss-security - Remote file download vulnerability in Wordpress Plugin image-export v1.1	Exploit Mailing List www.openwall.com text/html	MLIST [oss-security] 20150713 Remote file download vulnerability in Wordpress Plugin image-export v1.1

Vulnerability	Exploit Third Party Advisory web.archive.org text/html Inactive Link Not Archived	MISC www.vapid.dhs.org/advisory.php?v=135
oss-security - Re: Remote file download vulnerability in Wordpress Plugin image-export v1.1	Exploit Mailing List www.openwall.com text/html	MLIST [oss-security] 20150720 Re: Remote file download vulnerability in Wordpress Plugin image-export v1.1

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Application	Image-export Project	Image-export	1.1	All	All	All
Application	Image-export Project	Image-export	1.1	All	All	All

cpe:2.3:a:image-export_project:image-export:1.1:*:*:*:*:wordpress:*:*

cpe:2.3:a:image-export_project:image-export:1.1:*:*:*:*:wordpress:*:*

No vendor comments have been submitted for this CVE

← Previous ID

Next ID→