



# CVE-1999-1228

Published on: 09/27/1998 04:00:00 AM UTC

Last Modified on: 03/23/2021 11:27:32 PM UTC

## CVE-1999-1228

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [Supra](#) from [Diamond](#) contain the following vulnerability:

Various modems that do not implement a guard time, or are configured with a guard time of 0, can allow remote attackers to execute arbitrary modem commands such as ATH, ATH0, etc., via a "+++" sequence that appears in ICMP packets, the subject of an e-mail message, IRC commands, and others.

CVE-1999-1228 has been assigned by [M](#) [cve@mitre.org](mailto:cve@mitre.org) to track the vulnerability

CVSS2 Score: **7.5 - HIGH**

Access  
Vector

**NETWORK**

Access  
Complexity

**LOW**

Authentication

**NONE**

Confidentiality  
Impact

**PARTIAL**

Integrity  
Impact

**PARTIAL**

Availability  
Impact

**PARTIAL**

## CVE References

Description

Tags

Link

'1+2=3, +++ATH0=Old school DoS' - MARC

[marc.info](#)  
[text/html](#)

[BUGTRAQ 19980927 1+2=3, +++ATH0=Old school DoS](#)

403 Forbidden

[Vendor Advisory](#)  
[www.macintouch.com](#)  
[text/html](#)  
[Inactive Link](#) [Not Archived](#)

[MISC www.macintouch.com/modemsecurity.html](#)

IBM X-Force Exchange

[exchange.xforce.ibmcloud.com](#)  
[text/html](#)

[XF global-village-modem-dos\(3320\)](#)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

| Type                                                                                       | Vendor                      | Product                     | Version | Update | Edition | Language |
|--------------------------------------------------------------------------------------------|-----------------------------|-----------------------------|---------|--------|---------|----------|
| Hardware  | <a href="#">Diamond</a>     | <a href="#">Supra</a>       | 33.6    | All    | All     | All      |
| Hardware  | <a href="#">Diamond</a>     | <a href="#">Supra</a>       | v.90    | All    | All     | All      |
| Hardware  | <a href="#">Diamond</a>     | <a href="#">Supra</a>       | 33.6    | All    | All     | All      |
| Hardware  | <a href="#">Diamond</a>     | <a href="#">Supra</a>       | v.90    | All    | All     | All      |
| Application                                                                                | <a href="#">Logicode</a>    | <a href="#">Quicktel</a>    | 28.8    | All    | All     | All      |
| Application                                                                                | <a href="#">Logicode</a>    | <a href="#">Quicktel</a>    | 28.8    | All    | All     | All      |
| Hardware  | <a href="#">Us Robotics</a> | <a href="#">Us Robotics</a> | 33.6    | All    | All     | All      |
| Hardware  | <a href="#">Us Robotics</a> | <a href="#">Us Robotics</a> | 33.6    | All    | All     | All      |
| cpe:2.3:h:diamond:supra:33.6:*****:                                                        |                             |                             |         |        |         |          |
| cpe:2.3:h:diamond:supra:v.90:*****:                                                        |                             |                             |         |        |         |          |
| cpe:2.3:h:diamond:supra:33.6:*****:                                                        |                             |                             |         |        |         |          |
| cpe:2.3:h:diamond:supra:v.90:*****:                                                        |                             |                             |         |        |         |          |
| cpe:2.3:a:logicode:quicktel:28.8:*****:                                                    |                             |                             |         |        |         |          |
| cpe:2.3:a:logicode:quicktel:28.8:*****:                                                    |                             |                             |         |        |         |          |
| cpe:2.3:h:us_robotics:us_robotics:33.6:*****:                                              |                             |                             |         |        |         |          |
| cpe:2.3:h:us_robotics:us_robotics:33.6:*****:                                              |                             |                             |         |        |         |          |

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)