



CVE-2000-1062

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

Summary

CVE	CVE-2000-1062
State	PUBLISHED
Assigner	mitre
Source Priority	CVE Program / NVD first with legacy fallback
Published	2000-12-11 05:00:00 UTC
Updated	2025-04-03 01:03:51 UTC
Description	Buffer overflow in the FTP service in HP JetDirect printer card Firmware x.08.20 and earlier allows remote attackers to cause

Risk And Classification

Primary CVSS: v2.0 5 from nvd@nist.gov

AV:N/AC:L/Au:N/C:N/I:N/A:P

Problem Types: NVD-CWE-Other | n/a

CVSS v2.0 Breakdown

Access Vector

Network

Access Complexity

Low

Authentication

None

Confidentiality

None

Integrity

None

Availability

Partial

AV:N/AC:L/Au:N/C:N/I:N/A:P

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Hp	Jetdirect	x.08.04	All	All	All

Hardware	Hp	Jetdirect	x.08.05	All	All	All
Hardware	Hp	Jetdirect	x.08.20	All	All	All
Vendor Declared Affected Products						
Source	Vendor	Product	Version	Platforms		
CNA	Na	N/a	affected n/a	Not specified		
References						
Reference	Source		Link		Tags	
HP JetDirect Multiple DoS Vulnerabilities	af854a3a-2127-422b-91ae-364da2661108		www.securityfocus.com		Patch, Vendor Advi	
IBM X-Force Exchange	af854a3a-2127-422b-91ae-364da2661108		exchange.xforce.ibmcloud.com			
marc.info	af854a3a-2127-422b-91ae-364da2661108		marc.info			
CVE Program record	CVE.ORG		www.cve.org		canonical	
NVD vulnerability detail	NVD		nvd.nist.gov		canonical, analysis	
No vendor comments have been submitted for this CVE.						
There are currently no legacy QID mappings associated with this CVE.						