



CVE-2001-0773

- MITRE
- NVD
- CVE.ORG
- JSON API
- Print: PDF

Summary

CVE	CVE-2001-0773
State	PUBLISHED
Assigner	mitre
Source Priority	CVE Program / NVD first with legacy fallback
Published	2001-10-18 04:00:00 UTC
Updated	2025-04-03 01:03:51 UTC
Description	Cayman 3220-H DSL Router 1.0 allows remote attacker to cause a denial of service (crash) via a series of SYN or TCP con

Risk And Classification

Primary CVSS: v2.0 5 from nvd@nist.gov

AV:N/AC:L/Au:N/C:N/I:N/A:P

Problem Types: NVD-CWE-Other | n/a

CVSS v2.0 Breakdown

Access Vector

Network

Access Complexity

Low

Authentication

None

Confidentiality

None

Integrity

None

Availability

Partial

AV:N/AC:L/Au:N/C:N/I:N/A:P

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Cayman	3220-h Dsl Router	1.0	All	All	All

Vendor Declared Affected Products				
Source	Vendor	Product	Version	Platforms
CNA	Na	N/a	affected n/a	Not specified

References		
Reference	Source	Link
SecurityFocus	af854a3a-2127-422b-91ae-364da2661108	www.securityfocus.com
CERT/CC Vulnerability Note VU#312761	af854a3a-2127-422b-91ae-364da2661108	www.kb.cert.org
IBM X-Force Exchange	af854a3a-2127-422b-91ae-364da2661108	exchange.xforce.ibmcloud.com
Cayman-DSL Router Portscan Denial of Service Vulnerability	af854a3a-2127-422b-91ae-364da2661108	www.securityfocus.com
CVE Program record	CVE.ORG	www.cve.org
NVD vulnerability detail	NVD	nvd.nist.gov

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.